

M.D. AUTO WORKS, INC.
Exotic Automotive Restorations
111-30 Van Wyck Expwy.
JAMAICA, NEW YORK 11420

(718) 529-2323

TO

TERMS:

JOE INVOICE

201 884.3036 № 5043

PHONE 201-234-0725	DATE OF ORDER 10/28/05
ORDER TAKEN BY VITO - NJ	CUSTOMER'S ORDER NUMBER
<input type="checkbox"/> DAY WORK	<input type="checkbox"/> CONTRACT <input type="checkbox"/> EXTRA
JOB NAME/NUMBER Petersa - Detomaso	white
JOB LOCATION	
JOB PHONE	STARTING DATE

[illegible]

DATE COMPLETED

TOTAL MATERIALS**Work ordered by**

Signature

I hereby acknowledge the satisfactory completion of the above described work.

TOTAL LABOR

TOTAL MATERIALS

TOTAL OTHER

TOTAL

Thank You

JOE INVOLVED

TO

PHONE 201-234 0725	DATE OF ORDER 8-29-86
ORDER TAKEN BY	CUSTOMER'S ORDER NUMBER
<input type="checkbox"/> DAY WORK <input type="checkbox"/> CONTRACT <input type="checkbox"/> EXTRA	
JOB NAME/NUMBER 1971 Porters	
JOB LOCATION	
JOB PHONE	STARTING DATE 8-29-86

Thank You

Signature _____ I hereby acknowledge the satisfactory completion of the above described work.

QTY.	PART NO. AND DESCRIPTION	PRICE
1	Rebuild Gasket	35.00
2	U.P.S. Change	1380.69
1	Dry Gas	125
1	Flare Gas	795
		<u>418.00</u>

GLADPACK SUNOCO, INC.
P.O. Box 481
1 Pottersville Road
GLADSTONE, NJ 07934
(908) 234-1355 FAX (908) 234-1368

42171

NAME	CUSTOMER'S ORDER NO.	DATE
ADDRESS	WRITTEN BY	PROMISED
CITY, STATE, ZIP		A.M. P.M.
HOME PHONE		1355
YEAR, MAKE AND MODEL		LICENSE NUMBER
SERIAL NUMBER	MOTOR NUMBER	11-140
TERMS		

1	Tow to Shop	55.00
1	E.P.A. Waste Charge (Gas Dirty)	5.00

DESCRIPTION OF WORK	AMOUNT
<input type="checkbox"/> LUBE <input type="checkbox"/> CHANGE OIL <input type="checkbox"/> OIL FILTER <input type="checkbox"/> TUNE-UP <input type="checkbox"/> TRANS. <input type="checkbox"/> DIFF	
Motor Veh Inspection	22.00
051 HC 127	
R & K Lubricants Corp. Lube	44.00
to be overhauled	
change out fuel lines & tank	66.00
Very Dirty	
190 FSD 006119-00 11/1/97 11/1/98	
Lumbermens Mutual Ins Co	
LITERS/GALS. OF GAS @	TOTAL LABOR
LITERS/GALS. OF OIL @	TOTAL PARTS
kg LBS. OF GREASE @	ACCESSORIES
	GAS, OIL AND GREASE
	SUBLET REPAIRS
	EPA /WASTE DISPOSAL
	TAX
	TOTAL

1 1/2% per month charge on unpaid balance over 30 days.

(MAY BE CONTINUED ON OTHER SIDE)

TOTAL PARTS	
ACCESSORIES	
3820368	150
11/9/97	
TOTAL ACCESSORIES	

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

SIGNATURE

Back #5885
Thank you

THE STABLE, LTD.
217 MAIN ST.
ALABAMA, NJ 07934
908-234-2055

1 of 2

10732

QUAN.	NUMBER	DESCRIPTION	PRICE
2	PARTS	1515 OIL FILTERS	13 90
2		ENGINE OIL TREATMENT	7 90
2		3900R FUEL FILTERS	22 60
1		13-3014 Rebuild Alternator	85 40
1		25-7410 Belt	16 25
1		25-9365 Belt	20 00
1		11515182 Manifold Gaskets	17 64
1		116082 FUEL PUMP	31 93
2		DA1605 PAINT SPRAY	13 90
1		7701763 TAP - TANK PAD	9 95
6		HARDWARE	4 50
1		VR420 Voltage Reg.	32 25
6		FT 3/8 Braided Hose	42 00
3	ACCESSORIES	FT 7/16 Braided Hose	21 00
1		FUEL TANK EXCHANGE	287 50
		Reb. Stock TANK G-8	
1		09003A Pickup-Sender	184 00
1		09004B Gasket	11 50
1	SUBLET REPAIRS	09008A Gasket	11 50
1		G-823 Filler Neck	113 85
2		SHIPPING ON TANKS	100 00
10		NPN HOSE CLAMPS 1.50	15 00
		GAS, OIL & GREASE	
		GALS. GAS @	15 00
12		QTS. OIL @ 2.50 =	30 00
		LBS. GREASE @	45 00

NAME _____ DATE 11-1-2001

ADDRESS _____

CITY _____ STATE _____ ZIP _____

MAKE Detomaso TYPE OR MODEL Pantera YEAR 1971

VIN THPNLUC02210

RECEIVED A.M. P.M.

PROMISED A.M. P.M.

ODOMETER 17,367 LICENSE NO. VTT 140 ENGINE NO. SSIC

PHONE WHEN READY? YES ☐ NO ☐

CUST. ORDER NO. _____ ORDER WRITTEN BY _____ PHONE _____

OPER. NO. _____ INSTRUCTIONS _____

DSS	ISJ	LABOR CHARGE
LUBRICATION	<input type="radio"/>	
CHANGE OIL	<input type="radio"/>	
CHANGE OIL FILTER	<input type="radio"/>	
CHANGE TRANS.	<input type="radio"/>	
CHANGE DIFF.	<input type="radio"/>	
PACK FRONT WHEEL BRGS.	<input type="radio"/>	
ADJUST BRAKES	<input type="radio"/>	
ROTATE TIRES	<input type="radio"/>	
WASH	<input type="radio"/>	
POLISH	<input type="radio"/>	

① VEHICLE WAS FLATBEDDED TO SHIP - WOULD START AFTER STORAGE - FUEL SYSTEM PROBLEMS!

Replace FUEL FILTER - Clean out Housing - Drain fuel tank AND ADD FRESH PETROL, STILL NO GOOD - found MASSIVE RUST INSIDE FUEL TANK AND PICKUP 5889 20

tube has rust holes AND DRAWS AIR.

REMOVE ENGINE / TRANAXLE ASSY AS REQUIRED TO GAIN ACCESS TO FUEL TANK AREA. Replace fuel tank with Rebuilt unit. Renew fuel pump, lines, filter, pickup AND tank sending unit. Remove Carburetor top AND Clean out inside of float bowls.

HAZARDOUS WASTE ENVIRONMENTAL CHARGES: 2.00 BASIC OVERHAUL OF COMPLETE

*If repair commencement is authorized but completion is not authorized a charge will be imposed for disassembly, reassembly or partially completed work.

SPECIAL INSTRUCTIONS OR COMMENTS	C	S
Sublet 2		
① Towing to Shop 56.76		5889 20
② NEW JERSEY INSP 72.00		1957 78
③ Complete Vehicle		
Delaying 289.95		
TOTAL LABOR		5889 20
TOTAL PARTS		1957 78
ACCESSORIES DISPOSAL		200
GAS, OIL & GREASE		45 00
SUBLET REPAIRS		418 71
PAINT & BODY SHOP MATERIALS		8325 69
TAX		499 54
TOTAL		75922 23

PARTS WARRANTY - TO THE EXTENT PERMITTED BY STATE OR LOCAL LAW, ANY WARRANTIES ON THE PRODUCTS SOLD HEREIN ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. IF REPAIR COMMENCEMENT IS AUTHORIZED, BUT COMPLETION IS NOT AUTHORIZED A CHARGE WILL BE IMPOSED FOR DISASSEMBLY, REASSEMBLY OR PARTIALLY COMPLETED WORK.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE CAR OR TRUCK HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

The limited warranties applying to the parts listed hereon are those which may be offered by the manufacturers. We hereby expressly disclaim all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose and neither assume, nor authorize any other person to assume for the company any liability in connection with the sale of this party's and/or service. Buyer shall not be entitled to recover from the company any consequential damages, to property, damages for loss of use, loss of time, loss of profits or income, or any other incidental damages.

GRO INC

PLCK #588 THE SIADLE, LTD.
217 MAIN ST.
GLADSTONE, NJ 07934
908-234-2055

[illegible]

PARTS WARRANTY - TO THE EXTENT PERMITTED BY STATE OR LOCAL LAW, ANY WARRANTIES ON THE PRODUCTS SOLD HERE ARE THOSE MADE BY THE MANUFACTURER. THERE BEING NO EXPRESS OR IMPLIED WARRANTIES, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. IF REPAIR COMMENCEMENT IS AUTHORIZED BUT COMPLETION IS NOT AUTHORIZED A CHARGE WILL BE IMPOSED FOR DISASSEMBLY, REASSEMBLY OR PARTIALLY COMPLETED WORK.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES
LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE
BEYOND OUR CONTROL.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE CAR OR TRUCK HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

If repair commencement is authorized but completion is not authorized a charge will be imposed for disassembly, reassembly or partially completed work.

SPECIAL INSTRUCTIONS OR COMMENTS

	DSS	ISJ	LABOR CHARGE		
	LUBRICATION	<input type="radio"/>			
	CHANGE OIL	<input type="radio"/>			
	CHANGE OIL FILTER	<input type="radio"/>			
	CHANGE TRANS.	<input type="radio"/>			
A.M. P.M.	CHANGE DIFF.	<input type="radio"/>			
A.M. P.M.	PACK FRONT WHEEL BRGS.	<input type="radio"/>			
EADY?	ADJUST BRAKES	<input type="radio"/>			
O	ROTATE TIRES	<input type="radio"/>			
	WASH	<input type="radio"/>			
	POLISH	<input type="radio"/>			
Sale Unit,					
needed, Clean					
Gilley,					
+ Gaskets					
labor					
- A/C Compressor					
Holding Charge					
Plate Mounts					
TOTAL LABOR	C	S			
TOTAL PARTS					
ACCESSORIES					
GAS, OIL, GREASE					
SUBLET REPAIRS					
PAINT & BODY SHOP MATERIALS					
TAX					
TOTAL					

The limited warranties applying to the parts listed herein are those which may be offered by the manufacturer. We hereby expressly disclaim all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, for the company or any person to assume for the company any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the company any consequential damages, in property, damages for loss of use, loss of time, loss of profits or income, or any other incidental damages.

GRO
N/C

[illegible][illegible]

THIS WARRANTY - TO THE EXTENT PERMITTED BY STATE OR LOCAL LAW - ANY WARRANTIES ON THE OUTSIDE BOX HEREIN ARE THOSE MADE BY THE MANUFACTURER, THE SELLER, OR THE CARRIER. IT CLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY CONNECTION WITH THE SALE OF SAID PRODUCTS. REPAIR COMMENCEMENT IS AUTHORIZED BUT REPLACEMENT IS NOT AUTHORIZED. A CHARGE WILL BE ASSESSED FOR DISASSEMBLY, REASSEMBLY OR PARTIALLY COMPLETED WORK.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES
LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE
BEYOND OUR CONTROL.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE CAR OR TRUCK HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

The limited warranties applying to the parts listed herein are those which may be offered by the manufacturer. We hereby expressly disclaim all warranties, either expressed or implied, including any implied warranties of the merchantability or fitness for a particular purpose and neither assume, nor authorize any other person to assume for the company any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the company any consequential damages, to property, damages for loss of use, loss of time, loss of profits or income, or any other incidental damages.

GRO
N/C

iUSP

417 MAIN ST.
GLADSTONE, NJ 07934
908-234-2055

QTY.	NUMBER	DESCRIPTION	PRICE
	PARTS		
1	ST82 Solenoid		29.81
1	711699 Ground Strap		6.74
1	Wire + Connectors		4.00
			40.55
	ACCESSORIES		
	SUBLET REPAIRS		
	GAS, OIL & GREASE		
	GALS. GAS @		
	QTS. OIL @		
	LBS. GREASE @		

NAME		DATE		DSS	ISJ	LABOR CHARGE	
ADDRESS		5-20-02		LUBRICATION	<input type="radio"/>		
CITY		STATE		CHANGE OIL	<input type="radio"/>		
MAKE		TYPE OR MODEL		CHANGE OIL FILTER	<input type="radio"/>		
YEAR		RECEIVED		CHANGE TRANS.	<input type="radio"/>		
VIN		PROMISED		CHANGE DIFF.	<input type="radio"/>		
ODOMETER		PHONE WHEN READY?		PACK FRONT WHEEL BRGS.	<input type="radio"/>		
CUST. ORDER NO.		ORDER WRITTEN BY		ADJUST BRAKES	<input type="radio"/>		
HAZARDOUS WASTE ENVIRONMENTAL CHARGES:		2.00		ROTATE TIRES	<input type="radio"/>		
OPER. NO.		INSTRUCTIONS		WASH	<input type="radio"/>		
		<p>① Check Veh. che WAS flatbedded to Shop - Electrical Problems.</p> <p>FOUND Starter Motor WAS Stuck on! - keeps Cranking.</p> <p>Check Starter - Solenoid AND Source power but WAS UNABLE to find ANY Problem.</p> <p>24360</p>					
		<p>② Replace Starter Solenoid - PROVIDE GROUNDING STRAP BETWEEN ENGINE AND CHASSIS, ALSO GROUND WIRE BETWEEN CHASSIS AND MOUNTING Plate for Voltage Regulator - AND Starter solenoid.</p> <p>HAZARDOUS WASTE ENVIRONMENTAL CHARGES: 2.00</p> <p>ALL OPERATIONS OK NEW</p>					
If repair commencement is authorized but completion is not authorized a charge will be imposed for disassembly, reassembly or partially completed work.		SPECIAL INSTRUCTIONS OR COMMENTS		C	S		
		(Customer own NEW BATTERY)		TOTAL LABOR		24360	
				TOTAL PARTS		4055	
				ACCESSORIES	Disposal	200	
				GAS, OIL, GREASE			
				SUBLET REPAIRS	Towing	18600	
				PAINT & BODY SHOP MATERIALS	Sub	47215	
				TAX		2833	
				TOTAL		\$50048	

THIS WARRANTY - TO THE EXTENT PERMITTED BY STATE OR LOCAL LAW, ALL WARRANTIES ON THE PRODUCTS SOLD HEREIN ARE THOSE MADE BY THE MANUFACTURER, THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY CONNECTION WITH THE SALE OF SAID PRODUCTS. REPAIR COMMENCEMENT IS AUTHORIZED BUT COMPLETION IS NOT AUTHORIZED A CHARGE WILL BE ASSESSED FOR DISASSEMBLY, REASSEMBLY OR PARTIALLY COMPLETED WORK.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES
LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE
BEYOND OUR CONTROL.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE CAR OR TRUCK HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

The limited warranties applying to the parts listed hereon are those which may be offered by the manufacturer. We hereby expressly disclaim all warranties, either expressed or implied, including any implied warranties of the merchantability or fitness for a particular purpose and neither assume, nor authorize any other person to assume for us any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the company any consequential damages, or loss of use, loss of time, loss of profits or income, or any other incidental damages.

GRC
N/C

2 of 3

217 MAIN ST. • P.O. BOX 557
GLADSTONE, NJ 07934
908-234-2055 www.stableltd.com

NAME		DATE		DSS		ISJ		LABOR CHARGE	
ADDRESS				12-23-22		LUBRICATION		<input type="radio"/>	
CITY				STATE		ZIP		CHANGE OIL	
MAKE		TYPE OR MODEL		YEAR		RECEIVED		CHANGE OIL FILTER	
DETOMASO PANTERA		1972				A.M. P.M.		CHANGE TRANS.	
THPILV02210						PROMISED		CHANGE DIFF.	
ODOMETER		LICENSE NO.		ENGINE NO.		PHONE WHEN READY?		PACK FRONT WHEEL BRGS.	
17650		VTT-140				YES <input type="radio"/> NO <input type="radio"/>		ADJUST BRAKES	
CUST. ORDER NO.		ORDER WRITTEN BY		PHONE				ROTATE TIRES	
								WASH	
OPER. NO.		INSTRUCTIONS						POLISH	
		<p>REMOVE CARBURETOR DISASSEMBLE AND REBUILD NEW SEALS GASKETS NEEDLE & SEAT, CLEAN AND REASSEMBLE.</p> <p>REPLACE MECHANICAL FUEL PUMP AND FLUSH GLASSES FUEL LINES.</p> <p>REPAIR LOST SPARK PLUGS AND IGNITION PARTS BASEL ENGINE TUNE UP</p> <p>ADD MARVEL OIL TO LUBS AND ALLOW TO SOAK ROTATE ENGINE WITH PLUGS OUT PRIOR TO ATTEMPT TO START.</p> <p>DRAIN ENGINE OIL - RENEW OIL AND OIL FILTER</p>							
HAZARDOUS WASTE ENVIRONMENTAL CHARGES:									
If repair commencement is authorized but completion is not authorized a charge will be imposed for disassembly, reassembly or partially completed work.		SPECIAL INSTRUCTIONS OR COMMENTS							
		FLAKED SERVICE FROM STORAGE BUILDING to SHOP				TOTAL LABOR		C S	
						TOTAL PARTS		ADD TO ROLL 2	
						ACCESSORIES			
						GAS, OIL, GREASE			
						SUBLET REPAIRS		1600.00	
						PAINT & BODY SHOP MATERIALS		155.16	
		TOTAL SHIPPING CHARGES				TAX			
						TOTAL			

The limited warranties applying to the parts listed hereon are those which may be offered by the manufacturer. We hereby expressly disclaim all warranties, either expressed or implied, including any implied

870
N/C

3063

3063

SPECIAL INSTRUCTIONS OR COMMENTS		C	S
If repair commencement is authorized but completion is not authorized a charge will be imposed for disassembly, reassembly or partially completed work.	Sublet	ADD TO ROTH	
	GASOLINE BODY		
LOSS OR DAMAGE TO VEHICLE OR IN CASE OF FIRE, THEFT OR ANY OTHER TITOL.	TINT FOR TREATMENT	ACCESSORIES	
	OF FINISH	GAS, OIL, GREASE	
THE ABOVE REPAIR WORK TO BE DONE NECESSARY MATERIAL, AND HEREBY GRANT EMPLOYEES PERMISSION TO OPERATE THE BED ON STREETS, HIGHWAYS OR ELSEWHERE OF TESTING AND/OR INSPECTION. AN LIEN IS HEREBY ACKNOWLEDGED ON THE AMOUNT OF REPAIRS THERETO.	Prior	SUBLET REPAIRS	5500
	TO REASSEMBLE	PAINT & BODY SHOP MATERIALS	
		TAX	
		TOTAL	

GRO
N/C



Stallion Motorsports
750 West 17th Street
Costa Mesa, CA 92627
(949) 759-2805
Vargas@Stallionmotorsports.co

Invoice #1429

Created: 10/3/2024
Invoiced: 10/21/2024
Payment Term: On Receipt
Service Writer: Angel Vargas

Peter Kumar

Gullwing Motor Cars INC
24-30 46th Street
Astoria, NY 11103
peterkumar@gullwingmotorcars.com

1971 Detomaso Panter (Red)

VIN: THPNLU02210
Mileage In: 17,722
Mileage Out: 17,726

Customer Comments

Inspection
brakes seized

Pantera Inspect Vehicle

	Description	HRS	Subtotal
1	Inspect Vehicle Current Conditions, Vehicle came in with Brakes Sticking. During Drop off Noticed Vehicle has Exhaust Leak. Hoist vehicle and Inspect Brake System. Rotated Vehicles wheels and Noticed Passenger side Rear Caliper Stuck. Driver Side Front Rotor Slightly Warped. During Inspection, Also found the following. 1) Exhaust manifolds gaskets Leaking. Recommend Replacing them 2) Found Steering Rack leaking, Commend Rebuilding Steering Rack and Add New Tie rod ends, with front end alignment. 3) Oil pan has a welded Nut to oil pan and oil drain plug leaking fluid and Oil pan gasket seeping Oil Recommend Replacing with upgraded oil pan and gasket.	1	\$210.00
Shop Supplies (3%): \$6.30			Total: \$216.30

Rebuild Rear Calipers

	Description	Price	QTY	HRS	Subtotal
1	Remove Passenger and Driver side Rear Calipers and Rebuild. Both sides. Resurface Brake Pad for new contact point. Remove Front hubs and Remove Front Rotors for Resurfacing, Also Resurface Brake Pad for new contact pad. Resurface all rotors for un even wear.			4.5	\$945.00
2	Rear Caliper Rebuild Kit (Pair)	\$104.93	1		\$104.93
3	Resurface Rear Rotors	\$216.00			\$216.00



Stallion Motorsports
750 West 17th Street
Costa Mesa, CA 92627
(949) 759-2805
Vargas@Stallionmotorsports.co

Invoice #1429

Created: 10/3/2024
Invoiced: 10/21/2024
Payment Term: On Receipt
Service Writer: Angel Vargas

Rebuild Rear Calipers

4	Dot 3 Brake Fluid	\$15.16	2	\$30.32
5	During the caliper rebuild, We noticed that the internal components have been rebuilt prior by another company, during the removal we noticed the internal function of the Rear E- brake was broken and was the main cause of the driver sider caliper being seized. Upon further analysis noticed that the ratcheting mechanism was broken internally and could not be fixed. Sourced New Rear inner piston and ratcheting mechanism, Installed and recalibrated Ebrake Function. During brake bleed procedure, we noticed during brake force applied we found the brake pedal weak and losing pressure. Inspected Brake Booster and found that there was a very thin vacuum hose used during pressure is applied, vacuum hose would collapse and stop air from traveling from engine over to the brake booster. Replace vacuum hose and installed Brake booster vacuum hose Brakes operate the way they should.		1.5	\$315.00
6	Rear Inner Piston Ratcheting mechanism	\$384.00	1	\$384.00
7	Brake Booster Vacuum Hose 2 feet	\$20.62	1	\$20.62
Shop Supplies (3%): \$13.70		Tax (7.75%): \$41.84	Total: \$2,071.41	

Steering Rack Rebuild

Description	Price	QTY	HRS	Subtotal
1 Remove Steering rack, send out to get rebuilt and reinstall steering rack with new tie rod ends and steering boots.			1.2	\$252.00
2 Rebuild internal Steering Rack	\$371.25			\$371.25
3 Rebuild Kit	\$224.99	1		\$224.99
4 Tie rod Ends	\$62.49	2		\$124.98
5 Front End Alignment	\$200.00			\$200.00
Tax (7.75%): \$27.12		Total: \$1,200.34		

Exhaust Manifold Leak

Description	Price	QTY	HRS	Subtotal
1 Remove and Replace Exhaust manifold gasket, Causing Loud Exhaust leak on both exhaust manifolds.			3	\$630.00
2 Exhaust Manifold gasket Set	\$60.68	1		\$60.68
Tax (7.75%): \$4.70		Total: \$695.38		



Stallion Motorsports
750 West 17th Street
Costa Mesa, CA 92627
(949) 759-2805
Vargas@Stallionmotorsports.co

Invoice #1429

Created: 10/3/2024
Invoiced: 10/21/2024
Payment Term: On Receipt
Service Writer: Angel Vargas

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

STORAGE FEE: \$50.00 PER DAY WILL BE CHARGED AFTER 48 HOURS AFTER RECEIVING THIS NOTIFICATION OF COMPLETION ON REPAIRS.

Signature _____

Totals only include authorized services

Parts	\$950.52
Labor	\$2,352.00
Subcontract	\$787.25
Subtotal	\$4,089.77
Shop Supplies	\$20.00
Tax	\$73.67
Grand Total	\$4,183.44
Paid To Date	(\$0.00)

REMAINING BALANCE	\$4,183.44
--------------------------	-------------------

Authorizations

In App by Colleen Sheehan 10/7/2024 at 3:39 PM PDT	+ Pantera Inspect Vehicle + Rebuild Rear Calipers + Steering Rack Rebuild + Exhaust Manifold Leak - Oil Pan Gasket Leaking	\$3,432.46
--	--	-------------------

Notes

Angel Vargas	10/3/2024 3:48 PM PDT
---------------------	-----------------------

Hi Colleen ,

Below is a link to the estimate you requested from Stallion Motorsports . Please review and let us know if you have any questions.

File: Estimate_1429_-_Pantera_Inspect_Vehicle_and_4_More_-_Colleen__Sheehan_-_1971_Detomaso_Panter.pdf

Angel Vargas	10/3/2024 3:49 PM PDT
---------------------	-----------------------

Hi Colleen ,

Below is a link to the estimate you requested from Stallion Motorsports . Please review and let us know if you have any questions.

File: Estimate_1429_-_Pantera_Inspect_Vehicle_and_4_More_-_Colleen__Sheehan_-_1971_Detomaso_Panter.pdf

Angel Vargas	10/22/2024 5:05 PM PDT
---------------------	------------------------

Hi Colleen ,

Below is a link to the invoice you requested from Stallion Motorsports . Please review and let us know if you have any questions.

File: Invoice_1429_-_Pantera_Inspection__Seized_Brakes__Leaking_Steering_Rack_-_Colleen__Sheehan_-_1971_Detomaso_Panter.pdf



Stallion Motorsports
750 West 17th Street
Costa Mesa, CA 92627
(949) 759-2805
Vargas@Stallionmotorsports.co

Invoice #1429

Created: 10/3/2024
Invoiced: 10/21/2024
Payment Term: On Receipt
Service Writer: Angel Vargas

Angel Vargas

10/23/2024 9:49 AM PDT

Hi Peter,

Below is a link to the invoice you requested from Stallion Motorsports . Please review and let us know if you have any questions.

File: Invoice_1429_-_Pantera_Inspection__Seized_Brakes__Leaking_Steering_Rack._-_Peter_Kumar_-
_1971_Detomaso_Panther.pdf

Declined

Oil Pan Gasket Leaking

	Description	Price	QTY	HRS	Subtotal
1	Oil pan is Leaking Oil, Drain plug looks to have been stripped out so they re-welded a nut to the oil pan repainted it and added a new drain plug but still leaking oil. Recommend replacing with new Upgraded oil pan and replace oil pan gasket. Drain Oil Remove Brake Cable and remove oil pan. Replace Gasket and Install New Pick up tube and Oil pan. Perform Oil Change			4	\$840.00
2	Oil Pan	\$684.25	1		\$684.25
3	Oil Pan Gasket	\$41.34	1		\$41.34
4	Oil Filter	\$12.48	1		\$12.48
5	Castrol Edge 10w-60 Oil	\$25.87	6		\$155.22
		Tax (7.75%): \$69.23		Total: \$1,802.52	