

PIONEER AUTO SERVICE

1955 SAN RAMON VALLEY BLVD.

SAN RAMON, CA 94583

B.A.R. AK 065921

EPA# CAD 094882883

(925) 837-1000

80853

QTY	PART NUMBER	DESCRIPTION	SALE
1	BC20	BRAKE CLEAN	7.95
2	57914	RED LINE 75W140	35.90
		PARTS TOTAL	43.85

NAME [REDACTED]

STREET [REDACTED]

CITY [REDACTED]

HOME PHONE [REDACTED]

REVISED ESTIMATE
+ \$ 0.00

REVISED ESTIMATE
+ \$ 0.00

REVISED ESTIMATE
+ \$ 0.00

INITIAL ESTIMATE
\$ 0.00

LICENSE 80853 / DATE 12/06/07

ODOMETER 0 PROMISED 12/06/07

YEAR-MAKE 1954 JAGUAR 12/13/07

MODEL XK120 WRITTEN BY

ENGINE F8375 SAVE PARTS?

I HEREBY ACCEPT THE INITIAL ESTIMATE, AND HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES, PERMISSION TO OPERATE THE CAR, TRUCK OR VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON CAR, TRUCK OR VEHICLE TO SECURE THE AMOUNT OF REPAIRS THEREON. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

ORIGINAL SIGNED COPY ATTACHED

AUTHORIZED BY X

HOURS	REPAIR ORDER - LABOR INSTRUCTIONS	CHECKED	
0.0			0.00
0.0	CHECK & REPAIR PER NOTE ATTACHED	15	0.00
0.0	REPAIRED ELECTRONIC CHOKE	15	50.00
0.0	REPAIRED BROKEN REAR SHOCKS LINKS	15	200.00
0.0	CLEANED LEAKING PINION SEAL	15	0.00
0.0	TIGHTEN CLAMPS ON LEAKING RADIATOR HOSES	15	0.00
0.0	REPLACED CAM COVERS (CUST. PROVIDED PARTS)	15	150.00
0.0	RESET LOOSE LEFT FRONT SWAY BAR MOUNT BUSHINGS	15	50.00
0.0	REPLACED LEFT HEAD LIGHT BULB (CUST. PROVIDED PARTS)	15	50.00
0.0	REPLACED TRANSMISSION FLUID (CUSTOMER PROVIDED OIL)	15	50.00
0.0	INSTALLED STARTER SOLENOID (CUSTOMER PROVIDED)	15	50.00
0.0			0.00
0.0			0.00

COMP	1/	2/	3/	4/	5/	6/	7/	8/		
RECOMMENDED SERVICE										
I acknowledge notice and oral approval of an increase in the original estimated price. X _____ ALL NEW REPLACEMENT PARTS AND LABOR HAVE A LIMITED WARRANTY FOR 4000 MILES OR 3 MONTHS WHICHEVER COMES FIRST. WARRANTY VALID ONLY IF VEHICLE IS RETURNED TO OUR SERVICE DEPARTMENT FOR ADJUSTMENTS.									MECHANICAL LABOR	600.00
									BODY SHOP LABOR	0.00
									SUBLET REPAIRS	0.00
									PARTS	43.85
									TIRES	0.00
									GAS, OIL & GREASE	0.00
									HAZARDOUS WASTE FEE \$	0.00
									MATERIALS	0.00
									TAX	3.62
TOTAL AMOUNT									647.47	

TOTAL OUTSIDE WORK

ALL NEW REPLACEMENT PARTS AND LABOR HAVE A LIMITED WARRANTY FOR 4000 MILES OR 3 MONTHS WHICHEVER COMES FIRST. WARRANTY VALID ONLY IF VEHICLE IS RETURNED TO OUR SERVICE DEPARTMENT FOR ADJUSTMENTS.

DISCLAIMER OF WARRANTIES: ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. BUYER SHALL NOT BE ENTITLED TO RECOVER FROM THE SELLER ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGE FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

FILE

Ship U.P.S.

HIGH LUSTRE CHROME PLATING
2466 AMERICAN AVENUE • HAYWARD, CA 94541
(510) 785-0198 • FAX (510) 786-1613

Customer
Order No.

Name

Address

SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MOSE. RETD.	PAID OUT	
Quantity	DESCRIPTION					PRICE	AMOUNT
52	JAG XK120						
2	VALVE COVERS						
	POLISH ONLY						150.00
PAID JLSA							
2	PC CENTER						
	WINDSHIELD BAR						300.00
	RE CHROME						
	SHIPPING						25.00
						TAX	
TOTAL							475.00

All claims and returned goods MUST be accompanied by this bill.

21224

Rec'd by



850 Fiero Lane
San Luis Obispo, CA 93401

CREDIT CARD

Phone: (800) 444-5247 (JAGS)

(805) 544-7864

Fax: (805) 544-1664

E-mail: xksunltd@aol.com

Jaguar: www.xks.com

Land Rover: www.xkslandrover.com

Cobra: www.cobrasbyxks.com

Gauges: www.stewartwarner.net

GROUND COMMERCIAL



* INVOICE *

Page 1

Inv # 01 466409

Ord# 62229

P/O # ASK FOR RICH

Br Acct

00 64213

RH

1/08/2008

15:50:57

Part Number	Order	Ship	B/O	Description	Unit	Net	TE	Value
08 BP5ES	6	6		SPARK PLUG	2.88	2.09		12.54
01 JM448	1	1		GASKET, CAM	4.07	4.07		4.07
01 JM448	1	1		GASKET, CAM	4.07	4.07		4.07
08 0415	6	6		PLUG END, C5479	9.95	8.49		50.94

Kats British ok to charge (Bill 7/20/05)

1957 XK140 DHC

**20% RESTOCK CHARGE ON ALL RETURNS **

NO RETURNS AFTER 45 DAYS NO EXCEPTIONS!

PARTS RECEIVED AFTER 45 DAYS WILL BE

RETURNED TO CUSTOMER AT CUSTOMER EXPENSE

CUSTOMER COPY

Tax Rate 7.25

14	71.62	8.90			5.19
TOTAL UNITS	PART TOTAL	CORE TOTAL	SHIPPING & HANDLING	MISCELLANEOUS	LABOR

IMPORTANT: The only warranties applying to this invoice are those which may be offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither the dealer nor any other person shall assume for any liability connected with the sale of this product, except as herein provided. Buyer is advised to inspect the product before any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits or income or any other incidental damages.

RCVD BY

PAY-TO'S AMOUNT

\$ 85.71

MUST HAVE COPY OF INVOICE TO MAKE A RETURN. BACK-ORDERS ARE CANCELLED AFTER 60 DAYS. IF STILL NEEDED, THEY MUST BE REORDERED.

B.A.R. AK 065921 EPA# CAD 094882883 (925) 837-1000

LICENSE	81150	DATE	01/17/08
ODOMETER	95492	PROMISED	01/17/08
YEAR MAKE	1952 JAGUAR		02/22/08
MODEL		WRITTEN BY	
ENGINE	KK120	SAVE PARTS?	
671685			
I HEREBY ACCEPT THE INITIAL ESTIMATE, AND HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEE, PERMISSION TO OPERATE THE CAR, TRUCK OR VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSES OF TESTING AND/OR INSPECTION AT EXCESSIVE MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON CAR, TRUCK OR VEHICLE TO SECURE THE AMOUNT OF REPAIRS THEREFO, YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLE LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.			
ORIGINAL SIGNED COPY ATTACHED			
AUTHORIZED BY X			

ORIGINAL SIGNED COPY ATTACHED

AUTHORIZED BY X

NAME
ST
CIT
HQ
PH

RECEIVED

44 000

REVISÉD ESTIMATE

48 0 00

REVISÉD ESTIMATE

+S 0 00

HOURS	REPAIR ORDER - LABOR INSTRUCTIONS
-------	-----------------------------------

CHECKED

0.0		0.00
0.0	REMOVED & REINSTALLED CAM COVER & INSTALLED NEW GASKETS	15 200.00
0.0	REPLACED FRONT EXHAUST MANIFOLD [CUSTOMER PROVIDED PART]	15 200.00
0.0	REPLACED PLUGS, WIRE ENDS, & IGNITION POINTS & CONDENSOR	15 350.00
0.0	REPAIRED FRONT CARBURATOR FUEL LEAK	15 450.00
0.0	REPAIRED CLUTCH PEDAL LINKAGE	15 350.00
0.0	CHECK CHOKE - CHOKE IS WORKING CORRECT AT THIS TIME	15 0.00
0.0	REPAIRED & REINSTALLED RIGHT REAR SWAY BAR LINK	15 200.00
0.0	REPLACED TRANSMISSION FLUID	15 75.00
0.0	INSTALLED CENTER POST FOR THE WINDSHIELD & TIGHTEN LEFT SIDE	15 50.00
0.0	STRAIGHTEN STEERING WHEEL & TIGHTEN TURN SIGNAL ARM	05 100.00
0.0		0.00
0.0	INSTALLED BATTERY CUT OFF	15 0.00

COMP	1/	2/	3/	4/	5/	6/	7/	8/
------	----	----	----	----	----	----	----	----

RECOMMENDED SERVICE

MECHANICAL LABOR	1975.00
BODY SHOP LABOR	0.00
SUBLET REPAIRS	0.00
PARTS	29.62
TIRES	0.00
GAS, OIL & GREASE	0.00
HAZARDOUS WASTE FEE\$	0.00
MATERIALS	0.00
TAX	2.44
TOTAL AMOUNT	2007.06

I acknowledge notice and oral approval of an increase in the original estimated price.

ALL NEW REPLACEMENT PARTS AND LABOR HAVE A LIMITED WARRANTY FOR 4000 MILES OR 3 MONTHS WHICHEVER COMES FIRST. WARRANTY VALID ONLY IF VEHICLE IS RETURNED TO OUR SERVICE DEPARTMENT FOR ADJUSTMENTS.

TOTAL OUTSIDE WORK

DISCLAIMER OF WARRANTIES: ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. BUYER SHALL NOT BE ENTITLED TO RECOVER FROM THE SELLER ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGE FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

FILE



850 Fiero Lane
San Luis Obispo, CA 93401

Phone: (800) 444-3247 (JAGS)
(805) 544-7864
Fax: (805) 544-1664
E-mail: xksunltd@aol.com
Jaguar: www.xks.com
Land Rover: www.xkslandrover.com
Cobra: www.cobrasbyxks.com
Cruisers: www.stewartwarner.net



* INVOICE *

Page 1

Inv # 01 470689
P/O # JACK

Ord# 71042

Br Acct
00 64213

JK

3/03/2008

13:15:19

Part Number	Order	Ship	P/O	Description	Unit	Net	TR	Value
LU 45169*	1	1		EARLY COIL	31.14	28.00		28.00
Kats British ok to charge (Bill 7/20/05)								
1957 XK140 DHC								

****20% RESTOCK CHARGE ON ALL RETURNS ****
NO RETURNS AFTER 45 DAYS NO EXCEPTIONS!
EXCITING NEWS! CHECK OUT OUR NEWEST
WEBSITE: WWW.WIREWHEELSOURCE.COM

CUSTOMER COPY

Tax Rate 7.25

1	28.00					2.03
TOTAL AMOUNT	PART TOTAL	ORDER TOTAL	SHIPPING & HANDLING	EXCESS/REBATE	LABOR	TAX

DISCLAIMER: This invoice is void if the purchaser does not receive the goods within the time specified. The seller shall not be responsible for any loss of profits, or any other damages, consequential damages, damages to property, or any other damages, except as may be caused by the negligence of the seller. The seller shall not be responsible for any loss of profits, or any other damages, consequential damages, damages to property, or any other damages, except as may be caused by the negligence of the seller.

RCVD
BY:

PAY THIS
AMOUNT

\$ 30.03

MUST HAVE COPY OF INVOICE TO MAKE A RETURN. BACK-ORDERS ARE CANCELLED AFTER 60 DAYS. IF STILL NEEDED, THEY MUST BE REORDERED.

81465

SAN RAMON, CA 94583

EPA# CAD 094882883

(925) 837-1000

COMP	1/	2/	3/	4/	5/	6/	7/	8/	
RECOMMENDED SERVICE									
MECHANICAL LABOR									200.00
BODY SHOP LABOR									0.00
SUBLET REPAIRS									0.00
PARTS									0.00
TIRES									0.00
GAS, OIL & GREASE									0.00
HAZARDOUS WASTE FEES									0.00
MATERIALS									0.00
TAX									0.00
TOTAL AMOUNT									200.00

I acknowledge notice and oral approval of an increase in the original estimated price. X _____

ALL NEW REPLACEMENT PARTS AND LABOR HAVE A LIMITED WARRANTY FOR 4000 MILES OR 3 MONTHS WHICHEVER COMES FIRST. WARRANTY VALID ONLY IF VEHICLE IS RETURNED TO OUR SERVICE DEPARTMENT FOR ADJUSTMENTS.

DISCLAIMER OF WARRANTIES: ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER KNOWN OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. BUYER SHALL NOT BE ENTITLED TO RECOVER FROM THE SELLER ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGE FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

FILE

PIONEER AUTO SERVICE

1955 SAN RAMON VALLEY BLVD.

SAN RAMON, CA 94583

B.A.R. AK 065921

EPA# CAD 094882883

(925) 837-1000

81515

QTY	PART NUMBER	DESCRIPTION	SALE
1	C19590K	PAN GASKET SET	34.20
12	15W40	15W40 CHEVRON 400 MOTOR O	39.00
2	90WT	GEAR OIL [PINTS]	4.13
		PARTS TOTAL	77.33

NAME	
STR	
CITY	
HOME	
PHONE	

REVISED ESTIMATE	INITIAL ESTIMATE
+\$ 0.00	
REVISED ESTIMATE	
+\$ 0.00	\$ 0.00
REVISED ESTIMATE	
+\$ 0.00	

LICENSE	DATE
81150 /	03/10/08
ODOMETER	PROMISED
0	03/10/09
YEAR/MARK	
1952 JAGUAR	03/14/08
MODEL	WRITTEN BY
XX120	
ENGINE	SAVE PARTS?
671685	
I HEREBY ACCEPT THE INITIAL ESTIMATE, AND HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES, PERMISSION TO OPERATE THE CAR, TRUCK OR VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON CAR, TRUCK OR VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERE TO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.	
ORIGINAL SIGNED COPY ATTACHED	
AUTHORIZED BY X	

HOURS	REPAIR ORDER - LABOR INSTRUCTIONS	CHECKED	
0.0			0.00
0.0	CHECK CARBS - READJUSTED CARBS. & ADJUSTED TIMING	15	0.00
0.0			0.00
0.0	DISCOUNT	02	-37.30
0.0	TRANSMISSION DRAIN AND REFILL	15	50.00
0.0			0.00
0.0			0.00
0.0	CHECK STARTER BUTTON	15	0.00
0.0	REPLACED OIL PAN GASKET	15	300.00
0.0			0.00
0.0	CHECK HORN - REMOVED & DISASSEMBLED HORN - CLEANED &		0.00
0.0	REPAIRED HORN	09	100.00
0.0			0.00

COMP	1/	2/	3/	4/	5/	6/	7/	8/	
RECOMMENDED SERVICE									
MECHANICAL LABOR									412.70
BODY SHOP LABOR									0.00
SUBLET REPAIRS									0.00
PARTS									77.33
TIRES									0.00
GAS, OIL & GREASE									0.00
HAZARDOUS WASTE FEES									3.60
MATERIALS									0.00
TAX									6.36
TOTAL AMOUNT									500.00

I acknowledge notice and oral approval of an increase in the original estimated price. X

TOTAL OUTSIDE WORK

ALL NEW REPLACEMENT PARTS AND LABOR HAVE A LIMITED WARRANTY FOR 4000 MILES OR 3 MONTHS WHICHEVER COMES FIRST. WARRANTY VALID ONLY IF VEHICLE IS RETURNED TO OUR SERVICE DEPARTMENT FOR ADJUSTMENTS.

DISCLAIMER OF WARRANTIES: ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. THE SELLER DOES NOT AUTHORIZE ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. BUYER SHALL NOT BE HELD RESPONSIBLE FOR THE SELLER'S NEGLIGENCE OR ANY OTHER INCIDENTAL DAMAGES.

FILE



San Ramon Body and Detail

10 Beta Court
San Ramon, California 94583
925.838.8380 FAX 925.838.6254
BAR# AH097174

Final Invoice

RO #:25849

Unit #:

Arrived: 3/17/2008

Ready:

Estimator: Quigley, Glenn

Customer Information

Name:
Address:
Phone:

Vehicle Information

Vehicle: 2063 RED JAGU XK120
Style: 2D CNVT
License: 1
VIN: 1
Mileage: 1
Mileage Out:

Insurance Information

Ins Co: SELF PAY
Contact:
Phone:
Claim #: 1
Deduct: \$0.00

#	S# Operation	Description	Type	Price	Adj Price	T	Lbr	Addl	Dept	Paint	Addl
1		PDR HOOD	SL	\$100.00					B		
2	Refinish	GLASS HOLDER				✓			R	1.0	
2	Repair	GLASS HOLDER				✓	1.0		B		
3	Refinish	RT FENDER				✓			R	2.0	
3	Repair	RT FENDER				✓	2.0		B		
4	Refinish	PASSENGER COVER				✓			R	2.0	
4	Repair	PASSENGER COVER				✓	1.0		B		
5		MATCH COLOR				✓	1.0		B		
6		POLISH				✓	1.0		B		
7		O/S COVER x2		\$20.00		✓	0.2		B		
11		Shop Supplies	SS	\$12.00		✓					
12		Paint Materials	PM	\$175.00		✓					

Totals:

RO:

Supp:

Total:

Final (Combined) Totals

Body Labor	\$496.00	\$496.00
Refinish Labor	\$400.00	\$400.00
LABOR TOTAL	\$896.00	\$896.00
Shop Supplies	\$12.00	\$12.00
Sublet	\$100.00	\$100.00
Paint Materials	\$175.00	\$175.00
Miscellaneous	\$20.00	\$20.00
Sub Total	\$1,203.00	\$1,203.00
Sales Tax (8.250%)		\$17.08
GRAND TOTAL		\$1,220.08

PIONEER AUTO SERVICE

1955 SAN RAMON VALLEY BLVD.

SAN RAMON, CA 94583

B.A.R. AK 065921

EPA# CAD 094882883

(925) 837-1000

QTY	PART NUMBER	DESCRIPTION	SALE
1	097-001	DRAIN PLUG GASKET 1/2" ID	0.36
5	MPB443CN	STAINLESS FASTENERS	17.34
		PARTS TOTAL	17.70

NAME	
STR	
CITY	
HON	
PHO	

LICENSE	81150 /	DATE	03/31/08
ODOMETER	55566	PROMISED	03/31/08
YEAR-MAKE	1952 JAGUAR		04/03/08
MODEL	XX120	WRITTEN BY	
ENGINE	671695	SAVE PARTS?	
I HEREBY ACCEPT THE INITIAL ESTIMATE, AND HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES, PERMISSION TO OPERATE THE CAR, TRUCK OR VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON CAR, TRUCK OR VEHICLE TO SECURE THE AMOUNT OF REPAIRS THEREON. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL. ORIGINAL SIGNED COPY ATTACHED AUTHORIZED BY X _____			

REVISED ESTIMATE	INITIAL ESTIMATE
+\$ 0.00	
REVISED ESTIMATE	\$ 0.00
+\$ 0.00	
REVISED ESTIMATE	
+\$ 0.00	

HOURS	REPAIR ORDER - LABOR INSTRUCTIONS	CHECKED	
0.0		09	0.00
0.0	PASSENGER HEADLIGHT LOOSE - REPAIRED LOOSE HEAD LIGHT FRAME	13	350.00
0.0	CHECK NO START - FOUND LOOSE TERMINALS AT THE FUSE BOX ASSY	13	0.00
0.0	REPAIRED FUSE BOX ASSY.	13	400.00
0.0	CLEAN & SERVICE BATTERY TERMINALS	13	50.00
0.0			0.00
0.0			0.00
0.0	REPLACED BOTH HEADERS & NUTS [CUSTOMER PROVIDED PARTS]	13	200.00
0.0			0.00
0.0			0.00
0.0	CHECK LIGHTS - ALL LIGHTS ARE WORKING AT THIS TIME	05	0.00
0.0			0.00
0.0			0.00

COMP	1/	2/	3/	4/	5/	6/	7/	8/	
RECOMMENDED SERVICE									
									MECHANICAL LABOR 700.00
									BODY SHOP LABOR 0.00
									SUBLET REPAIRS 0.00
									PARTS 17.70
									TIRES 0.00
									GAS, OIL & GREASE 0.00
									HAZARDOUS WASTE FEES 0.00
									MATERIALS 0.00
									TAX 1.46
									TOTAL AMOUNT 719.16
I acknowledge notice and oral approval of an increase in the original estimated price. X _____									
ALL NEW REPLACEMENT PARTS AND LABOR HAVE A LIMITED WARRANTY FOR 4000 MILES OR 3 MONTHS WHICHEVER COMES FIRST. WARRANTY VALID ONLY IF VEHICLE IS RETURNED TO OUR SERVICE DEPARTMENT FOR ADJUSTMENTS.									

TOTAL OUTSIDE WORK

DISCLAIMER OF WARRANTIES: ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR GUARANTEES THE RESULTS OF ANY REPAIRS. THE SELLER SHALL NOT BE ENTITLED TO RECOVER FROM THE BUYER ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, LOSS OF TIME, LOSS OF INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

850 Fiero Lane
San Luis Obispo, CA 93401

Phone: (800) 444-5247 (JAGS)
(805) 544-7864
Fax: (805) 544-1664
E-mail: xksunltd@aol.com
Jaguar: www.xks.com
Land Rover: www.xkslandrover.com
Cobra: www.cobrasbyxks.com
Gauges: www.stewartwarner.net



★ I N V O I C E ★

Page 1

Inv # 01 474014
P/O # JACK

Ord# 77766

Br Accent
00 64213

JK

4/14/2008

11:22:39

Part Number	Order	Ship	B/O	Description	Unit	Net	TE	Value
17 3650	1	1		PERTRONIX KIT	193.70	174.00		174.00

Note: This kit fits XK-120, XK-140, MK VII and Mk VIII with positive ground.

Kats British ok to charge (Bill 7/20/05)

1957 XK140 DHC

20% RESTOCK CHARGE ON ALL RETURNS
 NO RETURNS AFTER 45 DAYS NO EXCEPTIONS!
 EXCITING NEWS! CHECK OUT OUR NEWEST
 WEBSITE: WWW.WIREWHEELSOURCE.COM

CUSTOMER COPY

Tax Rate						
1	174.00		10.46			
TOTAL UNITS	PART TOTAL	CORE TOTAL	SHIPPING & HANDLING	MISC. CHARGES	LABOR	TAX

DISCLAIMER: The only agreement applying to this program is the one which may be offered by the manufacturer. The selling dealer has no liability, contractual or otherwise, as a supplier, a sponsor, a participant, or a witness in the sale of the merchandise. The dealer is not a party to the sale, and neither assumes any liability nor any other position in the sale, and any liability occurring in the sale of the merchandise under this program shall not be applied to or assumed by the selling dealer and contractor. No damages, damages to property, damages to persons, or any other form of liability, or injury, or death shall be assumed by the dealer.

RCVD.
BY

**PAY THIS
AMOUNT.**

e 184.46

MUST HAVE COPY OF INVOICE TO MAKE A RETURN. BACK-ORDERS ARE CANCELLED AFTER 60 DAYS. IF STILL NEEDED, THEY MUST BE REORDERED.



850 Fiero Lane
San Luis Obispo, CA 93401

Phone: (800) 444-5247 (JAGS)
(805) 344-7864
Fax: (805) 344-1664
E-mail: xksunltd@aol.com
Jaguar: www.xks.com
Land Rover: www.xkslandrover.com
Cobra: www.cobrasbyxks.com
Gauges: www.stewartwarner.net



* I N V O I C E *

Page 1

Inv # 01 474266
P/O # JACK

Ord# 78214

Br Acct
00 64213

JK

4/16/2008

10:09:51

Part Number	Order	Ship	B/O	Description	Unit	Net	TR	Value
17 0101	1	1		TOOL ROLL	61.97	55.00		55.00
11 0020	1	1		OWNER'S MANUAL	46.20	40.00		40.00
11 0010	1	1		OWNER'S MANUAL	40.88	35.00		35.00

Kats British ok to charge (Bill 7/20/05)
1957 XK140 DHC

****20% RESTOCK CHARGE ON ALL RETURNS ****
NO RETURNS AFTER 45 DAYS NO EXCEPTIONS!
EXCITING NEWS! CHECK OUT OUR NEWEST
WEBSITE: WWW.WIREWHEELSOURCE.COM

C U S T O M E R C O P Y

Tax Rate 7.25

3	130.00	10.92			9.43
TOTAL UNITS	PART TOTAL	CORE TOTAL	SHIPPING & HANDLING	MISCELLANEOUS	LABOR

IMPORTANT: The only warranty we are giving is this price, we know which may be offset by the manufacturer. The selling dealer hereby
represents that the vehicle is in good condition, either as shown or implied, and is giving no implied warranty of merchantability for use for a particular
purpose, and neither we, nor our dealer, can be held responsible for any liability arising from the use of this product and/or
service. Buyer is not to be held responsible for any damage to the vehicle, use, or other damage, damage to property, damage to a self
love, loss of time, loss of profits, or income, or any other financial damage.

RCVD
BY:

PAY THIS
AMOUNT

\$ 150.35

MUST HAVE COPY OF INVOICE TO MAKE A RETURN. BACK-ORDERS ARE CANCELLED AFTER 60 DAYS. IF STILL NEEDED, THEY MUST BE REORDERED.

81689

SAN RAMON, CA 94583

EPA# CAD 094882883

(925) 837-1000

LICENSE	81150 /	DATE	04/17/08
ODOMETER	9560	PROMISED	04/17/08
YEAR-MAKE	1952 JAGUAR		04/17/08
MODEL		WRITTEN BY	
ENGINE	XK120	SAVE PARTS	
S71685			
I HEREBY ACCEPT THE INITIAL ESTIMATE, AND HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AROUND FOUR EMPLOYEES PERMISSION TO OPERATE THE CAR, TRUCK OR VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR FARMHOUSES FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS WARRANTY IS NOT GIVEN. MY SIGNATURE BELOW INDICATES THAT I HAVE NO OTHER CLAIMS LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.			
ORIGINAL SIGNED COPY ATTACHED			

[illegible]

ORIGINAL SIGNED COPY ATTACHED

... ..

NA 33 P	
BT	
CI	
HC	
PH	

REVISED ESTIMATE	INITIAL ESTIMATE
+\$ 0.00	
REVISED ESTIMATE	
+\$ 0.00	\$ 0.00
REVISED ESTIMATE	
+\$ 0.00	

[illegible]

COMP	1/	2/	3/	4/	5/	6/	7/	8/
RECOMMENDED SERVICE								
MECHANICAL LABOR								
BODY SHOP LABOR								
SUBLET REPAIRS								
PARTS								
TIRES								
GAS, OIL & GREASE								
HAZARDOUS WASTE FEES								
MATERIALS								
TAX								
TOTAL AMOUNT								

DISCLAIMER OF WARRANTIES: ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. BUYER SHALL NOT BE ENTITLED TO RECOVER FROM THE SELLER ANY CONSEQUENTIAL DAMAGES FOR LOSS OF PROFITS, LOSS OF TIME, LOSS OF USE, LOSS OF DATA, OR FOR ANY OTHER INCIDENTAL DAMAGES.

FILE

Pioneer Auto Service
1955 San Ramon Valley Blvd
San Ramon, CA. 94583
Phone - 925-837-1000 Fax - 925-837-2513

INVOICE

10742

ARD# AF234142
EPA# CAL000284528

INVOICE

Print Date : 07/21/2008

1952 Jaguar - XK120

I6

Lic # : 81150

Odometer In : 9560

Unit # :

Vin # : 671685

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
				Check engine for running	2.00	200.00
				Found the distributor Bad - Installed new points & condensor - Did not repair problem		
				Replaced distributor with new points & condensor	3.00	300.00
				Installed electronic ignition in the original distributor - Test drove - OK	3.50	350.00
[Technicians : Condon, John 15]						

Org. Estimate \$0.00 Revisions \$0.00 Current Estimate \$ 0.00 Additional Cost Revised Estimate

Labor:	850.00
Parts:	0.00
Sublet:	0.00

Sub:	850.00
Tax:	0.00
Total:	850.00
Bal Due:	\$0.00

[Payments - Check - \$850.00]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....

Pioneer Auto Service
 1955 San Ramon Valley Blvd
 San Ramon, CA. 94583
 Phone - 925-837-1000 Fax - 925-837-2513

INVOICE

10880

ARD# AF234142
 EPA# CAL000284528

INVOICE

Work Completed Date : 08/12/2008

Print Date : 09/04/2008

1952 Jaguar - XK120

I6

Lic # : 81150

Odometer In : 9600

Unit # :

Vin # : 671685

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
Engine Mount CO428	2.00	35.00	70.00	Check engine cut out	1.00	120.00
Engine Mount CO478	1.00	53.00	53.00	Found the front carburetor float sticking - adjusted & rechecked - Test drove -OK		
Switch sls24	1.00	19.70	19.70	Check missing bolts in rear end	1.00	120.00
Pan Gasket Pai 19590PR	1.00	10.57	10.57	Installed 3 missing nuts in the rear springs		
Cork Strip 2302	1.00	12.95	12.95	2 Wheel Alignment	1.00	95.00
trac rod bushing C3493	1.00	96.54	96.54	2 wheel alignment and road test vehicle.		
				Check engine & transmission mounts - all check OK	N/A	N/C
				Check transmission oil leak	N/A	N/C
				Spray sealant on all seals & gasket [accesable]		
				Replaced brake light switch	2.50	300.00
				Check engine oil leak	N/A	N/C
				Found the engine oil pan gasket leaking - tighten pan gasket bolts & sprayed sealant on gasket		
				Refaced front brake drums	2.00	240.00
				Replaced steering rod bushings	2.50	300.00
				Hazardous Materials		5.00

[Technicians : Condon, John 15; Please Select, Technician]

Org. Estimate \$0.00 Revisions \$0.00 Current Estimate \$ 0.00 Additional Cost Revised Estimate

Labor:	1,180.00
Parts:	262.76
Sublet:	0.00

Sub:	1,442.76
Tax:	21.68
Total:	1,464.44
Bal Due:	\$0.00

[Payments - Check - \$1464.44]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....

Pioneer Auto Service
1955 San Ramon Valley Blvd
San Ramon, CA. 94583
Phone - 925-837-1000 Fax - 925-837-2513

INVOICE

13770

ARD# ARD234142
EPA# CAL000284528

INVOICE

Print Date : 09/04/2009

1952 Jaguar - XK120

I6


Lic # : 81150

Odometer In : 9600

Unit # :

Vin # : 671685

Hat # :



Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
				Repaired ding on the left front fender	1.00	120.00
				Repaired loose steering wheel	0.50	60.00
[Technicians : Fuenzalida, Bob]						

Org. Estimate \$0.00	Revisions \$0.00	Current Estimate \$ 0.00	Additional Cost	Revised Estimate	Labor:	180.00
					Parts:	0.00
					Sublet:	0.00

					Sub:	180.00
					Tax:	0.00
					Total:	180.00
					Bal Due:	\$180.00
[Payments -]						

I hereby authorize the above repair work to be done along with the necessary material. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty valid only if vehicle is returned at customer's expense to Pioneer Auto Service & cannot exceed the original cost of repair. All replaced parts are new unless other wise specified.

SIGNATURE..... Date..... Time.....



1390 West Highway 26
Blackfoot, Idaho 83221
Internet: www.vintagejag.com

Voice: (208) 684-4767
Fax: (208) 684-3386
Email: sales@vintagejag.com

8808

XK-120

BILL TO	
NAME:	
ADDRESS:	
PHONE:	
FAX OR EMAIL:	

SHIP TO	
NAME:	PIONEER AUTO SERVICE
ADDRESS:	1955 SAN RAMON VALLEY BLVD. SAN RAMON, CA. 94583
PHONE:	925 837 1000
FAX OR EMAIL:	

CUSTOMER'S ORDER	SALESMAN	TERMS	SHIP VIA	F.O.B. LOCATION	DATE
core reid	WALT.		UPS-GRND.	BLFT.	10 NOV 09

1 C2549/1 Rebuilt Transmission, Recond-Exch.
(Core reid - Rebuild customer's core)

1 C905 3rd/4th Selector Pinion

1 C858 Speedo Assy.

1 C1897 1st SPEED GEAR

1 C1853 " " 1st Hub. } matched pair

Thank you for your business.

2000 dollar value

Su
Sale
Shipping and Handling
TC

110 #s 36x21x20

william ross

From: [REDACTED]
 To: [REDACTED]
 Sent: Monday, December 07, 2009 1:07 PM
 Subject: UltraRev.com: Order receipt #1043

You have received this notification from UltraRev.com because you are a registered user or you or some other registered user requested some information for you from our store.

Dear Mr. william ross,

Thank you for your order. Please come back soon!

Invoice:




INVOICE

Date: 12/07/2009 15:07:48
 Order id: #1043
 Order status: Processed
 Payment method:
 Purchase Order
 Delivery method:
 FedEx Home Delivery


UltraRev.com
 750 Central Ave, Farmingdale
 07727, New Jersey
 United States
 CALL US: 1-877-858-7272
 International: 732-938-3999
 Fax: 732-938-4999
 E-Mail: ray@ultrarev.com

Company:
 First Name:
 Last Name:
 Phone:
 Fax:
 E-Mail:
 URL:




Billing Address

Address:
 City:
 State:
 Country:
 Zip/Postal code:



Shipping Address

First Name:
 Last Name:
 Address:
 City:
 State:
 Country:
 Zip/Postal code:



Products ordered

SKU	Product	Item price	Quantity	Total
119421	Fidanza Aluminum Flywheel Options: application_note: 133 Ring Gear engine_type: 3.4L	\$320.00	1	\$320.00

Subtotal: \$320.00

Shipping cost: \$20.00

Total: \$340.00



Voice: (208) 684-4767
Fax: (208) 684-3386
Email: sales@vintagejag.com

8842

BILL TO	
NAME:	
ADDRESS:	
PHONE:	
FAX OR EMAIL:	

SHIP TO	
NAME:	
ADDRESS:	
PHONE:	
FAX OR EMAIL:	

CUSTOMER'S ORDER	SALESMAN	TERMS	SHIP VIA	F.O.B. LOCATION	DATE
ph. BILL	WALT.	RP. VISA	UPS-GRND.	BLFT	4 JAN 10
1	CRT 200K	Short Cracks Repair Kit.			8779

Thank you for your business.

Subtotal	87.79
Sales tax	
Shipping and Handling Fees	10.92
TOTAL	98.71

(# $8 \times 4 \times 3$)



850 Fiero Lane
San Luis Obispo, CA 93401

CREDIT CARD

Pho: (800) 444-5247 (JAGS)
(805) 544-7864
Fax: (805) 544-1664
E-mail: xksunltd@aol.com
Jaguar: www.xks.com
Land Rover: www.xkslandrover.com
Cobra: www.cobrasbyxks.com
Gauges: www.stewartwarner.net



* INVOICE *

Page 1

Inv # 01 520555
P/O # DARYL EXT242

Ord# 69547

Br Acct
00 64213

GROUND RESIDENTIAL

DB

1/14/2010

16:19:07

Part Number	Order	Ship	B/O	Description	Unit	Net	TE	Value
BD 13051	1	1		150 WINDSHIELD	368.22	349.81		349.81
SP 0001	30	30		SPECIAL PACKING	1.00	1.00		30.00
18 0011	1	1		RUBBER W/S SEAL	107.46	102.08		102.08
18 2017-1	11	11		W/S LOCK STRIP	2.19	1.99		21.89

1957 XK140 DHC

1960 XK150 (SOLD TO [REDACTED])

20% RESTOCK CHARGE ON ALL RETURNS

NO RETURNS AFTER 45 DAYS NO EXCEPTIONS!

EXCITING NEWS! CHECK OUT OUR NEWEST

WEBSITE: WWW.WIREWHEELSOURCE.COM

CUSTOMER COPY

Tax Rate 8.25

43	503.78	104.84				39.09
TOTAL UNITS	PART TOTAL	CORE TOTAL	SHIPPING & HANDLING	MISCELLANEOUS	LABOR	TAX

DISCLAIMER: The only warranties applying to this product are those which may be offered by the manufacturer. The selling dealer hereby disclaims any and all warranties, express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither we, nor our authorized sales representatives, assume any liability in connection with the sale of this product and/or service. Buyer shall not be entitled to a return from the selling dealer for any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

RCVD.
BY: _____

PAY THIS
AMOUNT

\$ 647.71

MUST HAVE COPY OF INVOICE TO MAKE A RETURN. BACK-ORDERS ARE CANCELLED AFTER 60 DAYS. IF STILL NEEDED, THEY MUST BE REORDERED.

Pioneer Auto Service
 1955 San Ramon Valley Blvd
 San Ramon, CA. 94583
 Phone - 925-837-1000 Fax - 925-837-2513

INVOICE

14131

ARD# ARD234142
 EPA# CAL000284528

INVOICE

Print Date : 02/03/2010



1952 Jaguar - XK120

I6

Lic # : 81150

Odometer In : 9731

Unit # :

Vin # : 671685

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
Housing gasket 2248	1.00	14.30	14.30	Check oil leak	N/A	N/C
Gasket, Cam JM448	2.00	4.97	9.94	oil pan gasket		
Valvoline - 30W 265	2.00	7.29	14.58	oil filter housing gasket		
Starter Motor 173999	1.00	239.95	239.95	valve cover gasket		
				radiator leak		
				Replaced left & right cam cover gaskets	2.00	240.00
				Replaced oil filter housing gasket & spray	1.50	180.00
				oil pan gasket with sealant		
				Adjust convertible top latch	1.50	180.00
				Remove & reinstall transmission	18.00	2,160.00
				Replaced starter motor & fly wheel		
				Replaced driver side battery [Warranty]	N/A	N/C
				Hazardous Materials		5.00

[Technicians : Condon, John 15; Please Select, Technician]

Org. Estimate \$0.00	Revisions \$0.00	Current Estimate \$ 0.00	Additional Cost	Revised Estimate	Labor:	2,765.00
					Parts:	278.77
					Sublet:	0.00

					Sub:	3,043.77
					Tax:	25.79
					Total:	3,069.56
					Bal Due:	\$3,069.56

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty valid only if vehicle is returned at customer's expense to Pioneer Auto Service & cannot exceed the original cost of repair. All replaced parts are new unless other wise specified.

SIGNATURE..... Date..... Time.....

Pioneer Auto Service
1955 San Ramon Valley Blvd
San Ramon, CA. 94583
Phone - 925-837-1000 Fax - 925-837-2513

INVOICE

15193

ARD# ARD234142
EPA# CAL000284528

INVOICE

Work Completed Date : 03/26/2010

Print Date : 03/26/2010

1952 Jaguar - XK120

I6

Lic # : 81150

Odometer In : 97420

Unit # :

Vin # : **671685**

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
Windshield adhesive				4 wheel alignment check	1.00	120.00
U-428	1.00	7.00	7.00	Check & align all four wheels and road test vehicle		
				Repaired right windshield wiper arm	0.50	60.00
				Adjusted parking brake	0.50	60.00
				Adjusted 4th gear shift linkage	2.00	240.00
				Hazardous Materials		5.00
[Technicians : Please Select, Technician]						

Org. Estimate \$0.00 Revisions \$0.00 Current Estimate \$ 0.00 Additional Cost Revised Estimate

Labor:	485.00
Parts:	7.00
Sublet:	0.00

Sub:	492.00
Tax:	0.65
Total:	492.65
Bal Due:	\$0.00

[Payments - Debit - \$492.65]

I hereby authorize the above repair work to be done along with the necessary material. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty valid only if vehicle is returned at customer's expense to Pioneer Auto Service & cannot exceed the original cost of repair. All replaced parts are new unless other wise specified.

SIGNATURE..... Date..... Time.....

Pioneer Auto Service
1955 San Ramon Valley Blvd
San Ramon, CA. 94583
Phone - 925-837-1000 Fax - 925-837-2513

INVOICE

16233

ARD# ARD234142
EPA# CAL000284528

INVOICE

Work Completed Date : 09/03/2010

Print Date : 09/03/2010

1952 Jaguar - XK120

I6

Lic # : 81150

Odometer In : 97953

Unit # :

Vin # : **671685**

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
Thermostat 33006	1.00	9.26	9.26	Check dash panel Tach, water, fuel Found that the tachometer needle was stock removed dash board and repair tachometer - Test Drove re checked ok at this time	3.00	390.00
				Check carbs popping and back firing Found that the coil wire wasn't making a good connection Cleaned connection and repair coil wire - Test Drove re check ok at this time	1.00	130.00
				Check steering loose and when hitting bump car drifts to the left Found that the right lower control arm bolt was loose Tightened - Test Drove re check ok at this time	1.00	130.00
				Check suspension for alignment issue Found that the alignment is to spec at this time OK	0.30	39.00
				Replace fuel sending unit (Customer supplied fuel sending unit) Replaced fuel sending unit re checked - Test Drove ok at this time	1.00	130.00
				Replace thermostat Found that there was no thermostat in cooling system Replaced Thermostat - Test Drove re check ok at this time	1.00	130.00
				Hazardous Materials		5.00

Pioneer Auto Service
1955 San Ramon Valley Blvd
San Ramon, CA. 94583
Phone - 925-837-1000 Fax - 925-837-2513

INVOICE

16233

ARD# ARD234142
EPA# CAL000284528

INVOICE

Work Completed Date : 09/03/2010

Print Date : 09/03/2010

1952 Jaguar - XK120

I6

Lic # : 81150

Odometer In : 97953

Unit # :

Vin # : 671685

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
---------------------------	-----	------	----------	-------------------	-------	----------

[Technicians : Please Select, Technician]

Org. Estimate	Revisions	Current Estimate	Additional Cost	Revised Estimate
---------------	-----------	------------------	-----------------	------------------

Labor:	954.00
Parts:	9.26
Sublet:	0.00

Sub:	963.26
Tax:	0.86
Total:	964.12
Bal Due:	\$0.00

[Payments - Check (#6857) - \$964.12]

I hereby authorize the above repair work to be done along with the necessary material. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty valid only if vehicle is returned at customer's expense to Pioneer Auto Service & cannot exceed the original cost of repair. All replaced parts are new unless other wise specified.

SIGNATURE..... Date..... Time.....

Pioneer Auto Service
 1955 San Ramon Valley Blvd
 San Ramon, CA. 94583
 Phone - 925-837-1000 Fax - 925-837-2513

INVOICE
16392

ARD# ARD234142
 EPA# CAL000284528

INVOICE

Print Date : 10/29/2010

1952 Jaguar - XK120

I6

Lic # : 81150

Odometer In : 97960

Unit # :

Vin # : **671685**

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
Transmission oil 50204	3.00	19.90	59.70	Check lose of power [Fuel lose] Adjusted carburetors - test drove - OK	2.00	240.00
B-12 carb Cleaner 0117C	1.00	7.86	7.86	Check loose front end [tighten gear box] Adjusted front shocks for a harder ride & tighten gear box	2.50	325.00
Carb rebuild kit 03 0044	2.00	38.02	76.04	Check transmission - sticks in 3rd gear at time	N/A	N/C
40W 98BC69	3.00	5.98	17.94	Recommend to remove transmission for repair Jim Groom Groom Service 510-525-4936 Removed & reinstalled transmission assy. Hazardous Materials	18.00	2,160.00 5.00

[Technicians : Fuenzalida, Bob; Please Select, Technician]

Org. Estimate \$0.00 Revisions \$0.00 Current Estimate \$ 0.00 Additional Cost Revised Estimate

Labor:	2,730.00
Parts:	161.54
Sublet:	0.00

Sub:	2,891.54
Tax:	14.94
Total:	2,906.48
Bal Due:	\$2,906.48

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty valid only if vehicle is returned at customer's expense to Pioneer Auto Service & cannot exceed the original cost of repair. All replaced parts are new unless other wise specified.

SIGNATURE.....

Date.....

Time.....

The largest independent retailer of new, used
& rebuilt Jaguar spares since 1965


** Cash Sale **

Invoice: 1-281873

Page: 1

Time: 02:52PM

Date: 01/20/11



Date Received: 01/20/11	Salesman: KORT, HERKY X164	Terms: CREDIT CARD
Date Shipped : 01/20/11	Ship CD : FIRST CLASS MAIL	Acct#: 38570
Emp : KORT, HERKY X164	P.O. # : XK120	Man #:

Ln	Qty	B/O	UOM	Part Number	Description	Price	Extended
001	1	0	EA	BD-3037	CVR JACK HOLE XK120 XK	18.95	18.95
002	2	0	EA	408120	NUT COIL WIRE LONG NUT	0.95	1.90
003	1	0	EA	164	HERKY'S EXT.IS 164		0.00
004	SHIPPED BY USM						5.56

** PAYMENT INFO **

CREDIT CARD XXXX-XXXX-XXXX-502

26.41

Expiration Date : 09/13

TOTAL AMOUNT TENDERED : 26.41

Sub Total :	20.85
Fgt Total :	5.56
Tax :	0.00
Total Due :	26.41



850 Fiero Lane
San Luis Obispo, CA 93401 U.S.A.

North America: (800) 444-5247 (JAGS)
International: (805) 544-7864
Worldwide Fax: (805) 544-1664
E-mail: customerservice@xks.com
Jaguar: www.xks.com
Land Rover: www.goldcoastrovers.com
Gauges: www.stewartwarner.net
Wheels: www.wirewheelsource.com



* I N V O I C E *

Page 1

Inv # 01 547346

Ord# 23645

P/O # BILL

Br Acct

00 64213

BH

2/22/201

15:13:0

Part Number	Order	Ship	B/O	Description	Unit	Net	TE	Value
CO 3455	1	1		RADIATOR CAP	16.54	16.54		16.54
02 FG2421	2	2		OIL FILTER	8.20	8.20		16.40
17 2100	1	1		U-JACK BADGE	18.29	16.25		16.25

1957 XK140 DHC AND 52 XK120

**20% RESTOCK CHARGE ON ALL RETURNS **

NO RETURNS AFTER 30 DAYS NO EXCEPTIONS!

***WE ARE NOW ON FACEBOOK- JOIN OUR

GROUP. GO TO WWW.XKS.COM TO SIGN UP***

CUSTOMER COPY

Tax Rate 8.25

4	49.19		11.33			4.06
TOTAL UNITS	PART TOTAL	CORE TOTAL	SHIPPING & HANDLING	MISCELLANEOUS	LABOR	TAX

NOT VALID: The only merchandise acceptable for return is that which may be offered by the manufacturer. The selling dealer hereby disclaims all liability for merchandise, whether original or rebuilt, accepting any implied warranties of manufacturer or dealer for a particular product, and neither manufacturer nor dealer shall be liable for any liability connection with the sale of this product, and the manufacturer, dealer and seller disclaim any liability for any consequential damage, damage to property, damage to person or loss of life, loss of profits, or other incidental damages.

RCVD.
BY:

PAY THIS
AMOUNT

\$ 64.58

MUST HAVE COPY OF INVOICE TO MAKE A RETURN. BACK-ORDERS ARE CANCELLED AFTER 60 DAYS. IF STILL NEEDED, THEY MUST BE REORDERED.



850 Fiero Lane
San Luis Obispo, CA 93401 U.S.A.

North America: (800) 444-5247 (JAGS)
International: (805) 544-7864
Worldwide Fax: (805) 544-1664
E-mail: customerservice@xks.com
Jaguar: www.xks.com
Land Rover: www.goldcoastrovers.com
Gauges: www.stewartwarner.net
Wheels: www.wirewheelsource.com



* I N V O I C E *

Page 1

Inv # 01 549604
P/O # STEVE

Ord# 27907

Br Acct
00 64213

SP

3/23/2011

12:38:41

Part Number	Order	Ship	B/O	Description	Unit	Net	TE	Value
17 2100	1	1		U-JACK BADGE	18.29	16.25		16.25
JA 1048	2	2		JACK PLUG, XK	6.27	5.45		10.90
LU DDB161	1	1		DISTRIBUTOR CAP	44.95	35.96		35.96
LU CYB301	7	7		WASHER	1.78	1.48		10.36

1957 XK140 DHC AND 52 XK120

**20% RESTOCK CHARGE ON ALL RETURNS **

NO RETURNS AFTER 30 DAYS NO EXCEPTIONS!

***WE ARE NOW ON FACEBOOK- JOIN OUR

GROUP. GO TO WWW.XKS.COM TO SIGN UP***

CUSTOMER COPY

Tax Rate 8.25

11	73.47	10.82				6.06
TOTAL UNITS	PART TOTAL	CORE TOTAL	SHIPPING & HANDLING	MISCELLANEOUS	LABOR	TAX

NOTE: The only warranties applying to this product are those which may be offered by the manufacturer. The selling dealer hereby disclaims any implied warranties of merchantability or fitness for a particular purpose, and neither, nor any other person is aware of any liability connection with the sale of this product and/or service. Items shall not be returned to seller from the selling dealer for any reason other than original damages, damage to property, damage for loss of use, abuse, fire, flood, theft, or other causes.

RCVD.
BY: _____

PAY THIS
AMOUNT

\$ 90.35

MUST HAVE COPY OF INVOICE TO MAKE A RETURN. BACK-ORDERS ARE CANCELLED AFTER 60 DAYS. IF STILL NEEDED, THEY MUST BE REORDERED.



850 Fiero Lane
San Luis Obispo, CA 93401 U.S.A.

North America: (800) 444-5247 (JAGS)
International: (805) 544-7864
Worldwide Fax: (805) 544-1664
E-mail: customerservice@xks.com
Jaguar: www.xks.com
Land Rover: www.goldcoastrovers.com
Gauges: www.stewartwarner.net



* INVOICE *

Page 1

Inv # 01 551123
P/O # MIKE

Ord# 30742

Br Acct
00 64213

M2

4/11/2011

16:23:31

Part Number	Order	Ship	B/O	Description	Unit	Net	TE	Value
03 H8KIT	2	2		CARBURETOR KIT	158.69	145.00		290.00
08 0415	6	6		PLUG END, C5479	9.95	9.00		54.00
***** Assembly contains the following parts:								
6.00	08 0416			LABEL, PLUG END				
***** Assembly contains the following parts:								
6.00	08 0416			LABEL, PLUG END				
***** Assembly contains the following parts:								
6.00	08 0416			LABEL, PLUG END				
1957 XK140 DHC	AND 52 XK120							
**20% RESTOCK CHARGE ON ALL RETURNS **								
NO RETURNS AFTER 30 DAYS NO EXCEPTIONS!								
***WE ARE NOW ON FACEBOOK- JOIN OUR								
GROUP. GO TO WWW.XKS.COM TO SIGN UP***								

CUSTOMER COPY

Tax Rate 8.25

8	344.00	13.90			28.38
TOTAL UNITS	PART TOTAL	CORE TOTAL	SHIPPING & HANDLING	MISCELLANEOUS	LABOR TAX

NOTES: 1. The seller warrants against the parts and labor which may be offered by the manufacturer. The selling dealer hereby disclaims any warranty, express or implied, including any implied warranties of merchantability or fitness for a particular purpose. 2. The seller does not warrant or assume any liability in connection with the sale of this product and/or service. 3. The seller is not responsible for any consequential damages, damages to property, damages for loss of profits, or any other incidental damages.

RCVD
BY:

PAY THIS
AMOUNT

386.28

\$

MUST HAVE COPY OF INVOICE TO MAKE A RETURN. BACK-ORDERS ARE CANCELLED AFTER 60 DAYS, IF STILL NEEDED, THEY MUST BE REORDERED.



850 Fiero Lane
San Luis Obispo, CA 93401 U.S.A.

North America: (800) 444-5247 (JAGS)
International: (805) 544-7864
Worldwide Fax: (805) 544-1664
E-mail: customerservice@xks.com
Jaguar: www.xks.com
Land Rover: www.goldcoastrovers.com
Gauges: www.stewartwarner.net



* I N V O I C E *

Page 1

Inv # 01 553183
P/O # DARYL EXT242

Ord# 34113

Br Acct
00 64213

DB

5/06/2011

16:27:20

Part Number	Order	Ship	B/O	Description	Unit	Net	TE	Value
CO 2415	1	1		COVER PLATE	195.41	152.93		152.93
JA FG.104/X	7	7		1/4" LOCK WASH.	.10	.08		.56

1957 XK140 DHC AND 52 XK120

NOTE: SCREWS JAG P/N CS125/3D > STANDARD 1/4" PER JAG FACTORY MANUAL

**20% RESTOCK CHARGE ON ALL RETURNS **

NO RETURNS AFTER 30 DAYS NO EXCEPTIONS!

***WE ARE NOW ON FACEBOOK- JOIN OUR

GROUP. GO TO WWW.XKS.COM TO SIGN UP***

CUSTOMER COPY

Tax Rate 8.25

8	153.49		13.54			12.66
TOTAL UNITS	PART TOTAL	CORE TOTAL	SHIPPING & HANDLING	MISCELLANEOUS	LABOR	TAX

DISCLAIMER: The only warranty applying to the product is that which may be offered by the manufacturer. The selling dealer hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor warrants any other person is entitled to a refund, including reimbursement with the sale of replacement and/or repair. Buyer shall not be entitled to receive from the selling dealer any money, credit, damages, damages to property, damages for loss of use, time, loss of profits, or interest, or any other incidental damages.

RCVD.
BY:

PAY THIS
AMOUNT

179.69

\$

MUST HAVE COPY OF INVOICE TO MAKE A RETURN. BACK-ORDERS ARE CANCELLED AFTER 60 DAYS. IF STILL NEEDED, THEY MUST BE REORDERED.

Pioneer Auto Service
 1955 San Ramon Valley Blvd
 San Ramon, CA. 94583
 Phone - 925-837-1000 Fax - 925-837-2513

INVOICE

17663

ARD# ARD234142
 EPA# CAL000284528

INVOICE

Work Completed Date : 05/06/2011

Print Date : 05/10/2011

1952 Jaguar - XK120

I6

Lic # : 81150

Odometer In : 97960

Unit # :

Vin # : 671685

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
Steel EXP Plug 550-025	1.00	0.99	0.99	Repaired & re finished left & right rear 1/4 panels	5.00	1,000.00
Spark plug 415	6.00	3.78	22.68	Replaced spark plugs & spark plug wires	1.00	100.00
Spark plug wire set 198903	1.00	57.95	57.95	Replaced distributor with electronic unit.	4.00	400.00
Wire & Cable BP56	1.00	1.75	1.75	Also changed car from a positive ground to a negative ground.		
Battery Cable A10-4	1.00	15.58	15.58	Replaced rear freeze plug	1.00	100.00
Relay HR-125	1.00	37.70	37.70	Replaced battery cables	0.50	50.00
Premium gas Gas	1.00	25.03	25.03	Straighten clutch pedal	0.50	50.00
				Replaced ignition coil	1.00	100.00
				Replaced temperature gauge & oil pressure gauge	3.50	350.00
				Replaced engine valve cover gaskets	2.00	200.00
				Re route wires under dash	2.00	200.00
				Cleaned under car - fenders & engine area	2.00	200.00
				Removed & re sealed both carburetors & adjusted fuel mixture & choke	4.00	400.00
				Switch wires on the amp meter for correct charging of batteries	2.00	200.00
				Replaced horn relay	3.00	300.00
				Installed transmission cover	N/A	N/C
				Hazardous Materials		5.00

Pioneer Auto Service
1955 San Ramon Valley Blvd
San Ramon, CA. 94583
Phone - 925-837-1000 Fax - 925-837-2513

INVOICE

17663

ARD# ARD234142
EPA# CAL000284528

INVOICE

Work Completed Date : 05/06/2011

Print Date : 05/10/2011

1952 Jaguar - XK120

I6

Lic # : 81150

Odometer In : 97960

Unit # :

Vin # : 671685

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
---------------------------	-----	------	----------	-------------------	-------	----------

[Technicians : Fuenzalida, Bob; Please Select, Technician]

Org. Estimate	Revisions	Current Estimate	Additional Cost	Revised Estimate
---------------	-----------	------------------	-----------------	------------------

Labor:	3,655.00
Parts:	161.68
Sublet:	0.00

Sub:	3,816.68
Tax:	14.96
Total:	3,831.64
Bal Due:	\$3,831.64

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty valid only if vehicle is returned at customer's expense to Pioneer Auto Service & cannot exceed the original cost of repair. All replaced parts are new unless other wise specified.

SIGNATURE..... Date..... Time.....

Armand's

27979

AUTO UPHOLSTERY INC.

CARRYING ON A FAMILY TRADITION SINCE 1897

2660 N. MAIN • WALNUT CREEK, CALIF. 94597

Phone (925) 934-4373 • FAX (925) 934-3233

NAME

ADDRESS

CITY

STATE

MAKE

MILEAGE

LICENSE NO.

VIN NO.

1% PER MONTH SERVICE CHARGE ADDED TO PAST DUE ACCOUNTS

CASH ☒	CHARGE ☐	CUSTOMER ORDER NO.	ESTIMATE DATE 5-16-11	
WORK PH NO.	HOME PH NO. 984 3632	WORK DATE 5/20/11		
DESCRIPTION			MATERIALS	LABOR

Repair Seat cushion

PAID
VISA

	SUPPLIES	
	FABRICATION LABOR	
	TOTAL MATERIALS	
	SALES TAX	
	INSTALLATION LABOR	120 0
AUTHORIZED & ACCEPTED BY OWNER OR AGENT	TOTAL	120 0

X

GUARANTEE: ONE YEAR PARTS AND LABOR

Pioneer Auto Service
 1955 San Ramon Valley Blvd
 San Ramon, CA. 94583
 Phone - 925-837-1000 Fax - 925-837-2513


INVOICE

18393

ARD# ARD234142
 EPA# CAL000284528

Print Date : 07/28/2011

INVOICE



1952 Jaguar - XK120

I6

Lic # : 81150

Odometer In : 98869

Unit # :

Vin # : **671685**

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
Brass Stud Nut 680-003	2.00	1.88	3.76	Cooling System Inspection for Leaks	1.00	100.00
V-Belt 090002	1.00	43.82	43.82	Pressure check complete coolant system & inspect for leaks, check drive belts & hoses		
				Found the water pump belt coming apart - Replaced belt & re filled cooling system - Test drove		
				Replaced customer provided exhaust headers	2.00	200.00
				Tighten horn button	1.00	100.00
				Hazardous Materials		5.00

[Technicians : Fuenzalida, Bob; Please Select, Technician]

Org. Estimate \$0.00 Revisions \$0.00 Current Estimate \$ 0.00 Additional Cost Revised Estimate

Labor:	405.00
Parts:	47.58
Sublet:	0.00
Sub:	452.58
Tax:	3.93
Total:	456.51
Bal Due:	\$456.51

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty valid only if vehicle is returned at customer's expense to Pioneer Auto Service & cannot exceed the original cost of repair. All replaced parts are new unless other wise specified.

SIGNATURE..... Date..... Time.....



850 Fiero Lane
San Luis Obispo, CA 93401 U.S.A.

North America: (800) 444-5247 (JAGS)
International: (805) 544-7864
Worldwide Fax: (805) 544-1664
E-mail: customerservice@xks.com
Jaguar: www.xks.com
Land Rover: www.goldcoastrovers.com
Gauges: www.stewartwarner.net
Wheels: www.wirewheelsource.com



* I N V O I C E *

Page 1

Inv # 01 564419
P/O #

Ord# 57348

Br Acct
00 64213

AP

10/05/2011

13:47:33

Part Number	Order	Ship	B/O	Description	Unit	Net	TE	Value
CO 2318	2	2		Manifold Gasket	7.95	7.15		14.30
LU 69151/2	1	1		Windtone Horns	98.57	90.58		90.58
1957 XK140 DHC AND 52 XK120								

**20% RESTOCK CHARGE ON ALL RETURNS **
NO RETURNS AFTER 30 DAYS NO EXCEPTIONS!
***WE ARE NOW ON FACEBOOK- JOIN OUR
GROUP. GO TO WWW.XKS.COM TO SIGN UP***

CUSTOMER COPY

Tax Rate 7.25

3	104.88		14.44				7.60
TOTAL UNITS	PART TOTAL	CORE TOTAL	SHIPPING & HANDLING	MISCELLANEOUS	LABOR		TAX

DISCLAIMER: This invoice is a sales document and does not constitute an offer. The selling dealer hereby disclaims all liability, either express or implied, for any injury or damage of any kind resulting from the use of any product or service provided by or for the selling dealer. The selling dealer is not responsible for any damage to property, damage to property, or any other loss or damage resulting from the use of any product or service provided by or for the selling dealer.

RCVD
BY:

PAY THIS
AMOUNT

\$ 126.92

MUST HAVE COPY OF INVOICE TO MAKE A RETURN. BACK-ORDERS ARE CANCELLED AFTER 60 DAYS. IF STILL NEEDED, THEY MUST BE REORDERED.

Spencer Trenery

From: [REDACTED]
Sent: Monday, December 12, 2011 8:11 AM
To: Fantasy Junction Sales; spencer
Subject: Re: 1952 XK120 - List of Items Done to Car

Bruce and Spence

Here is a list that may be useful regarding this car.

Engine and Trans - other Mechanicals

- Rebuilt claim by Bill Tracy - I believe it as he was adamant that I "run - in" the engine carefully. I have several emails describing which I will forward.
- Cylinder head is a "Type C" spec with high lift cams and hardened (stellite) valve seats for unleaded fuel.
- Electronic Ignition
- Gear reduction starter
- Stainless steel large diameter exhaust
- Large Sand Cast Carbs - rare and a great feature
- Aluminum flywheel for faster revs
- Trans rebuilt twice - once by Walt Osborne and second time by Groom in Berkeley - looking for his receipt - but OK to call him. In fact he had to redo it as the shifter went too far in third gear and stuck.
- Extra heavy torsion bars

Body and Cosmetics

- Very straight doors, gaps, finish
- (72) louvered hood
- Tri Bar headlights
- P 700 driving lights
- All new bumpers and mounting chrome/hardware - very proper
- Leather gaiters
- Dunlop Alloy Race wheels - alloy rims with SS spokes/hubs set of 5
- Complete and correct tool kit
- Tire air pump, jack, grease gun fitted properly to car
- New leather upholstery

I drove and loved this car for a total of perhaps 7 tanks of fuel. At 160 miles avg per tank that's just over 1000 miles. I suppose I spent most of my time sorting out this car and hope the next owner will appreciate all that I have done.

Best,

AUTO REPAIR ORDER

NAME	
ADDR	
CITY	

[illegible]

I HEREBY AUTHORIZE THE ABOVE PERMIT WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND EQUIPMENT TO BE LOANED TO YOU BY THE PERMITTING AGENCY TO OPERATE THE CAR TRUCK OR VEHICLE HEREIN DESCRIBED ON PUBLIC HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING A VEHICLE TO DETERMINE BUSINESS MECHANICS' LEX IS HEREBY ACKNOWLEDGED ON ABOVE CAR, TRUCK OR VEHICLE TO BECOME THE PROPERTY OF THE PERMITTING AGENCY.

YOU ARE ENTITLED TO A FREE ESTIMATE FOR THE REPAIRS YOU HAVE AUTHORIZED. THE FINAL PRICE MAY BE LESS THAN THE ESTIMATE, BUT WILL NOT EXCEED THE ESTIMATE WITHOUT YOUR PERMISSION. YOUR SIGNATURE WILL INDICATE YOUR ESTIMATE SELECTION.

RENTAL ESTIMATE: I UNDERSTAND THAT MY CAR WILL BE REASSEMBLED WITHIN _____ DAYS
OF THE DATE SACKNIF CHOOSING NOT TO AUTHORIZE THE SERVICE RECOMMENDED.

3. I request an estimate of a living before you begin repairs.

2. Please proceed with repairs, but call me before demolishing if the patio will be used.

13. *For the next two questions, assume that the following information is true:*

AUTO REPAIR ORDER

Vintage Auto Service
4721 Tidewater Ave Suite A
Oakland, CA 94601
510 534 5404

AUTO REPAIR ORDER

NAME	[REDACTED]
ADDRESS	[REDACTED]
CITY, STATE	[REDACTED]

QUAN.	PART NO.	NAME OF PART	PRICE	CUSTOMER'S INFORMATION			
1	N	performance cam	600.00	DATE	CUSTOMER'S ORDER NO.	WHEN PROMISED	PHONE
1	N	flywheel inset	99.90	YEAR • MAKE • MODEL	SERIAL NO. 671685		
1	N	clutch cover	288.00	'92 Jag XK120 OTS		MOTOR NO. W 3783-8	
1	N	pilot bushing	7.99	LICENSE NO.	ODOMETER	WRITTEN BY	
1	N	cam bearing	86.95	☐ LUBE ☐ OIL CHANGE ☐ FLUSH TRANS. ☐ FLUSH DIFF. ☐ WASH ☐ POLISH			
1	N	tappet	87.48				
2	N	carb kits	52.80				
1	N	Battery odyssey	299.00	Instal 5-speed Trans. lower chain tension			
1	N	kick pedal kit	139.00	spring, new cam shafts, tappets and cam			
9	N	valve shims	44.91	bearings. Remove and instal new clutch			
1	N	Oil Filter	13.50	with flywheel for balancing and timing.			
1	N	STS 5 speed kit	4586.00	mark correction. Rebuild oil pump and			
1	N	starter solenoid	29.95	carbs. replace pilot bushing and flywheel			
4	N	breather gaskets	16.40	face			
2	N	cam cover gaskets	26.85	Machine Carb float bowls			
1	N	pan gasket	19.99	balance clutch + flywheel heli coat flywheel			
1	N	crank seal track	58.50	weld hole in carb TDS			
2	N	front brake screen	74.90				
TOTAL PARTS 6550.42				GAS, OIL & GREASE		ACCESSORIES	
				GALS. GAS	17 -	Coolant	17 -
				QTS. OIL	96.80	Waterwetter	16.50
				LBS. GREASE	10 -	Trans oil	21 -
				TOTAL GAS OIL & GREASE		Diff oil	13 -
MECHANICS RECOMMENDATIONS				RETAIN PARTS		TOTAL ACCESSORIES	
1-20-12 2,000 Deposit				DESTROY PARTS			
4-3-12 6,000 "				AUTHORIZED BY		LABOR ONLY 0120	
4-28-12 7,000 "						PARTS 0250.42	
						ACCESSORIES	
						GAS, OIL & GREASE 191.30	
						MISC. MERCHANDISE	
						SUBLET REPAIRS 465.00	
						Freight 345.00	
						TAX 588.15	
ESTIMATE AMOUNT • PARTS & LABOR						TOTAL 14,251.87	

I HEREBY AUTHORIZE THE ABOVE WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE CAR, TRUCK OR VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR OTHERWISE FOR THE PURPOSE OF TESTING AND/OR REPAIR. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON ABOVE CAR, TRUCK OR VEHICLE TO SECURE THE AMOUNT OF REPAIR THEREON.

YOU ARE ENTITLED TO A PRICE ESTIMATE FOR THE REPAIRS YOU HAVE AUTHORIZED. THE REPAIR WORK MAY BE LESS THAN THE ESTIMATE, BUT WILL NOT EXCEED THE ESTIMATE WITHOUT YOUR PERMISSION. YOUR SIGNATURE WILL INDICATE YOUR ESTIMATE SELECTION.

TEAR DOWN ESTIMATE. I UNDERSTAND THAT MY CAR WILL BE DISASSEMBLED WITHIN _____ DAYS OF THE DATE SHOWN IF I DO NOT SIGN NOT TO AUTHORIZE THE SERVICE RECOMMENDED.

- I request an estimate in writing before any work is done.
- Please proceed with repair, but call me before continuing if the price will exceed \$_____.
- I do not want an estimate.

Vintage Auto Service
4721 A Tidewater Ave
Oakland, CA 94601
511-534-5464

AUTO REPAIR ORDER

N	
A	
C	

QUAN.	PART NO.	NAME OF PART	PRICE	CUSTOMER'S INFORMATION			
2	N	carb needle	46.-	DATE	CUSTOMER'S ORDER NO.	WHEN PROMISED	PHONE
2	N	carb float	226.-	YEAR • MAKE • MODEL	SERIAL NO.		
8	N	Fiber washer	8.80	52 Jig XL 120 OTS	MOTOR NO.		
2	N	48 grose Jet	154.60	LICENSE NO.	ODOMETER	WRITTEN BY	
2	N	pedal boot	23.80				
1	N	clank seal	8.99	☐ LUBE ☐ OIL CHANGE ☐ FLUSH TRANS. ☐ FLUSH DIFF. ☐ WASH ☐ POLISH			
1	N	cork seal	11.89	Instal short pedal set, Tonneau, pan gasket seals and race.			
1	N	Timing gaskets	6.90	Flush and pressure test cooling system.			
1	N	Chain spring	14.99	Change diff. and dressing in fluid.			
6	N	Spark-plugs	23.10	Lube chassis and tighten bolts.			
				Repair reverse and license plate lights			
				Modify horn button and repair horn relay. Instal new starter solenoid.			
				Electrical diagnostic.			
				GAS, OIL & GREASE		ACCESSORIES	
				LABOR ONLY		PARTS	
				ACCESSORIES		GAS, OIL, & GREASE	
				MISC. MERCHANDISE		SUBLET REPAIRS	
				Freight		TAX	
				TOTAL ACCESSORIES		TOTAL	
TOTAL PARTS			525.07				
MECHANICS RECOMMENDATIONS							
ESTIMATE AMOUNT • PARTS & LABOR							

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE CAR, TRUCK OR VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANICS LIEN IS HEREBY ACKNOWLEDGED ON ABOVE CAR, TRUCK OR VEHICLE TO SECURE THE AMOUNT OF REPAIRS THEREON.

YOU ARE ENTITLED TO A PRICE ESTIMATE FOR THE REPAIRS YOU HAVE AUTHORIZED. THE REPAIR PRICE MAY BE LESS THAN THE ESTIMATE, BUT WILL NOT EXCEED THE ESTIMATE WITHOUT YOUR PERMISSION. YOUR SIGNATURE WILL INDICATE YOUR ESTIMATE SELECTION.

TEARDOWN ESTIMATE: I UNDERSTAND THAT MY CAR WILL BE REASSEMBLED WITHIN _____ DAYS OF THE DATE SHOWN IF I CHOOSE NOT TO AUTHORIZE THE SERVICES RECOMMENDED.

1. I request an estimate in writing before you begin repairs.

2. Please proceed with repairs, but call me twice confirming if the price will exceed \$_____.

3. I do not want an estimate.

AUTO REPAIR ORDER

Vintage Auto Service

4721 Tidewater Ave. • Oakland, CA 94601
Phone 510•534•5464 • Fax 510•534•5424
vintageautoservice@gmail.com

000241

QUAN.	PART NO.	DESCRIPTION	SALE AMOUNT
24	N	Valve keeper	71 76
12	N	Tappet	118 20
1	N	Set cam bearing	86 90
1	N	Tappet hold down kit	74 99
12	N	Valve stem	71 88
14	N	Head studs	179 91
1	N	Cometic head gasket 40	205 -
1	N	Engine gasket set	147 -
1	N	Chain kit	108 -
1	N	Timing pointer	10 50
1	N	Spin-on oil filter kit	289 90
1	N	Water pump	476 -
1	N	Chrome head set	108 -
2	N	Engine mount	86 -
36	N	Copper washers	412 84
1	N	SP wire loom	39 95
21	N	FT. plug wire	27 30
6	N	Spark plug ends	65 18
6	N	Spark plugs	23 22
1	N	Spark coil	48 99
1	N	Choke cable	27 85
1	N	Oil filter	17 95

TOTAL PARTS

2327 32

ESTIMATE AMOUNT

PARTS
LABOR

ADDL AUTH. AMT	TIME	BY	
Deposit 6-14-12			7,000 -
ADDL AUTH. AMT			4,000 -
12-20-12			
ADDL AUTH. AMT			4,000 -
3-9-13			

ESTIMATE TOTAL

15,000 -

Unless otherwise provided by law, the seller (above named Dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

NAME

ADDRESS

CITY

YEAR

TYPE OR MODEL

MOTOR NO.

SERIAL NUMBER

LICENSE NUMBER

ODOMETER

OPER. NO.

REPAIR ORDER - LABOR INSTRUCTIONS

ORDER
WRITTEN BYLUBRICATE ☐CHANGE OIL ☐FLUSH TRANS ☐FLUSH OIL ☐WASH ☐POLISH ☐

\$

Engine Machine work: Oil, base + 20, deck .006 and align hone block. Mag crank and grind 10, 10. Modify rear of crank for updated seal. Recondition rods, balance crank parts, rods and pistons. Assemble pistons, rods and crank in block.

2880 - 5

Head: Glass head, pressure test, surface .015, install new valve seats, valves, springs, seals guides and hold-downs.

9195 - 5

Hasselgren engineering dyno time; break-in and tuning

1685 - 5

RETAIN PARTS ☐DESTROY PARTS ☐

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE, ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THEREIN. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

AUTHORIZED BY

RECEIVED BY

99 GAL GASOLINE

978 91

99 QTS OIL

98 91

99 LBS GREASE

22 -

TOTAL GAS - OIL - GREASE

TOTAL LABOR

TOTAL PARTS

GAS, OIL, GREASE

SPECIAL REPAIRS

ENVIRONMENTAL CHARGES

STATE TAX

TOTAL AMOUNT

2327 32

219 82

3875 - 5

70 -

224 24

6721 38

DATE

TERMS

CUSTOMER'S ORDER NO

NO

4/19/13

00054m

2880 - 5

9195 - 5

1685 - 5

2327 32

219 82

3875 - 5

70 -

224 24

6721 38

2327 32

219 82

3875 - 5

70 -

224 24

6721 38

2327 32

219 82

3875 - 5

70 -

224 24

6721 38

2327 32

219 82

3875 - 5

70 -

224 24

6721 38

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

Vintage Auto Service

4721 Tidewater Ave. • Oakland, CA 94601

Phone 510•534•5464 • Fax 510•534•5424

vintageautoservice@gmail.com

000250

QUAN.	PART NO.	DESCRIPTION	SALE AMOUNT	
1	Core	3.8 Jag Engine	900	—
1	U	E Type Oil Pan	300	—
2	U	Jet Hot Exh Mani	200	—
6	N	CP Pistons	2047	60
1	N	ARP Rod Bolts	126	—
1	N	Set main bearings	156	90
1	N	Set Rod bearings	69	79
1	N	Crank sprocket	79	99
1	N	Crank lock tab	7	88
1	N	Crank distance spacer	58	90
1	N	Pair thrust washer	21	—
1	N	Pilot ~~ball~~ bushing	7	99
3	N	Oil lock tabs	14	70
1	N	Flywheel lock Plate	10	90
1	N	Oil pump drive	98	90
1	N	Oil pump OE	299	—
1	N	Rear seal cover	359	99
1	N	Set valve spring	56	95
6	N	SS intake valve (120)	66	—
6	N	SS Exh valve (155)	149	60
12	N	valve set	148	85
6	N	valve seal	~~148~~ 29.10	—

TOTAL PARTS

5410 04

ESTIMATE AMOUNT

PARTS
LABOR

ADDL. AUTH. AMT.

TIME


BY

ADDL. AUTH. AMT.

ADDL. AUTH. AMT.

ESTIMATE TOTAL

Unless otherwise provided by law, the seller (above named dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.



YEAR	TYPE OR MODEL	MODIFIED	SERIAL NUMBER	LICENSE NUMBER	ODOMETER
52	XK120	LA 7100-9 B1251	6711685	6TYH846	00054 mi

OPER. NO.	REPAIR ORDER — LABOR INSTRUCTIONS	ORDER WATCH BY
-----------	-----------------------------------	-------------------

FLUSH TRANS. ☐ FLUSH DIFF. ☐ WASH ☐ POLISH ☐ \$

Remove engine, assemble new engine, detail engine and part ment, install new engine.

Remove brake drums and inspect brakes, replace brake reservoir hose, reseal bottom of reservoir.

Alignment

RETAIN PARTS ☐ DESTROY PARTS ☐

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE, ALONG WITH NECESSARY MATERIALS YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THEREON. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

AUTHORIZED BY

RECEIVED BY

GAL GASOLINE

QTS OIL

LBS GREASE

TOTAL GAS - OIL - GREASE

TOTAL LABOR

TOTAL PARTS

GAS, OIL, GREASE

SPECIAL REPAIRS

ENVIRONMENTAL CHARGES

STATE TAX

TOTAL AMOUNT

120 —

70 — 5

4800 —

5410 04

3350

35 —

489 92

10768 46

DATE 4/19/13

TERMS

CUSTOMER'S ORDER NO.

ODOMETER

00054 mi

ORDER WATCH BY

\$

hasselgren engineering
1221 4th st.
Berkeley Ca.94710
510 524 2485

Date : 03-01-2013 Time : 17:27:29
INF=.5 Mode : A-Sweep

T17:33 D03-01 :2 FLAT S:32cam:wad- wad 9.5 /1
C [REDACTED] JAG Xk120 fl:92 SU:2.750" needle:richest
EX:std 3/1 headers SINGLE PIPE 1.875/1.625 valve
w/o flters maxamal race fuel

FileName : JAG04.D04

Speed	C TQ	CPower	OILpsi	ecm	ATMO	OilTankfuel	p
RPM	lbft	C HP	PSI			°F	
*3000	247.2	141.2	57.9	.84	14.8	68	2.8 78
*3100	246.5	145.5	58.3	.82	14.78	68	2.9 78
*3200	244.9	149.2	58.8	.81	14.79	68	2.9 78
*3300	244	153.3	59.3	.8	14.76	68	2.9 78
*3400	243	157.3	59.5	.8	14.79	68	2.8 78
*3500	241.7	161	59.8	.8	14.8	68	2.8 78
*3600	241.1	165.2	60	.82	14.8	68	2.8 78
*3700	241.6	170.2	60.1	.81	14.8	68	2.8 78
*3800	242.7	175.6	59.9	.79	14.8	68	2.8 78
*3900	242.6	180.1	59.8	.79	14.8	68	2.8 78
*4000	242.7	184.8	59.6	.82	14.8	68	2.8 78
*4100	243.2	189.9	59.6	.83	14.8	68	2.8 78
*4200	243.6	194.8	59.6	.85	14.79	68	2.8 78
*4300	242	198.1	59.7	.85	14.8	68	2.8 78
*4400	240.3	201.3	59.8	.86	14.8	68	2.8 78
*4500	237.8	203.8	59.8	.87	14.8	68	2.8 78
*4600	236.4	207.1	59.8	.86	14.8	68	2.8 78
*4700	235.2	210.5	59.5	.88	14.8	68	2.8 78
*4800	232.3	212.3	59.5	.89	14.8	68	2.8 78
*4900	229.8	214.4	59.2	.9	14.78	68	2.8 78
*5000	225.5	214.7	59	.92	14.8	68	2.8 78

Average data in * band

4000	240.23	182.43	59.45	.84	14.79	68	2.81 78
------	--------	--------	-------	-----	-------	----	---------

000023

[illegible]

NAME		DATE 5/30/13	
ADDRESS		TERMS	
CITY		CUSTOMER'S ORDER NO.	
YEAR	TYPE OR MODEL	MOTOR NO.	SERIAL NUMBER
52	XK120	LA 7180-9 B1261	671685
LICENSE NUMBER		ODOMETER	
		34 mi	

OPER. NO.	REPAIR ORDER — LABOR INSTRUCTIONS					ORDER WARRANTY BY						
LUBRICATE	☐	CHANGE OIL	☐	FLUSH TRANS.	☐	FLUSH DIFF.	☐	WASH	☐	POLISH	☐	\$

- Remove old distributor gear and install ~~new~~ gear on new distributor; install new distributor; tune and adjust 1.5 hrs @ \$120

TOTAL PARTS		289	75
ESTIMATE AMOUNT		PARTS LABOR	
ADD'L AUTH AMT	TIME	EV	
ADD'L AUTH AMT			
ADD'L AUTH AMT			
ESTIMATE TOTAL			

Unless otherwise provided by law, the seller (above named dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE, ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEE'S MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT YOUR RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERE TO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.					TOTAL LABOR	180 -
AUTHORIZED BY _____ RECEIVED BY _____					TOTAL PARTS	28975
GAL. GASOLINE @					GAS, OIL, GREASE	
QTS. OIL @					SPECIAL REPAIRS	
LBS. GREASE @					ENVIRONMENTAL CHARGES	
TOTAL GAS - OIL - GREASE					Freight	15 -
					STATE TAX	26 07
					TOTAL AMOUNT	510 82

Vintage Auto Service

4721 Tidewater Ave. • Oakland, CA 94601
Phone 510•534•5464 • Fax 510•534•5424
vintageautoservice@gmail.com

000100

QUAN.	PART NO.	DESCRIPTION	SALE AMOUNT	
5	N	16" Dayton Wire Wheel	2375	-
5	N	16" Vredestein Tire	1675	-
5	N	Inner Tube	195	-

NAME	[REDACTED]		DATE	10/21/13
ADDRESS	[REDACTED]		TERMS	
CITY	[REDACTED]		CUSTOMER'S ORDER NO.	
YEAR	TYPE OR MODEL	MOTOR NO.	SERIAL NUMBER	ODOMETER
52	XX120		671685	00773

OPER. NO.

REPAIR ORDER — LABOR INSTRUCTIONS

ORDER WRITTEN BY

LUBRICATE ☐ CHANGE OIL ☐ FLUSH TRANS ☐ FLUSH DIFF. ☐ WASH ☐ POLISH ☐ \$

SPECIAL REPAIRS

maint and balance five wheels

150 - S

RETAIN PARTS ☐ DESTROY PARTS ☐

TOTAL PARTS

4245 -

ESTIMATE AMOUNT

PARTS LABOR

ADDITIONAL AUTH. AMT.

TIME

BY

ADDITIONAL AUTH. AMT.

ADDITIONAL AUTH. AMT.

ESTIMATE TOTAL

Unless otherwise provided by law, the seller (above named dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE, ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

AUTHORIZED BY

RECEIVED BY

GAL. GASOLINE @

QTS. OIL @

LBS. GREASE @

TOTAL GAS - OIL - GREASE

TOTAL LABOR

TOTAL PARTS

GAS, OIL, GREASE

SPECIAL REPAIRS

ENVIRONMENTAL CHARGES

Freight

STATE TAX

TOTAL AMOUNT

4245 -

150 - S

170 -

382.05

4947.05

Vintage Auto Service

4721 Tidewater Ave. • Oakland, CA 94601

Phone 510-534-5464 • Fax 510-534-5424

vintageautoservice@gmail.com

000367

QUAN.	PART NO.	DESCRIPTION	SALE AMOUNT
1	N	Oil Filter Wix	17 97
2	N	Rear Wheel Cylinders	~~180.00~~ 181.50
4	N	Copper Washers	3 96
4	N	Brake Adjuster Bar	263 80
2	N	E-brake clip	44 32

NAME

ADDRESS

CITY

YEAR

TYPE OR MODEL

MOTOR NO.

SERIAL NUMBER

LICENSE NUMBER

ODOMETER

OPER. NO.

REPAIR ORDER — LABOR INSTRUCTIONS

ORDER WRITTEN BY

LUBRICATE ☐CHANGE OIL ☐FLUSH TRANS. ☐FLUSH DIFF. ☐WASH ☐POLISH ☐

\$

• Brakes: Removed four drums & turn. Remove all brake shoes and shims for re-lining; removed and install new rear wheel cylinders; repaired rear adjusters; Re-install new brake shoes w/ new front adjusters; Adjust ~~front~~ brakes; bleed system; Test drive.

• Install missing emergency brake spring clip.

• Adjust emergency brake handle.

• Change oil.

9 hrs @ \$130

1080 -

SPECIAL REPAIRS

• Re-line shoes on R4S

• Turn drums

360 -

60 -

RETAIN PARTS ☐DESTROY PARTS ☐

TOTAL PARTS

517 55

ESTIMATE AMOUNT

PARTS LABOR

ADD'L AUTH. AMT.

TIME

BY

ADD'L AUTH. AMT.

ADD'L AUTH. AMT.

ESTIMATE TOTAL

Unless otherwise provided by law, the seller (above named dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE, ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

AUTHORIZED BY

RECEIVED BY

GAL GASOLINE @

9 QTS OIL Joe Gibbs 10-40

LBS GREASE @

TOTAL GAS - OIL - GREASE

TOTAL LABOR

TOTAL PARTS

GAS, OIL, GREASE

SPECIAL REPAIRS

ENVIRONMENTAL CHARGES

Freight

STATE TAX

TOTAL AMOUNT

10

517

116 91

420 -

5 -

95 -

57 10

7291 56

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE
 * CODE = N-NEW U-USED R-REBUILT O-OEM A-AFTERMARKET C-CUSTOMER SUPPLIED

SELECT ELECTRICS
 821 Gilman St. • Berkeley, CA 94710
 Phone (510) 528-7005
 BAR No. ARD 240575



003503

REPAIR INVOICE

LABOR CHARGE PER HR 132.00

NAME [REDACTED] DATE 11-20-14
 ADDRESS [REDACTED]
 CITY [REDACTED] STATE [REDACTED] ZIP [REDACTED]
 PHONE [REDACTED] REC'D TIME PROM.
 PH. WHEN READY WRITTEN BY MILEAGE LIC. PLATE #
☐ YES ☐ NO
 YR / MAKE / MODEL 120
 V.I.N. [REDACTED]
 CUST. PO#

☐ MAINTENANCE INSPECTION
☐ LUBRICATION
☐ CHANGE OIL GRADE
☐ CHANGE OIL FILTER CART
☐ TRANS.
☐ DIFF.
☐ ROTATE TIRES
☐ ALIGN FRONT END
☐
☐

OPR. # REPAIR ORDER • DESCRIPTION OF LABOR

Diagnosed charge LT problem
 needed new Voltage regulator
 installed one provided adjusted
 voltage regulator for 14.25 v @ 1700

4 Hr

REPLACED PARTS REQUESTED BY CUSTOMER? ☐ YES ☐ NO TOTAL PARTS

OUTSIDE-SUBLET REPAIRS

INITIAL TO AUTHORIZE SUBLET REPAIRS:

TOTAL SUBLET REPAIRS

☐ TIRE PRESSURE INSPECTION PERFORMED: LF RF LR RR (psl)

☐ TIRE PRESSURE INSPECTION DECLINED, REASON:

INITIALS:

☐ GALS. GAS @ = TOTAL GAS, OIL & GREASE
☐ QTS. OIL @ =
☐ LBS. GREASE @ =

FOLLOWING REPAIRS RECOMMENDED

1. 3.
 2. 4.

WARRANTY: FROM DATE OF DELIVERY FOR A PERIOD OF 4,000 MILES OR 90 DAYS, WHICHEVER COMES FIRST, THIS FIRM WILL REPAIR FREE OF CHARGE ANY DEFECTS IN MATERIAL AND WORKMANSHIP TO THE REPAIRS STATED ON THIS INVOICE. ALL WORK TO BE DONE IN THIS SHOP ONLY. THIS DOES NOT INCLUDE TOWING OR CUSTOMER SUPPLIED PARTS

STORAGE FEE: \$ PER DAY WILL BE CHARGED 24 HOURS AFTER NOTIFICATION OF WORK COMPLETED

PAYMENT: ☐ CASH ☐ CHECK ☐ CHARGE ☐ DEBIT CARD ☐ CREDIT CARD

ORIGINAL ESTIMATE \$ 400.00 DATE TIME PHONE# • FAX# • EMAIL ☐ BY PHONE ☐ EMAIL ☐ IN PERSON ☐ FAX

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERE TO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT, DYNAMOMETER TESTING OR ANY OTHER CAUSE BEYOND YOUR CONTROL. IN THE EVENT LEGAL ACTION IS NECESSARY TO ENFORCE THIS CONTRACT, I UNDERSTAND THAT I AM SOLELY RESPONSIBLE FOR ALL COSTS INCLUDING ATTORNEY'S FEES AND COURT COSTS. I HAVE READ AND UNDERSTAND THE ABOVE AND ACKNOWLEDGE RECEIPT OF AN ESTIMATE. SMOG CHECK CUSTOMERS: BY LAW YOU MAY CHOOSE ANOTHER SMOG CHECK STATION TO PERFORM ANY REPAIRS, INSTALLATIONS, ADJUSTMENTS OR SUBSEQUENT TESTS

REVISED ESTIMATE \$ DATE TIME PHONE# • FAX# • EMAIL ☐ BY PHONE ☐ EMAIL ☐ IN PERSON ☐ FAX

REASON

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. AUTH. BY REC'D BY

REVISED ESTIMATE \$ DATE TIME PHONE# • FAX# • EMAIL ☐ BY PHONE ☐ EMAIL ☐ IN PERSON ☐ FAX

REASON

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE REVISED ESTIMATED PRICE. AUTH. BY REC'D BY

TOTAL LABOR 1000.00

TOTAL PARTS

GAS, OIL, GREASE

HAZARDOUS WASTE DISPOSAL

SUBLET REPAIRS

SMOG CERTIFICATE

SUBTOTAL 400.00

TAX

PLEASE PAY THIS AMOUNT 400.00

INTEREST WILL BE CHARGED AT A RATE OF 1% PER MONTH ON ACCOUNTS OVER 30 DAYS

THANK YOU

TERMS ARE CASH UNLESS PRIOR ARRANGEMENTS ARE MADE
 SEE IMPORTANT INFORMATION ON BACK

Vintage Auto Service

4721A Tidewater Ave. • Oakland, CA 94601

Phone 510-534-5464 • Fax 510-534-5424

vintageautoservice@gmail.com

000564

DATE 7/9/15

QUAN.	PART NO.	DESCRIPTION	SALE AMOUNT
1	N	Oil Filter	23 49
1.5	Gts	Recline 75-90, Dpf	30 51
1	N	Aluminum Radiator	1050 -
1	N	Radiator Cap	9 99
1	N	XK140 Fan	189 -
1	N	Radiator Support Rod	50 -
1	N	Water Neck Gasket	4 99
1	N	Recline Water Wether	14 99
1.5	G	Anti-Breeze	28 49
1	N	License Plate Frame	10 99

NAME	[REDACTED]		TIME RECEIVED	TERMS
ADDRESS	[REDACTED]		AM	PM
CITY	[REDACTED]		TIME PROMISED	CUSTOMER'S ORDER NO.
YEAR	TYPE OR MODEL	MOTOR NO.	SERIAL NUMBER	LICENSE NUMBER
52	XK120 GS		671685	6TYH1846
				ODOMETER
				101,753

OPER. NO.	REPAIR ORDER — LABOR INSTRUCTIONS						ORDER WRITTEN BY
	LUBRICATE ☐	CHANGE OIL ☐	FLUSH TRANS. ☐	FLUSH DIFF. ☐	WASH ☐	POLISH ☐	\$
Please see attached							
6 hrs @ \$130 780 -							
SPECIAL REPAIRS							
Tax from Perfect Reflections to V.A.S 110 -							
RETAIN PARTS ☐ DESTROY PARTS ☐							

TOTAL PARTS		ESTIMATE AMOUNT		PARTS LABOR
ADD'L AUTH. AMT.	TIME	BY		
ADD'L AUTH. AMT.				
ADD'L AUTH. AMT.				
ESTIMATE TOTAL				
Unless otherwise provided by law, the seller (above named dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.				

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE, ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.		TOTAL LABOR		780 -
AUTHORIZED BY _____		TOTAL PARTS		1412 45
RECEIVED BY _____		GAS, OIL, GREASE		116 91
GAL. GASOLINE @		SPECIAL REPAIRS		110 -
9 QTS. OIL Joe Gibbs 10-40	116.91	ENVIRONMENTAL CHARGES oil disposal		4 -
LBS. GREASE @		Freight		55 -
TOTAL GAS - OIL - GREASE		STATE TAX		137 64
		TOTAL AMOUNT		2616 -

Vintage Auto Service

4721A Tidewater Ave. • Oakland, California 94601
Phone 510•534•5464 • Fax 510•534•5424
vintageautoservice@gmail.com

7/8/15


'52 Jaguar XK120 OTS
#671685

- Changed oil and oil filter and differential fluid; Topped off steering box and idler arm; Test drove car – brakes ok
- Found broken vein in grill; Removed and repaired broken vein; Re-install grill
- Drained cooling system; Removed water neck, lower radiator hose, lower radiator plate, and side brackets; Disassembled support rods and removed radiator; Removed and replaced fan blade with XK140 blade; Test fit and removed new radiator to modified radiator brackets for best possible fitment; Replaced one support rod; Re-install new radiator and adjusted fan blade; Re-assembled water neck, lower radiator hose, plate, and side brackets; Bleed cooling system and test drive
- Installed license plate frame and missing screws on trunk handle; lube handle

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

* CODE = N-NEW U-USED R-REBUILT O-OEM A-AFTERMARKET C-CUSTOMER SUPPLIED

SELECT ELECTRICS

821 Gilman St. • Berkeley, CA 94710
Phone (510) 528-7005
BAR No. ARD 240575



003628

REPAIR INVOICE

LABOR CHARGE PER HR. 100

Paid
ck #
5260

NAME	[REDACTED]		DATE	8-11-15
ADDRESS	[REDACTED]		STATE	ZIP
CITY	[REDACTED]		TIME REC'D	TIME PROM.
PHONE	[REDACTED]		LIC. PLATE #	
PH. WHEN READY	WRITTEN BY	MILEAGE	G.V.W.R.	MOTOR #
☐ YES ☐ NO	TS			
YR / MAKE / MODEL	Jeep XJ 120		CUST. PO#	
V.I.N.				
OPR. #	REPAIR ORDER • DESCRIPTION OF LABOR			

Complaint of not charging a charged voltage
Regulator system and V Reg pointer froze
on a disconnected V Reg and swapped
it out. Looks like problem is with Field
Circuit inside generator using too many
Amps.

3 Hr

REPLACED PARTS REQUESTED BY CUSTOMER? ☐ YES ☐ NO TOTAL PARTS

OUTSIDE-SUBLET REPAIRS

INITIAL TO AUTHORIZE SUBLET REPAIRS:

TOTAL SUBLET REPAIRS

☐ TIRE PRESSURE INSPECTION PERFORMED: LF RF LR RR (psi)	
☐ TIRE PRESSURE INSPECTION DECLINED, REASON:	INITIALS:
☐ GALS. GAS @ =	TOTAL GAS, OIL & GREASE
☐ QTS. OIL @ =	
☐ LBS. GREASE @ =	

FOLLOWING REPAIRS RECOMMENDED

1.	3.
2.	4.

WARRANTY: FROM DATE OF DELIVERY FOR A PERIOD OF 4,000 MILES OR 90 DAYS, WHICHEVER COMES FIRST, THIS FIRM WILL REPAIR FREE OF CHARGE ANY DEFECTS IN MATERIAL AND WORKMANSHIP TO THE REPAIRS STATED ON THIS INVOICE. ALL WORK TO BE DONE IN THIS SHOP ONLY. THIS DOES NOT INCLUDE TOWING OR CUSTOMER SUPPLIED PARTS.

STORAGE FEE: \$ PER DAY WILL BE CHARGED 24 HOURS AFTER NOTIFICATION OF WORK COMPLETED

PAYMENT: ☐ CASH ☐ CHECK ☐ CHARGE ☐ DEBIT CARD ☐ CREDIT CARD

ORIGINAL ESTIMATE \$	300.00	DATE	TIME	PHONE# • FAX# • EMAIL	☐ BY PHONE ☐ EMAIL ☐ IN PERSON ☐ FAX	TOTAL LABOR	300.00
I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THEREON. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF THEFT, ACCIDENT, DYNAMOMETER TESTING OR ANY OTHER CAUSE BEYOND YOUR CONTROL. IN THE EVENT LEGAL ACTION IS NECESSARY TO ENFORCE THIS CONTRACT, I UNDERSTAND THAT I AM SOLELY RESPONSIBLE FOR ALL COSTS INCLUDING ATTORNEY'S FEES AND COURT COSTS. I HAVE READ AND UNDERSTAND THE ABOVE AND ACKNOWLEDGE RECEIPT OF AN ESTIMATE. SMOG CHECK CUSTOMERS: BY LAW YOU MAY CHOOSE ANOTHER SMOG CHECK STATION TO PERFORM ANY REPAIRS, INSTALLATIONS, ADJUSTMENTS OR SUBSEQUENT TESTS.							
REASON	DATE	TIME	PHONE# • FAX# • EMAIL	☐ BY PHONE ☐ EMAIL ☐ IN PERSON ☐ FAX	ADD'L COSTS \$	TOTAL PARTS	
I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.							
REASON	DATE	TIME	PHONE# • FAX# • EMAIL	☐ BY PHONE ☐ EMAIL ☐ IN PERSON ☐ FAX	ADD'L COSTS \$	SMOG CERTIFICATE	
I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE REVISED ESTIMATED PRICE.							
REASON	DATE	TIME	PHONE# • FAX# • EMAIL	☐ BY PHONE ☐ EMAIL ☐ IN PERSON ☐ FAX	ADD'L COSTS \$	SUBTOTAL	300.00
PLEASE PAY THIS AMOUNT							
TAX							
300.00							

INTEREST WILL BE CHARGED AT A RATE OF 1 1/2% PER MONTH ON ACCOUNTS OVER 30 DAYS

THANK YOU

TERMS ARE CASH UNLESS PRIOR ARRANGEMENTS ARE MADE
SEE IMPORTANT INFORMATION ON BACK

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

* CODE = N-NEW U-USED R-REBUILT O-OEM A-AFTERMARKET C-CUSTOMER SUPPLIED

SELECT ELECTRICS

821 Gilman St. • Berkeley, CA 94710

Phone (510) 528-7005

BAR No. ARD 240575



003625

REPAIR INVOICE

LABOR CHARGE PER HR. 100.00

QTY	*	PART NO. & DESCRIPTION	AMOUNT
1	N	Drive end bearing	10.00
1	N	Commutator end bearing	9.00
2	N	Commutator Brushes	6.00

NAME		DATE		☐ MAINTENANCE INSPECTION	
ADDRESS		10-13-15		☐ LUBRICATION	
CITY		ZIP		☐ CHANGE OIL GRADE	
PHONE / E-MAIL		TIME REC'D		☐ CHANGE OIL FILTER CART	
☐ H ☐ W		TIME PROM.		☐ TRANS.	
PH. WHEN READY		WRITTEN BY		☐ DIFF.	
☐ YES ☐ NO		TJ		☐ ROTATE TIRES	
YR / MAKE / MODEL		MILEAGE		☐ ALIGN FRONT END	
52 Jaguar XK 120		LIC. PLATE #		☐	
V.I.N.		CUST. PO#		☐	
OPR. #		REPAIR ORDER • DESCRIPTION OF LABOR			

Paid ck #
9928

R&R Generator. 2 Hr
Rebuilt Generator. Disassembled unit washed all parts
- solvent tank thoroughly cleaned all parts. Look Very Good
Revised Field coils and gnd with insulating varnish.
Tested Armature on generator. Soldered commutator Replaced
Bearings and Brushes Reassembled unit. Found a pair
where solder on Field coil was touching Gnd. Filed
away excess solder Tested on bench. 4 Hr
Adjusted voltage Regulator on car. Run 14 V
1 1/2 Hr

6 1/2 Hr Total

REPLACED PARTS REQUESTED BY CUSTOMER? ☐ YES ☐ NO	TOTAL PARTS	25.00
OUTSIDE-SUBLET REPAIRS		

INITIAL TO AUTHORIZE SUBLET REPAIRS:	TOTAL SUBLET REPAIRS
--------------------------------------	----------------------

☐ TIRE PRESSURE INSPECTION PERFORMED: LF RF LR RR (psi)	INITIALS:
☐ TIRE PRESSURE INSPECTION DECLINED, REASON:	
☐ GALS. GAS @ =	TOTAL GAS, OIL & GREASE
☐ QTS. OIL @ =	
☐ LBS. GREASE @ =	

FOLLOWING REPAIRS RECOMMENDED			
1.	2.	3.	4.

WARRANTY: FROM DATE OF DELIVERY FOR A PERIOD OF 4,000 MILES OR 90 DAYS, WHICHEVER COMES FIRST, THIS FIRM WILL REPAIR FREE OF CHARGE ANY DEFECTS IN MATERIAL AND WORKMANSHIP TO THE REPAIRS STATED ON THIS INVOICE. ALL WORK TO BE DONE IN THIS SHOP ONLY. THIS DOES NOT INCLUDE TOWING OR CUSTOMER SUPPLIED PARTS.	
STORAGE FEE: \$ PER DAY WILL BE CHARGED 24 HOURS AFTER NOTIFICATION OF WORK COMPLETED	
PAYMENT: ☐ CASH ☐ CHECK ☐ CHARGE ☐ DEBIT CARD ☐ CREDIT CARD	

ORIGINAL ESTIMATE \$	DATE	TIME	PHONE# • FAX# • EMAIL	☐ BY PHONE ☐ EMAIL ☐ IN PERSON ☐ FAX	TOTAL LABOR	650.00
I HEREBY AUTHORIZE THE ABOVE REPAIRS TO BE DONE ALONG WITH THE NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S USE IS ACKNOWLEDGED ON ABOVE VEHICLE TO GUARANTEE THE AMOUNT OF REPAIRS THEREON. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT, CYCLOCOUNTER TESTING OR ANY OTHER CAUSE BEYOND YOUR CONTROL. IN THE EVENT LEGAL ACTION IS NECESSARY TO ENFORCE THIS CONTRACT, I UNDERSTAND THAT I AM SOLELY RESPONSIBLE FOR ALL COSTS INCLUDING ATTORNEY'S FEES AND COURT COSTS. I HAVE READ AND UNDERSTAND THE ABOVE AND ACKNOWLEDGE RECEIPT OF AN ESTIMATE. SMOG CHECK CUSTOMERS: BY LAW YOU MAY CHECKUP ANOTHER SMOG CHECK STATION TO PERFORM ANY REPAIRS, INSTALLATIONS, ADJUSTMENTS OR SUBSEQUENT TESTS.					TOTAL PARTS	25.00
REVISED ESTIMATE \$	DATE	TIME	PHONE# • FAX# • EMAIL	☐ BY PHONE ☐ EMAIL ☐ IN PERSON ☐ FAX	GAS, OIL, GREASE	
REASON					HAZARDOUS WASTE DISPOSAL	
I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. AUTH. BY REC'D BY					SUBLET REPAIRS	
REVISED ESTIMATE \$	DATE	TIME	PHONE# • FAX# • EMAIL	☐ BY PHONE ☐ EMAIL ☐ IN PERSON ☐ FAX	SMOG CERTIFICATE	
REASON					SUBTOTAL	675.00
I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE REVISED ESTIMATED PRICE. AUTH. BY REC'D BY					TAX	2.25
PLEASE PAY THIS AMOUNT						677.25

INTEREST WILL BE CHARGED AT A RATE OF 15% PER MONTH ON ACCOUNTS OVER 30 DAYS

THANK YOU

TERMS ARE CASH UNLESS PRIOR ARRANGEMENTS ARE MADE
SEE IMPORTANT INFORMATION ON BACK

DATE 4/21/17

[illegible]

NAME			DATE	4/21/17	
ADDRESS			TIME RECEIVED	TERMS	
			A.M.	P.M.	
CITY			TIME PROMISED	CUSTOMER'S ORDER	
			A.M.	P.M.	NO.
YEAR	TYPE OR MODEL	MOTOR NO.	SERIAL NUMBER	LICENSE NUMBER	ODOMETER
52	XK120 QS		6071685		102 471

OPER. NO.	REPAIR ORDER — LABOR INSTRUCTIONS						ORDER WRITTEN BY
	LUBRICATE ☐	CHANGE OIL ☐	FLUSH TRANS. ☐	FLUSH DIFF. ☐	WASH ☐	POLISH ☐	\$
- Coolant leak @ heater core - Drain cooling system; removed heater hoses, valve, and heater core assembly; Dis assemble, clean, and re-seal heater valve - Disassemble heater core and fan; clean and inspect fan - ok; Re-assemble w/ new core and adjust heater fan blade - Re-install heater core assembly, valve, and hoses; fill system and pressurize - ok - Remove tunnel carpet and crush and clean							
2.5 hrs @ \$130							325 —
RETAIN PARTS ☐ DESTROY PARTS ☐							

TOTAL PARTS		369 88	
ESTIMATE AMOUNT		PARTS LABOR	
ADD'L AUTH. AMT.	TIME	BY	
ADD'L AUTH. AMT.			
ADD'L AUTH. AMT.			
ESTIMATE TOTAL			

Unless otherwise provided by law, the seller (above named dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE, ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.					TOTAL LABOR		325	—
					TOTAL PARTS		369	88
					GAS, OIL, GREASE			
					SPECIAL REPAIRS			
					ENVIRONMENTAL CHARGES			
AUTHORIZED BY _____ RECEIVED BY _____					Freight		11	—
GAL. GASOLINE @					STATE TAX		34	21
QTS. OIL @					TOTAL AMOUNT		740	09
LBS. GREASE @								
TOTAL GAS - OIL - GREASE								