BURLINGAME MOTORS, INC.

Since 1979

Independent Mercedes Benz Dept.
1295 Rollins Road
BURLINGAME, CA 94010-2416
(650) 343-8858 Fax (650) 343-9261

Since 1979

EPA #CAL 000398238 BAR # ARD275257

Date 8.10.19 — 020960

Time Received A.M. P.M. — Written By RENE

Promised A.M. P.M. — Cust. Order No.

Phone when ready Yes ☒ No ☒

Cell Phone

Home Phone

Work Phone

Other

Name [redacted]

Address Apt. No.

City

Year-Make-Model 1937 Peugot — License No. — Odometer

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE ☒ DISCARD ☒

Estimate Amount $ — Engine Size — VIN Number

Revised Estimate $ — Date — Time — Description — Authorized By — INITIAL

Revised Estimate $ — Date — Time — Description — Authorized By — INITIAL

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

*CODE N-NEW U-USED R-REBUILT

QTY	*	PART NO. OR DESCRIPTION			SALE
2		CARBURETORS			1920 00
28		ROUNDELLES			336 00
		HEADLIGHTS + DRIVING LIGHTS ETC.			300 00
		USED PARTS FROM GERMANY			360 00
		MISC. SMALL PARTS PANIS			600 00
1		FUEL FLOAT			121 00
		ENGINE PAINT			52 48
2		CHASSIS PLATES	127	20	254 40
2	G	SIMPLE GREEN	24	25	49 50
1	G	RED HOT DEGREASER			35 50
1		SHEET METAL			43 80
2	L	BLACK OXIDE			205 00
6		PRIMER BLACK SPRAY	22	77	136 62
		MISC. FASTENERS			12 00
		TOTAL PARTS ▶			10150 30

TIRE PRESSURE CHECK SERVICE COMPLETED ☒

TIRE PRESSURE: LF _____ RF _____ LR _____ RR _____ (psi)

DECLINED ☒ Initial REASON: PARTS TICKET 6573 886.25

SUBLET REPAIRS

		WHEEL TRUE + TOOL			1000 00
		MOAL			16356 00
		WEST VALLY GAGES			800 00
		SH + HANDLING			300 00
		DUTY			120 00
		TOTAL SUBLET REPAIRS ▶			27976 00

OPER NO.	REPAIR ORDER — LABOR INSTRUCTION	LABOR CHG.
	INSPECT AND FOTO DOCUMENT CAR LOCATE CHASSIS NUMBERS AND VERIFY	
	REMOVE INTERIOR AND WOOD PANELS INSPECT WOOD STRUCTURE AND CHASSIS	
	REMOVE GAGES SWITCHES AND DASH PANEL SEND OUT GAGES FOR REBUILD	
	REMOVE WHEELS AND INSPECT SUSPENSION, STEERING GEAR, DRAIN FLUIDS AND BRAKES AND REMOVE LINKAGE START CLEANING CARRIAGE	
	REMOVE TRANSMISSION AND PARTIAL DRIVE SHAFT, CLEAN AND BEAD BLAST PAINT	
	INSTALL MOCK CARBURETTOR FOR CLEARANCE ISSUES AND CONFIRM HEIGHT	
	REMOVE RADIATOR HOSES, REMOVE ALTERNATOR AND SET	
	MOCKUP GENERATOR PLUS BRACKETS BOOM IN GERMANY	
	REMOVE ENGINE, LIGHTS AND COMPLETE ELECTRICAL WIRING	
	SEND OUT C.I.E RIMS FOR TRUING AND CRACK CHECKING	
	FABRICATE ENGINE BLOCK SIDE COVERS TO OEM SPEC	
	TOW CAR TO MOAL COACH BUILDERS IN OAK.	

WARRANTY ON PARTS & LABOR

- ☒ 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.
- ☒ 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST.
- ☒ 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST.
- ☒ 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST.
- ☒ NOT GUARANTEED - NEED ADDITIONAL SERVICE(S).

WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR PERSONAL DAMAGE. A $25 PER DAY STORAGE FEE WILL BE CHARGED IF VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS

QTY.		SALE
	QTS. OIL	
	QTS. OIL	
	LBS. GREASE	
	TOTAL OIL, GREASE	

RECOMMENDED SERVICE:

1. 7/25/19 CK 5299 $5000
2.
3.
4.
5.

I hereby authorize the repair work above to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Authorized By _____

TOTAL LABOR ▶	3600 00
PARTS	10150 30
SUBLET REPAIRS	27976 00
OIL & GREASE	
GAS	
SALES TAX	964 27
HAZARDOUS WASTE DISPOSAL FEE	15 00
TOTAL AMOUNT ▶	75105 57

COPY

INVOICE

MOAL, Inc.
937 East 12th Street
Oakland, CA 94606
510.834.9066
Fax: 510.272.9288

MOAL
COACHBUILDERS

Account Summary Burlingame Motors					
Date	**Invoice**	**Detail**	**Debit**	**Credit**	**Balance**
10/21/2019	Ck # 4474	Deposit Peugeot 302		$4,000.00	$4,000.00
11/13/2019	1394	Peugeot Roundels	$5,356.00		-$1,356.00
12/30/2019	Ck # 4545	Payment		$1,356.00	$0.00
3/16/2020	Ck # 4631	Deposit Peugeot 302		$5,000.00	$5,000.00
3/23/2020	1408	Disassemble body and strip paint	$10,147.98		-$5,147.98
4/17/2020	Cash	Payment/Deposit		$5,200.00	$52.02
5/11/2020	Ck # 5337	Deposit Peugeot 302		$20,000.00	$20,052.02
6/2/2020	1442	Body Restoration Work, Fenders	$20,251.56		-$199.54
6/15/2020	Ck # 5372	Payment/Deposit		$20,000.00	$19,800.46
6/18/2020	1458	Body Restoration Work, Wood Work	$15,013.88		$4,786.58
6/30/2020	1463	Rear Body Restoration Work	$6,719.18		-$1,932.60
7/9/2020	Ck # 5824	Payment/Deposit		$21,733.06	$19,800.46
7/20/2020	1466	Rear wheel covers, front nose woodwork	$18,237.65		$1,562.81
7/30/2020	Ck # 5839	Deposit Peugeot 302		$20,000.00	$21,562.81
8/4/2020	1471	Nose, hood, front jack pads	$14,547.70		$7,015.11
8/17/2020	1474	Windshield, spare tire cover, fenders	$14,603.11		-$7,588.00
8/24/2020	Ck # 5963	Payment/Deposit		$20,000.00	$12,412.00
8/27/2020	1478	Hood hold downs, grille, body trim	$16,143.41		-$3,731.41
9/3/2020	Ck # 5971	Payment/Deposit		$20,000.00	$16,268.59
9/10/2020	1483	Grille, hold downs, fuel tank	$14,052.53		$2,216.06
11/11/2020	1489	Final body, grille, and fuel tank	$11,348.16		-$9,132.10

REMAINING BALANCE DUE

- $9,132.10 -

THANK YOU FOR THE BUSINESS! WE'VE ENJOYED BEING A PART OF SUCH A UNIQUE RESTORATION PROJECT.

M. MOAL

20 Years of Platinum Innovation

[illegible] East 12th Street
Oakland, CA. 94606
Phone: 510-834-9066 Fax: 510-272-9288

INVOICE
1458

INVOICE

Date: 06/18/2020

Burlingame Motors
1295 Rollins Road
Burlingame, CA 94010
Office 650-343-8858

1937 Peugeot - 302 Darl'mat -
Lic # :
VIN # :

Odometer In : 0

Part Description / Number	Qty	Sale	Ext
Shop supplies and materials, sheet metal, epoxy sealer, wood for body framework *Moal*	1.00	150.00	150.00

Labor Description	Hours	Ext
Body Work Performed Complete repair of outer section of left rear fender. Form steel reinforcement strips where fenders mount to body. Weld strips inside right and left rear fenders. Hand plannish rear fenders and fit to body.	27.00	3,645.00
Body Work Performed Remove spare tire well, spare tire support rail, and inner sheet steel panels from rear body section. Remove sheet steel panels from rear wheel wells to access inner wood structure. Remove angle iron steel framework from rear tail section of body. Media blast spare tire well and steel frame. Media blast rear body bracing and angle iron parts, inner trunk panels, 13 parts altogether. Set up all media blasted parts in paint booth and epoxy seal.	9.00	1,215.00
Body Work Performed Weld reinforcement strips inside front fenders. Drill out reinforcement strips for mounting screws and install front fenders back onto car. Cut rear center section of body open to access damaged wood structure. Remove damaged wood in rear body section and make patterns for new pieces.	32.00	4,320.00
Body Work Performed Fabricate new wood structure in rear tail section of body. Fabricate missing lower wood rails and install. Remove damaged wood from right rear qtr. panel area of body where fender attaches. Fabricate new wood sections and graft back into body framework as needed. Fabricate and install steel brace to reinforce new wood right qtr. panel section with existing framework. Install spare tire steel support structure and spare tire well back into body. Fabricate and install steel inner brace for lower wood tail section of body and install. Install new sheet metal inner panels in rear of body.	42.00	5,670.00

$5024
MIS

Org. Estimate 0.00 *Revisions 0.00* *Current Estimate 0.00*

Labor:	14,850.00
Parts:	150.00
SubTotal:	15,000.00
Tax:	13.88
Total:	15,013.88
Bal Due:	$15,013.88

yments -]
hicle Received: 6/9/2020
ERMS - DUE ON RECEIPT

Customer Number : 161

Copyright (c) 2020 Mitchell Repair Information Company, LLC invhrs 1.16.20dc

PLATINUM SERIES

20 Years of Platinum Innovation

INVOICE
1463

Oakland, CA. 94606
Phone: 510-834-9066 Fax: 510-272-9288

Date: 06/30/2020

INVOICE

Burlingame Motors
1295 Rollins Road
Burlingame, CA 94010
Office 650-343-8858

1937 Peugeot - 302 Darl'mat -
Lic # :

VIN # :

Odometer In : 0

Part Description / Number	Qty	Sale	Ext
Ash plank, 48" X 8" X 2" *MacBeath*	1.00	42.82	42.82
Steel bar, 1/4" thick, 1" wide, 6 ft. *McMaster Carr*	1.00	27.14	27.14
Slotted oval head screw, M6 x 1mm, 25mm long, pack *McMaster Carr*	1.00	17.37	17.37
Hex nut, stainless, M8 X 1.25mm, pack *McMaster Carr*	1.00	12.97	12.97
Hex nut, stainless, M5 X .8mm, pack *McMaster Carr*	1.00	7.22	7.22
Slotted flat head wood screw, number 5, 3/4"long, pack *McMaster Carr*	1.00	4.30	4.30
Slotted flat head screw, M4 X .7mm, 20mm long, pack *McMaster Carr*	1.00	7.40	7.40
Square nut, class 5, M6 X 1mm, pack *McMaster Carr*	1.00	15.60	15.60
Square nut, class 5, M8 X 1.25mm, pack *McMaster Carr*	1.00	6.50	6.50
Ball with shank end roller swage end fitting, stainless, for 1/16" wire rope *McMaster Carr*	6.00	1.59	9.54
Shop supplies and materials *Moal*	1.00	25.00	25.00

Labor Description	Hours	Ext
Body Work Performed Complete installation of rear inner sheet metal panels. Weld aluminum rear body boattail section back onto body and plannish. Align, transfer punch, drill, and attach left and right rear fenders to body. Fabricate and install new support rail for lower sections of rear fenders. Straighten and repair right and left rocker panels to underside of car. Begin fabricating and fitting missing wood sections inside right and left lower rocker panels.	48.00	6,480.00
McMaster Carr Shipping		36.69
McMaster Carr Shipping		10.3

#5824
M/S

$21,733.06

Org. Estimate 0.00 Revisions 0.00 Current Estimate 0.00

Labor:	6,480.0
Parts:	175.8
Sublet:	47.0
SubTotal:	6,702.9
Tax:	16.2
Total:	6,719.1
Bal Due:	$6,719.1

{ Payments - }
Vehicle Received: 6/25/2020

Customer Number : 16

TERMS - DUE ON RECEIPT

Copyright (c) 2020 Mitchell Repair Information Company, LLC invhrs 1.16.2

Moal Inc
937 East 12th Street
Oakland, CA. 94606
Phone: 510-834-9066 Fax: 510-272-9288

INVOICE
1478

INVOICE

Date: 08/27/2020

Burlingame Motors
1295 Rollins Road
Burlingame, CA 94010
Office 650-343-8858

1937 Peugeot - 302 Darl'mat -
Lic # :
VIN # :

Odometer In : 0

Part Description / *Number*	Qty	Sale	Ext
Clear Plexiglass, 24" X 48" X 1/4" *Tap Plastics*	1.00	107.12	107.12
Lighting white plastic, 60%, 20" X 20" X 1/8" *Tap Plastics*	1.00	31.08	31.08
Neoprene rubber strip, 1" X 36" X 1/8" thick, 60A durometer *McMaster Carr*	1.00	11.93	11.93
Neoprene rubber strip, 1" X 36" X 1/8" thick, 40A durometer *McMaster Carr*	1.00	11.93	11.93
Neoprene rubber strip, 1" X 36" X 1/8" thick, 50A durometer *McMaster Carr*	1.00	11.93	11.93
Clear Plexiglass, 4" X 24" X 3/16" *Tap Plastics*	1.00	45.08	45.08
Clear Plexiglass, 24" X 24" X 1/8" *Tap Plastics*	1.00	30.82	30.82
Shop supplies and materials, aluminum for hood hold downs *Moal*	1.00	85.00	85.00

Labor Description	Hours	Ext
Body Work Performed Complete scale drawings of hood hold downs and make pattern to machine pockets. Cut out blank aluminum material to be machined. Draw out hold down handle on aluminum block after machining pockets. Cut and hand shape hold down handles. Carve recess for catch into underside of handles. Trim down rubber strap material to fit handles. Fab steel hooks for latches to mount on hood.	44.40	5,994.00
Machine Work Performed Mill pockets in aluminum blocks for hood hold downs	3.00	405.00
Body Work Performed Complete lay out and trimming of round body side vents, fit, and install on car. Order and pick up acrylic materials for small windscreen and license plate panel.	8.40	1,134.00
Body Work Performed Complete fitment on spare wheel cover. Begin fabrication work on front grille shell assembly.	51.00	6,885.00
Body Work Performed Fabricate mock up windscreen based on photos. Create plan to mount windscreen and what brackets will look like. Fabricate oval brass trim bezels where rubber strap material goes through body for hood hold downs.	10.00	1,350.00
McMaster Carr Shipping		9.54

Org. Estimate 0.00 Revisions 0.00 Current Estimate 0.00

Labor:	15,768.00
Parts:	334.89
Sublet:	9.54
SubTotal:	16,112.43
Tax:	30.98
Total:	16,143.41
Bal Due:	$16,143.41

[Payments -]
Vehicle Received: 8/18/2020

Customer Number : 161

TERMS - DUE ON RECEIPT

Copyright (c) 2020 Mitchell Repair Information Company, LLC invhrs 1.16.20dc

Moal Inc
937 East 12th Street
Oakland, CA. 94606
Phone: 510-834-9066 Fax: 510-272-9288

INVOICE
1483

INVOICE

Date: 09/10/2020

Burlingame Motors
1295 Rollins Road
Burlingame, CA 94010
Office 650-343-8858

1937 Peugeot - 302 Darl'mat -
Lic # :
VIN# :

Odometer In : 0

Part Description / Number	Qty	Sale	Ext
Steel bar, 3/16" thick, 1 1/2" wide, 6 foot length *McMaster Carr*	1.00	23.39	23.39
Steel tubing, 2.375" X .065" X 4 feet *SPD*	1.00	31.10	31.10
101 copper tubing, .032" thick, 3/8" OD, 6 feet *McMaster Carr*	1.00	34.85	34.85
Shop supplies and materials, copper rivets *Moal*	1.00	45.00	45.00

Labor Description	Hours	Ext
Body Work Performed Complete fabrication work on hood latch strap brass trim bezels. Cut plexiglass for license plate and drill holes for surround bezel. Update template for windscreen to match photos from Peugeot museum. Fabricate hold down brackets for right and left rubber hood straps. Fabricate steel base and keepers for each side.	12.20	1,647.00
Body Work Performed Complete fabrication on grille and upper mounting bracket. Fabricate rear hood brace and install. Modify forward hood brace to tie in with hood hold down handles.	46.00	6,210.00
Body Work Performed Fabricate copper fuel tank with internal plumbing and baffles matched to original. Fabricate flanges for 2 filler necks, solder, and rivet together. Fabricate 3 steel mounting straps like original tank, rivet onto new tank. (Note - fuel tank is waiting for new fuel gauge sending unit before it can be final riveted and soldered, Rene' is working on obtaining unit).	44.00	5,940.00
McMaster Carr Shipping		44.66
SPD Shipping		38.29
McMaster Carr Shipping		25.81

Org. Estimate 0.00 Revisions 0.00 Current Estimate 0.00

Labor:	13,797.00
Parts:	134.34
Sublet:	108.76
SubTotal:	14,040.10
Tax:	12.43
Total:	14,052.53
Bal Due:	$14,052.53

PAID

Customer Number : 161

[Payments -]
Vehicle Received: 8/31/2020

TERMS - DUE ON RECEIPT

Copyright (c) 2020 Mitchell Repair Information Company, LLC invhrs 1.16.20dc

Invoice

Weber Carburetor Restoration, Inc
321 Kishimura Drive
Gilroy, CA 95020

Telephone: 408-842-6670

WWW.PIERCEMANIFOLDS.COM

Invoice No.	400131
Customer No.	BURLMOT

Bill To

BURLINGAME MOTORS
1295 ROLLINS RD
BURLINGAME, CA 94010

Ship To

BURLINGAME MOTORS
1295 ROLLINS RD
BURLINGAME, CA 94010

Contact: RENE WIEGAND
Telephone: 650 343 8858

Contact: RENE WIEGAND
Telephone: 650 343 8858

Ship Via	F.O.B.	Payment Method	Salesperson
UPS GROUND		CREDIT CARD	

Invoice Date	Order Date	SO Number	Ordered By	Customer PO Number	Resale Number
					srgh 102-504863

Order Quantity	Ship Quantity	Tax	Item Number / Description		Unit Price	Extended Price
2	2	Y	3501 STROMBERG REBUILD KIT	U of M: Each	82.00	164.00
1	1	Y	C.P.P. 4 CUSTOM PLATED PARTS-PHIL WHITE	U of M: Each	209.00	209.00
1	1	N	LABOR SHOP	U of M: Each	2,702.00	2,702.00

PAID
9/17/2020
✓ 5984

Print Date	09/17/20
Print Time	10:49:31 AM
Page No.	1

Total Paid	0.00
Balance Due	3,075.00
Due Date	

Subtotal	3,075.00
Freight	0.00
Invoice Total	3,075.00

Printed By: Mike Pierce

BURLINGAME MOTORS, INC.

Since 1979

Independent Mercedes Benz Dept.
1295 Rollins Road
BURLINGAME, CA 94010-2416
(650) 343-8858 Fax (650) 343-9261

Since 1979

EPA #CAL 000398238 BAR # ARD275257

021402

Date

Time Received A.M. P.M.

Written By

Cust. Order No.

Promised A.M. P.M.

Phone when ready Yes ☒ No ☒

Cell Phone

Home Phone [redacted]

Work Phone

Other

Name [redacted]

Address

City

Year-Make-Model 1937 Peugeot

License No.

Odometer

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE. SAVE ☒ DISCARD ☒

Estimate Amount $ | Engine Size | VIN Number

Revised Estimate $ | Date | Time | Description | Authorized By | INITIAL

Revised Estimate $ | Date | Time | Description | Authorized By | INITIAL

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

* CODE N-NEW U-USED R-REBUILT

QTY	*	PART NO. OR DESCRIPTION		SALE	
1		FUEL FILTER		13	18
		PAINT		38	79
1		EL. FUEL PUMP		206	20
		MISC ZINC HARDWARE		26	62
		TOOL BLACK		86	50
1		PAINT		38	79
2		HARPON TAILLIGHT LENSES	160 00	320	00
1		STEERING WHEEL		100	00
5		MICHELIN TIRES	258 00	1791	00
5		INNER TUBES	41 50	207	50
2		FEU VIELLE	58 25	116	50
2		SCREWDRIVERS		150	00
3	V	SWITCHES	60 00	180	00
2		TIRE IRON	48 00	96	00
1		BATTERY MASTER SWITCH		140	00
4	FT	FUEL PIPE	16 00	64	00
2		1/2 FUEL FITTING	2 40	4	80
2		FERRULES	1 20	2	40
		FUEL HOSE		36	00
6		CLAMPS	2 20	13	20
		CHARGE LIGHT		40	00
		FILLER NECK HOSE		50	00
6	FT	5/9 BANJO	11 50	66	00
4	00	9MM TWISI CLAMPS	9 00	36	00
4		BLACK PRIMER	16 99	67	96
		TOTAL PARTS ▶		4298	44

TIRE PRESSURE CHECK SERVICE COMPLETED ☒
TIRE PRESSURE: LF _____ RF _____ LR _____ RR _____ (psi)
DECLINED ☒ Initial REASON:

SUBLET REPAIRS

	SHERMS		385	20
	TRESSER TOW		200	00
3	S+H FRANCE - US		240	00
	PITT WAY ELECTRIC		425	00
	TOTAL SUBLET REPAIRS ▶			

OPER NO.	REPAIR ORDER — LABOR INSTRUCTION	LABOR CHG.
	ASSEMBLE DASH BOARD WITH TWO MAIN GAGES INSTALL DASHBOARD	
	DISASEMBLE STEERING COLUMN AND BOX - SEND OUT FOR REPAIR	
	INSTALL STEERING COLUMN AND STEERING WHEEL	
	REMOVE WOOD PANELS TRIM AND FINISH PANELS PAINT ALL PANELS	
	FABRICATE TANK PROTECTION SHEET FOUR UNDER CAR	
	PRESSURE TEST FUEL TANK AND SOLDER VARIOUS AREAS	
	POLISH FUEL TANK AND INSTALL FABRICATE MOUNING BRACKETS	
	INSTALL FUEL LINES AND EL. FUEL PUMP WITH FILTER	
	CLEAN AND ADJUST BRAKE CABLES	
	CLEAN AND POLISH BALL JOINT GREASER	

WARRANTY ON PARTS & LABOR

- ☒ 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.
- ☒ 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST.
- ☒ 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST.
- ☒ 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST.
- ☒ NOT GUARANTEED - NEED ADDITIONAL SERVICE(S)

WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR PERSONAL DAMAGE. A $25 PER DAY STORAGE FEE WILL BE CHARGED IF VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS.

QTY.		SALE
	QTS. OIL	
	QTS. OIL	
	LBS. GREASE	
	TOTAL OIL, GREASE	

RECOMMENDED SERVICE:

1 CK 6041 $2000.00
2 CK 6380 $5000.00-2500.00
3 CK 6467 $10,000.00

BALANCE DUE $11456.88

I hereby authorize the repair work above to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Authorized By _____

TOTAL LABOR ▶	2000 00
PARTS	4298 44
SUBLET REPAIRS	1250 20
OIL & GREASE	
GAS	
SALES TAX	413 24
HAZARDOUS WASTE DISPOSAL FEE	
TOTAL AMOUNT ▶	25956 88

INVOICE COPY

BURLINGAME MOTORS, INC.

Since 1979

Independent Mercedes Benz Dept.
1295 Rollins Road
BURLINGAME, CA 94010-2416
(650) 343-8858 Fax (650) 343-9261

Since 1979

EPA #CAL 000398238 BAR # ARD275257

022031

Date 3/22/2023
Time Received A.M. P.M.
Promised A.M. P.M.
Written By
Cust. Order No.
Phone when ready Yes ☒ No ☒
Cell Phone [redacted]
Home Phone
Work Phone
Other

Name [redacted]
Address
City

Year-Make-Model 1954 Peugeot
License No. —
Odometer —

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE. SAVE ☒ DISCARD ☒

Estimate Amount $	Engine Size	VIN Number

Revised Estimate $	Date	Time	Description	Authorized By	INITIAL
Revised Estimate $	Date	Time	Description	Authorized By	INITIAL

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

*CODE N-NEW U-USED R-REBUILT

QTY	*	PART NO. OR DESCRIPTION			SALE	
1		HORN KIT			49	99
1		9MM HOSE CLAMP + BAND KIT			165	50
		BATTERIE ACID			45	00
		DRAIN PLUG RADIATOR			23	50
2		BROOKLAND SCREEN GLASS				
		MISC. HARDWARE	500	00	100	00
2	G	COOLANT	28	50	28	50

PD 0.5^{12} MS 6/12/23

TOTAL PARTS ► 1312 49

TIRE PRESSURE CHECK SERVICE COMPLETED ☒
TIRE PRESSURE: LF _____ RF _____ LR _____ RR _____ (psi)
DECLINED ☒ Initial REASON:

SUBLET REPAIRS

ODD PARTS FABRICATION		2200 00
ODD PARTS FABRICATION		1900 00
SHUTTER FLY BOOKS		1400 00
SAN JOAQUIN CHROME		165 00
BROADWAY PAINT		1200 00
TOTAL SUBLET REPAIRS ►		6865 00

OPER NO.	REPAIR ORDER — LABOR INSTRUCTION	LABOR CHG.
	FINISH CARB AIR FILTER AND FIT AND INSTALL	
	DETAIL - UNDERCARRIAGE - ENGINE BAY - POLISH HARDWARE	
	~~Collect~~ FILL BATTERIES WITH ACID AND SLOW DEEPCYCLE CHARGE	
	START CAR RUN TO OPERATING TEMPERATUR - CK FOR LEAKS	
	DRAIN ENGINE OIL AND REFILL (3)	
	ENERGIZE TRANSMISSION WINDINGS AND STATORS	
	TEST DRIVE - DRAIN TRANSMISSION OIL AND REFILL (3)	
	PREPAIR BOOK WITH PHOTOSHOP	
	FILL ANTI FREEZE TO -30°C FOR AIRFREIGHT	
	PREPARIE CAR FOR SHIPPING PACK UP SPATS REMOVE SCREEN	
	TAPE BATTERIES SECURE HOODSTRAPS	
	REMOVE WINDSHIELD AND FIT NEW GLASS	
	FABRICATE AND FIT BROOKLAND SCREEN GLASS	

WARRANTY ON PARTS & LABOR

- ☒ 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.
- ☒ 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST.
- ☒ 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST.
- ☒ 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST.
- ☒ NOT GUARANTEED - NEED ADDITIONAL SERVICE(S).

WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR PERSONAL DAMAGE. A $25 PER DAY STORAGE FEE WILL BE CHARGED IF VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS.

QTY.		SALE		
10	QTS. OIL 50W GEAR	28	40	284 00
16	QTS. OIL 30W HD	14	99	239 84
	LBS. GREASE			
	TOTAL OIL, GREASE			523 44

RECOMMENDED SERVICE:

1. 3/22/23 Dep CK# 6495 5,333.33
2.
3. (-$18,136.87)
4.
5.

I hereby authorize the repair work above to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Authorized By _____

TOTAL LABOR ►	1600 00
PARTS	
SUBLET REPAIRS	6865 00
OIL & GREASE	523 44
GAS	20 00
SALES TAX	50 38
HAZARDOUS WASTE DISPOSAL FEE	12 00
TOTAL AMOUNT ►	2347 08

GRUBER BUSINESS FORMS (650) 726-1113

4/15/23

Invoice

SOLD TO: Acker Leather Works
ADDRESS: 81 Digital Dr
CITY, STATE, ZIP: Novato Ca 94949 415 604 2178

SHIPPED TO: WA
ADDRESS: [redacted]
CITY, ST

1932 Peugeot 302 — 4.12.23

	Constr. Lt/Rt Backrest & Cushion Pads	390 (EA)		780 -
2	Styled, Cut, Sewed & Installed Lt/Rt Seat Covers	1300 (EA)		2600 -
5	Constr Center Rubber Trans Cover Installed			415 -
	Cut, Fit, Bound & Installed Lt/Rt Ribbed Rubber Mats			1500 -
-	Cut, Sewed Fit & Installed Lt/Rt Side Curtains		425 (EA)	850 -
	Constr, Sewed Fit Jack Bag			380 -
	Cut, Colored, Fit Forward & Rear Hood Straps		160 (EA)	320 -
	Cut, Colored, Fit & Installed Hood Seals		100 (EA)	200 -

08740

INVOICE NO. 671591

Invoice

SHIPPED TO

Acker Leather Works

ADDRESS [redacted]

21 Digital Dr

CITY, STATE, ZIP

Novato Ca 94949 4156622118

VIA

QUANTITY	DESCRIPTION	F.O.B.	DATE
	1937 Peugeot 302		4.12.21
	PARTS		2110 00
	LABOR		4935 00
	TAX		137 15
	TOTAL		7182 15
	DEPOSIT		3500 -
	BALANCE		3682 15

BURLINGAME MOTORS, INC.

Since 1979

Independent Mercedes Benz Dept.
1295 Rollins Road
BURLINGAME, CA 94010-2416
(650) 343-8858 Fax (650) 343-9261

Since 1979

EPA #CAL 000398238 BAR # ARD275257

Date 6/5/2024 022350

Time Received	Written By
A.M. P.M.	Cust. Order No.
Promised A.M. P.M.	Phone when ready Yes ☐ No ☐
Cell Phone [redacted]	
Home Phone	
Work Phone	
Other	

N[redacted]
A[redacted] o.
C[redacted]

Year-Make-Model 1957 Peugeot | License No. | Odometer

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE. SAVE ☒ DISCARD ☒

Estimate Amount $	Engine Size	VIN Number

Revised Estimate $	Date	Time	Description	Authorized By / INITIAL
Revised Estimate $	Date	Time	Description	Authorized By / INITIAL

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

* CODE N-NEW U-USED R-REBUILT

QTY	*	PART NO. OR DESCRIPTION	SALE
1		GASKET MATERIAL	25 00
		SHEET PLUSHINUM	100 00
		RAILANCE 1/23/2025	
		PAID CHECK #	
		TOTAL PARTS ▶	125 00

TIRE PRESSURE CHECK SERVICE COMPLETED ☒
TIRE PRESSURE: LF _____ RF _____ LR _____ RR _____ (psi)
DECLINED ☒ Initial REASON:

SUBLET REPAIRS

ODD PARTS	3800 20
PRECISION POWER INC	4550 00
S+H X 4 21	240 00
PIERCE CARB TESTOR	500 00
ELECTRO PLATING	2200 00
TOTAL SUBLET REPAIRS ▶	9310 00

OPER NO.	REPAIR ORDER — LABOR INSTRUCTION	LABOR CHG.
	R+R GAGES AND GENERATOR	
	SEND OUT GENERATOR + TACH	
	TO PRECISION ELECTRIC IN MICHIGAN	
	REWIRE GENERATOR FOR O.E STYLE VOLTAGE REGULATOR	
	SEND TACH OUT TO RECALIBRATE AND INSTALL ELECTRONIC DRIVE	
	INSTALL GAGES AND REWIRE FOR ELECTRONIC TACH	
	CLEAN HEADLIGHT REFLECTORS AND PAINT	
	CLEAN UNDER CARRIAGE	
	CLEAN ENGINE COMPARTMENT > AFTER FIRE <	
	R+R CARBURETORS AND SEND OUT FOR REPAIR AND REBUILD	
	FABRICATE DRIP TRAY AND POLISH DRIP TRAY	
	CLEAN BATTERIES AND CHARGE	
	TEST DRIVE CAR AND ADJUST CARBURETORS	

WARRANTY ON PARTS & LABOR

☒ 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.
☒ 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST.
☒ 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST.
☒ 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST.
☒ NOT GUARANTEED - NEED ADDITIONAL SERVICE(S).

WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR PERSONAL DAMAGE. A $25 PER DAY STORAGE FEE WILL BE CHARGED IF VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS

QTY.		SALE
	QTS. OIL	
	QTS. OIL	
	LBS. GREASE	
	TOTAL OIL, GREASE	

RECOMMENDED SERVICE:

6/5
1. Deposit $5K CK 1045
2.
3. BALANCE $ 14487.03
4.
5.

I hereby authorize the repair work above to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Authorized By _____

TOTAL LABOR ▶	1000 00
PARTS	125 00
SUBLET REPAIRS	9310 00
OIL & GREASE	
GAS	40 00
SALES TAX	12 03
HAZARDOUS WASTE DISPOSAL FEE	
TOTAL AMOUNT ▶	19487 03

INVOICE COPY