



ROSEPASSION.COM

ROSEPASSION.COM Europe & World

AUTOMOTION

AUTOMOTION.COM USA & World

SARL ROSE PASSION au capital de 18900 €
BP 40075

54703 PONT A MOUSSON CEDEX

Tél: 03.82.468.911 Fax: 03.82.468.930

Web: www.rosepassion.com Courriel: contact@rosepassion.fr

Siret: 410 206 064 00033 APE 503 B

N° TVA Intracom: FR 59 410 206 064

Identifiant EORI: FR41020606400033

IBAN: FR76 3008 7333 0000 0284 4080 150 SWIFT: CMCIFRPP

TOUTES PIECES NEUVES POUR 356 911 912 914 924 928 944 959 964 968
986 987 991 993 996 997 BOXSTER CARRERA GT CAYENNE CAYMAN GT2
GT3 GT4 PANAMERA RS RSR CUP PROTOTYPE COMPETITION

FACTURE

25/09/2020

F531099

Commande : 716745

Incoterm: DAP


Pas d'escompte accordé en cas de paiement anticipé.

Conditions de règlement: COMPTANT

Taux de calcul des pénalités de retard: 2,61 %

Indemnité forfaitaire de recouvrement: 40€

Adresse de facturation



Adresse de livraison



Tél: +1 408-828-6825 Mob: +1 408-828-6825 Fax: +1 650-618-1555 Courriel: mj_39@hotmail.com

LE NOUVEAU CATALOGUE ROSE PASSION EST ARRIVE VOUS POUVEZ LE COMMANDER SUR ROSEPASSION.COM

Ref RP	Ref RP2	Désignation	PU HT	Qté	Poids	Total
	P13818	VIDE POCHE ARD 911 69-73	513,42 €	1	0,841	513,42 €
Mode de livraison: Fedex Inter Express			Sous-total HT			513,42 €
Paiement: PAYPAL REÇU INTERNET			Port			36,60 €
			Total HT			550,02 €

L'exportateur des produits couverts par le présent document déclare que sauf indication claire du contraire, ces produits ont l'origine préférentielle Union Européenne



PRIDE AUTO BODY - HASKELL

7950 HASKELL AVE., Van Nuys, CA 91406

Phone: (818) 909-0660

Workfile ID:


2ff39552

PartsShare:

65bvFg

Final Bill

RO Number: 144003159

Customer:	Insurance:	Adjuster:	Estimator:	Eli Badro
	CUSTOMER PAY	Phone:	Create Date:	12/16/2020
		Claim:		
		Loss Date:		
		Deductible:		

1974 PORS 911S 2D CPE 6- Gasoline blk

VIN: 9113301256	Interior Color: blk	Mileage In: 0	Vehicle Out: 1/8/2021
License: 639FDE	Exterior Color: blk	Mileage Out:	
State: CA	Production Date: 5/1973	Condition:	Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		QUARTER PANEL & LAMPS						
2	E01		NO WARRENTY ON REPAIRS						
3	E01		vehicle has poor prior paint work						
4	E01		body filler visable thru paint/ shrinkage						
5	E01		paint over 19mils						
6	E01		Prep Right Quarter panel for paint only						2.0
7	E01	Refinish	RT Outer panel standard						3.5
8	E01		clear coat						1.4
9	E01	Remove/Install	RT Qtr glass fixed type tinted				1.0	Body	
10	E01	Remove/Install	RT Lens				0.2	Body	
11	E01	Blend	Rt Roof Rail edge						1.0
12	E01	Remove/Install	Lift cap				0.2	Body	
13	E01	Remove/Install	Rt Chrome Wheel arch molding				1.0	Body	
14	E01		REAR BODY						
15	E01	Remove/Install	Panel license lid center				1.5	Body	
16	E01	Repair	Weld fill holes Rear License Panel				3.0	Body	1.2
17	E01		clear coat						0.3
18	E01		ENGINE LID						
19	E01	Remove/Install	R&I lid				1.0	Body	
20	E01	Remove/Install	Grille w/o turbo				0.5	Body	
21	E01	Repair	Lid				7.0	Body	2.0
22	E01		Overlap Major Adj. Panel						(0.4)
23	E01		clear coat						1.0
24	E01	Refinish	underside						2.0
25	E01		clear coat						1.0
26	E01	Remove/Install	Nameplate 911S black				0.2	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 144003159

1974 PORS 911S 2D CPE 6- Gasoline blk

27	E01	Remove/Install	Nameplate Letters Porsche			0.2	Body	
28	E01		REAR BUMPER & LAMPS					
29	E01	Remove/Install	R&I bumper assy			1.3	Body	
30	E01	Remove/Install	LT Guard wide w/o turbo			0.5	Body	
31	E01	Remove/Install	RT Guard wide w/o turbo			0.5	Body	
32	E01		Mask jams/openings					0.3
33	E01		Mask engine					0.2
34	E01	Remove/Replace	Corrosion protection primer					0.5
35	E01		Color tint					0.5
36	E01		cover car for ref 2nd bag primer					0.5
37	E01		feather edge block sand					1.0
38	E01		Color sand & buff					1.3
39	E01	Sublet	haz waste	1	4.99		Other	

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Sublet/Miscellaneous					4.99
Labor, Body			60.00	18.1	1,086.00
Labor, Refinish			60.00	19.3	1,158.00
Material, Paint					868.50
Subtotal					3,117.49
Sales Tax					82.51
Grand Total					3,200.00
Net Total					3,200.00

Estimate Version	Total \$
Original	3,200.00

Insurance Total \$:	0.00
Received from Insurance \$:	0.00
Balance due from Insurance \$:	0.00
Customer Total \$:	3,200.00
Received from Customer \$:	0.00
Balance due from Customer \$:	3,200.00

WARRANTY - Completed repairs are warranted as long as you own the specified vehicle. The warranty applies only if the defects occur under normal driving conditions and as a result of faulty repairs or workmanship. The warranty shall be deemed null and void in the event the vehicle has been subject to accidents, alterations, negligence, abuse, or misuse. Specifically excluded from the warranty are scratches and chips acquired from driving conditions or intentional negligent acts. This four-part written warranty with specific additional limitations pertaining to each section as described below.

1 Metal work -Pride Auto Body provides a limited lifetime warranty against defective workmanship, which includes welding and the application of materials, utilized in the repair process against cracking, flaking, pitting, and deterioration (excluding recurring rust). Pride Auto Body will after inspection and at its sole discretion, repair and repaint any metal work warranted.

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



INCORPORATED

TRE AUTOMOTIVE - www.tremotorsports.com

15854 Strathern St, Van Nuys, Ca 91406

(818)909-9220

Work Order No. 301214002


Independent Porsche

SERVICE-REPAIR-RESTORATION HIGH PERFORMANCE

73 Porsche 911 Black Ref: 922
Mileage in:105558 out:
Lic: 639FDE/CA H6Cyl 2.3
Vin: 91133001256 05/73
Eq:

I acknowledge notice & oral approval of an increase in the original estimated price.
1 12/14/20 08:42am 350.00
2 12/14/20 09:02am 1000.00
3 01/23/21 09:17am 1996.06
Signature: michael in person
initial quote
repairs

- 1) Passenger door rattle and install client door pocket
2) brake fluid residue damaged the left front wheel finish- check and report
3) refinish spare wheel and left front
4) pride auto body- rear lid, l.p. panel, right quarter only<< correct plate bracket, insulation pad and retainer once completed
5) pride auto body- rear lid underside center damage repair
6) shell a/f sticker
7) check seat belt retractors
8) suspension squeak right front
9) instrument gauge illumination
10) steering column squeak and horn contact- works only one side (mushroom spring?)
11) fuel/oil combo gauge- check- possible level sender
12) red bosch rear black trim lenses?
13) estimate headliner replacement



Job01 Rebuild left front caliper Labor: 3.00 hrs@\$160.00/hr=\$480.00

Table with 4 columns: Part Number, Description, Quantity, Price. Includes items like Metal/Plastic Cleaner-N, Caliper kit-Alloy-N, ATE Super Gold-N. Job Subtotal: \$575.80

Job02 Install Fuel level sender Labor: 0.00 hrs@\$160.00/hr=\$0.00

Table with 4 columns: Part Number, Description, Quantity, Price. Includes Fuel level sender-N. Job Subtotal: \$175.00

Job03 Trim Parts Labor: 1.00 hrs@\$160.00/hr=\$160.00

Table with 4 columns: Part Number, Description, Quantity, Price. Includes Tailight seal-Right-N. Price: 23.18

----->----->----->-----Continued on the next page----->----->----->----->

Handwritten notes: 2/13/21, PAID M/C 06255 J

Customer Acknowledgement form with checkboxes for 'ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE' and 'ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE'. Includes logos for Visa, MasterCard, American Express, Discover, and ASC.



INCORPORATED

Independent Porsche

SERVICE-REPAIR-RESTORATION HIGH PERFORMANCE

TRE AUTOMOTIVE - www.tremotorsports.com

15854 Strathern St, Van Nuys, Ca 91406

(818)909-9220

Work Order No. 301214002

Job03 Trim Parts

Ref: 922

HEADLINER	Headliner-S	1.0 @	175.00 = \$	175.00	
001	Fastening hardware-N	4.0 @	5.00 = \$	20.00	
MM74353	seat belt-S	1.0 @	53.00 = \$	53.00	271.18

Job Subtotal: \$431.18

Job04 Refinish gauges

Sublet: \$950.00

Job05 Wheels

Sublet: \$730.00

Refinish two wheels to factory original

Job06 Tire

Labor: 0.20 hrs@\$160.00/hr=\$32.00

for the spare- so all 5 match

PIRELLI CINTUATO	185/70VR15 Tire-S	1.0 @	320.00 = \$	320.00	320.00
------------------	-------------------	-------	-------------	--------	--------

Job Subtotal: \$352.00

Job07 Tire shop

Sublet: \$140.00

dismount, remount three wheels and tires. (inc new tire install for spare)

Job08 Glass Removal/ installation

Sublet: \$400.00

Remove and reinstall windshield, back glass and L/R quarter glass for headliner replacement

Job09 Headliner installation

Sublet: \$750.00

Remove old headliner and sunroof for new installation of headliner and sunroof.

Job10 Install heat shield material

Labor: 1.00 hrs@\$160.00/hr=\$160.00

on inside of license plate panel . install bracket and support . install plate

Job Subtotal: \$160.00

Job11 Sunroof work

Labor: 1.00 hrs@\$160.00/hr=\$160.00

Sunroof was not timed correctly and missing hardware. Time cables side to side, refasten and test. Early model roof motors are noisy- this is normal

001	Fastening hardware-N	2.0 @	5.00 = \$	10.00	10.00
-----	----------------------	-------	-----------	-------	-------

Job Subtotal: \$170.00

Tire Pressure 32/36psi: LF[0418] RF[0418] LR [0218] RR [0418]

----->----->----->---Continued on the next page--->----->----->----->

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD

BAR # ARD00228518 DEBIT

EPA # CAD982050866

I acknowledge notice and oral approval of an increase in the original estimated price. X

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle here in described on streets, highways or elsewhere for the purpose at testing and/or inspection, if automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made, I have read and understand the statements and estimates made on this side and the reverse at this/these pages (connected with this vehicle), I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains with the Repair Garage.

CUST. SIG. X

CUSTOMER ACKNOWLEDGEMENT



INCORPORATED

TRE AUTOMOTIVE - www.tremotorsports.com

15854 Strathern St, Van Nuys, Ca 91406

(818)909-9220

Work Order No. 301214002

Payments to TRE Automotive

Status: New Work Order

Payments:

Independent
Porsche

SERVICE-REPAIR-RESTORATION
HIGH PERFORMANCE

Ref: C034 Summary

Labor	992.00
Parts	871.98
Sublet	2970.00
Haz Waste	1.00
Whl Finish Shppn	104.92
Shipping tire	20.06
Tax	82.84
Total	\$5042.80
Payments	0.00
Bal Due	5042.80

Thank you for choosing TRE Automotive



ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

CALIFORNIA

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD

BAR # ARD00228518

DEBIT



EPA # CAD982050866

I acknowledge notice and oral approval of an increase in the original estimated price. X

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle here in described on streets, highways or elsewhere for the purpose at testing and/or inspection, if automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made, I have read and understand the statements and estimates made on this side and the reverse at this/these pages (connected with this vehicle), I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains with the Repair Garage.

CUST. SIG. X

CUSTOMER ACKNOWLEDGEMENT



INCORPORATED

TRE AUTOMOTIVE - www.tremotorsports.com

15854 Strathern St, Van Nuys, Ca 91406

(818)909-9220

Work Order No. 310323002

Independent Porsche


SERVICE-REPAIR-RESTORATION HIGH PERFORMANCE

73 Porsche 911 Black

Mileage in:05835 out:
Lic: 639FDE/CA H6Cyl 2.3
Vin: 91133001256 05/73
Eq:

I acknowledge notice & oral approval of an increase in the original estimated price.
Michael in person SIGNATURE
initial estimate

- 1) headliner has wrinkles
2) stain on headliner pass side coat hook
3) center cap for right front
4) oem rear seat belts both sides
5) squeak from right front suspension
6) Letter O for rear lid
7) double check oil temp / thermostat opening on engine and oil tank
8) master cylinder and pedal bushings
9) seat belt warning lamp not working- lamp disconnected
10) Check pad glazing- de glaze
11) Handbrake lamp in gauge not connected
12) Clean floor and carpet driver front



10)

No jobs/tasks have been recorded for this work order.

Tire Pressure: LF
RF
LR
RR

Payments to TRE Automotive

Status: New Work Order

Payments:

Cost Summary

Table with 2 columns: Item, Amount. Rows: Labor (0.00), Parts (0.00), Total (\$0.00), Payments (0.00), Bal Due (0.00)

Thank you for choosing TRE Automotive

Form with payment logos (VISA, MasterCard, ASC), acknowledgment checkboxes, and signature line.

TRE AUTOMOTIVE - www.tremotorsports.com
15854 Strathern St, Van Nuys, Ca 91406
(818)909-9220

Work Order No. 331129002

73 Porsche 911 Black Ref: Yellow Quotes
Odometer reading in:6503 out: 1 11/29/23 08:49am 1000.00
Lic: 639FDE/CA H6Cyl 2.3 michael in person.
Vin: 91133001256 05/73
Eq:

Last in 3/23/2021

- 1- Oil filter service and inspection
- 2- Left rear fuel leak
- 3- Check squeak from right front creaking

Job01 UPDATE 11/30/23 11:14 am Labor: 0.00 hrs@\$185.00/hr=\$0.00

Job Subtotal: \$0.00

Job02 Replace fuel hoses and pump Labor: 2.00 hrs@\$185.00/hr=\$370.00

Replace soft hoses front and rear on the car/ replace fuel pump

901 608 105 05	fuel pump mfi-S	1.0 @	870.00 =	\$ 870.00
HS-108	Fuel line 8mm-N	3.0 @	10.50 =	\$ 31.50
HS-114	Fuel line 14mm-N	1.0 @	18.95 =	\$ 18.95
911 608 206 00	Mount-N	2.0 @	11.95 =	\$ 23.90
001	Fastening hardware-N	1.0 @	4.95 =	\$ 4.95
FL-500	Metal/Plastic Cleaner-N	1.0 @	9.95 =	\$ 9.95
				959.25

Job Subtotal: \$1,329.25

Job03 Oil filter service-911 Labor: 1.00 hrs@\$185.00/hr=\$185.00

Drain engine oil. Drain oil from oil tank. Drain oil from S-hose. Remove and replace oil filter. Refill system with oil. Check for leaks. Run car and check oil level.

930 107 764 00	Oil filter-OC54-N	1.0 @	18.89 =	\$ 18.89
FL-100	Brad Penn 20-50-N	11.0 @	14.95 =	\$ 164.45
001	Fastening hardware-N	1.0 @	4.95 =	\$ 4.95
				188.29

Job Subtotal: \$373.29

Job04 Brake System Flush Labor: 1.00 hrs@\$185.00/hr=\$185.00

FL-250	ATE Super Gold-N	2.0 @	22.95 =	\$ 45.90
FL-500	Metal/Plastic Cleaner-N	1.0 @	9.95 =	\$ 9.95
				55.85

Job Subtotal: \$240.85

Job05 Tighten front sway bar links Labor: 0.20 hrs @ \$160.00/hr= N/C

----->----->----->---Continued on the next page--->----->----->----->

Handwritten signature and number: PAD 044096

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE CALIFORNIA ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD

BAR # ARD00228518 DEBIT     

EPA # CAD982050866

I acknowledge notice and oral approval of an increase in the original estimated price. X

CUST. SIG. X

CUSTOMER ACKNOWLEDGEMENT



Independent Porsche Service and Repair
Excellence since 1974

TRE AUTOMOTIVE - www.tremotorsports.com
15854 Strathern St, Van Nuys, Ca 91406
(818)909-9220

Work Order No. 331129002

Job05 Tighten front sway bar links

Ref: Yellow

Tire Pressure: LF
RF
LR
RR


Payments to TRE Automotive
Status: New Work Order

Payments:

Cost Summary

Labor	740.00
Parts	1203.39
Haz Waste	3.00
Tax	114.32
Total	\$2060.71
Payments	0.00
Bal Due	2060.71

Thank you for choosing TRE Automotive



ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

BAR # ARD00228518

EPA # CAD982050866

DEBIT



ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle here in described on streets, highways or elsewhere for the purpose at testing and/or inspection, if automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse at this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate customer is hereby notified that the said property is not insured or protected against loss or damage by theft, fire or vandalism while the property remains with the Repair Garage.

CUST. SIG. X

CUSTOMER ACKNOWLEDGEMENT

I acknowledge notice and oral approval of an increase in the original estimated price. X