

**Kostenaufstellung 2033**

Angebotsdatum: 18.11.2021

Kunden-Nr.: 99999

Auftragsinfo: Porsche 962

Bearbeiter:

Ident.Nr.:

Fahrzeug:

KM-Stand: 0

Amtl. Kennz.:

Nächste HU:

Erstzul.:

Nächste AU:

ET/AW-Nr	Bezeichnung	Menge	ME	E-Preis	G-Preis
	Tank geöffnet, Intankpumpen und Hauptpumpen ersetzt, Kraftstoffpumpen neu verlegt	12,00		105,00	1.260,00 €
72108862	Intankpumpe	4,00	St	143,55	574,20 €
254044	Hauptpumpe	2,00	St	478,32	956,64 €
9281104750Y	Hutmutter	2,00	St	4,21	8,42 €
1074-0	Ringstück 18mm D-06 Alu	2,00	St	24,43	48,86 €
1110-0	Hohlschraube	2,00	St	6,80	13,60 €
	Turbolader aus- und eingebaut, Neuer Turbolader an Abgasanlage angepasst, Doppelflansch Abgasanlage Muster angefertigt	15,00		105,00	1.575,00 €
962AW300SX	Turbolader	1,00	St	3.250,00	3.250,00 €
962AW400	Doppelflansch Abgasanlage	1,00	St	868,00	868,00 €
429443	Hosenrohrflansch	1,00	St	34,55	34,55 €
460628	V-Band Schelle	1,00	St	32,05	32,05 €
XSHL63	Samco Schlauch	1,00	St	115,87	115,87 €
	Fahrzeug für Prüfstand vorbereitet, Messgeräte aus- und eingebaut,	10,00		105,00	1.050,00 €
	Abstimmungsarbeiten auf dem Prüfstand	1,00		2.300,00	2.300,00 €
	Türen aus- und eingebaut, Türscheiben aus- und eingebaut und anfertigen lassen, Türscheiben ersetzt	4,00		105,00	420,00 €
962L500	Türscheibe	1,00	St	650,00	650,00 €
962R500	Türscheibe	1,00	St	650,00	650,00 €

 Rinaldi Automotive GmbH & Co. KG  
 Am alten Fort 115  
 56743 Mendig  
 Tel. 02652/939142  
 Fax. 02652/939144  
 Mail: [info@rinaldi-racing.de](mailto:info@rinaldi-racing.de)

 Steuer-Nr.: 29/200/02700  
 USt-IdNr.: DE309152897

 Amtsgericht Koblenz: HRA 21803  
 Persönlich haftende Gesellschafterin:  
 Rinaldi Automotive Verwaltungs GmbH  
 Sitz: Mendig  
 Amtsgericht Koblenz: HRB 23891  
 Geschäftsführer: Michele Rinaldi

 Bankverbindung:  
 Kreissparkasse Mayen  
 BIC: MALADE51MYN  
 IBAN:  
 DE36 5765 0010 0098 0536 14

ET/AW-Nr	Bezeichnung	Menge	ME	E-Preis	G-Preis
----------	-------------	-------	----	---------	---------

	Sonst		Teile	Lohn	ZW. Summe
	3.350,00		7.202,19	3.255,00	13.807,19

Grundlagen:  
Steuerwerte:

**Gesamtbetrag EUR 13.807,19**

Rinaldi Automotive GmbH & Co. KG  
 Am alten Fort 115  
 56743 Mendig  
 Tel. 02652/939142  
 Fax. 02652/939144  
 Mail: [info@rinaldi-racing.de](mailto:info@rinaldi-racing.de)

Steuer-Nr.: 29/200/02700  
 USt-IdNr.: DE309152897

Amtsgericht Koblenz: HRA 21803  
 Persönlich haftende Gesellschafterin:  
 Rinaldi Automotive Verwaltungs GmbH  
 Sitz: Mendig  
 Amtsgericht Koblenz: HRB 23891  
 Geschäftsführer: Michele Rinaldi

Bankverbindung:  
 Kreissparkasse Mayen  
 BIC: MALADE51MYN  
 IBAN:  
 DE36 5765 0010 0098 0536 14

## Kostenaufstellung 1717

Angebotsdatum: 07.10.2020

Kunden-Nr.: 99999

Auftragsinfo: #Porsche 962 Vorbereitung Portimao

Bearbeiter:

Ident.Nr.:

Fahrzeug:

KM-Stand: 0

Amtl. Kennz.:

Nächste HU:

Erstzul.:

Nächste AU:

ET/AW-Nr	Bezeichnung	Menge	ME	E-Preis	G-Preis
	Fahrzeug für Test Portimao vorbereitet	1,00		3.000,00	3.000,00 €
	- Hauptbremszylinder umgebaut				
	- Tank zerlegt und zusammengebaut				
	- Bremse VA und HA ersetzt				
	- Rückfahrkamera eingebaut				
	- Drehzahlmesser ersetzt				
	- Funksystem eingebaut				
	- Zünderverteiler und Zündkerzen ersetzt				
	- Getriebe geöffnet und geprüft				
	- Mapping Motorsteuergerät geändert				
	- Ölverlust Motor beseitigt				
RMD231008781	Verteilerkappe	3,00	St	356,25	1.068,75 €
R2525-10	Zündkerze	12,00	St	53,45	641,40 €
93010519103	Dichtung <b>new spark plugs and distributor caps</b>	1,00	St	9,22	9,22 €
00004320458	Dichtmasse Kurbelgehäuse	1,00	St	20,41	20,41 €
047105169A	Lagerhülse	1,00	St	72,42	72,42 €
BASL15217	Wellendichtring <b>gearbox checked</b>	2,00	St	15,00	30,00 €
RRS000003	Syntix Getriebeöl 75W140	5,00	St	20,00	100,00 €
100003186L	Bremsscheibe Links	2,00	St	367,49	734,98 €
100003186R	Bremsscheibe Rechts	2,00	St	367,49	734,98 €
100002651	Bremssbelagsatz VA <b>brake discs and pads</b>	1,00	St	721,01	721,01 €
7700.11.25.34	Bremssbelagsatz HA	1,00	St	435,85	435,85 €
3401-3	Vorratsbehälter	1,00	St	44,53	44,53 €
3414-0	Vorratsbehälter	1,00	St	23,53	23,53 €
3455-4	Hauptbremszylinder <b>new brake cylinder</b>	2,00	St	278,16	556,32 €

Rinaldi Automotive GmbH & Co. KG  
 Am alten Fort 115  
 56743 Mendig  
 Tel. 02652/939142  
 Fax. 02652/939144  
 Mail: info@rinaldi-racing.de

Steuer-Nr.: 29/200/02700  
 USt-IdNr.: DE309152897

Amtsgericht Koblenz: HRA 21803  
 Persönlich haftende Gesellschafterin:  
 Rinaldi Automotive Verwaltungs GmbH  
 Sitz: Mendig  
 Amtsgericht Koblenz: HRB 23891  
 Geschäftsführer: Michele Rinaldi

Bankverbindung:  
 Kreissparkasse Mayen  
 BIC: MALADE51MYN  
 IBAN:  
 DE36 5765 0010 0098 0536 14

ET/AW-Nr	Bezeichnung	Menge	ME	E-Preis	G-Preis
E809106-T	Alu Anschluss Teflon D06 90	2,00	St	20,16	40,32 €
E800106	Alu Anschluss D06 gerade	2,00	St	9,66	19,32 €
RRS0000011	Pagid Bremsflüssigkeit	2,00	St	50,00	100,00 €
010470	Hitzeschutzschlauch-Kit 9,5mm	1,00	St	26,05	26,05 €
ST2004105S	Drehzahlmesser	1,00	St	280,25	280,25 €
DTM062S	Deutsch Stecker inkl. Pins	2,00	St	1,30	2,60 €
05551032	Hella Stecker inkl. Pins <b>engine tachometer</b>	2,00	St	1,24	2,48 €
05559232	Lötverbinder	10,00	St	0,51	5,10 €
99910010011	Kabelbinder	40,00	St	0,40	16,00 €

	Teile	Lohn	ZW. Summe
Grundlagen:	5.685,52	3.000,00	8.685,52
Steuerwerte:			
	<b>Gesamtbetrag EUR</b>		<b>8.685,52</b>

Rinaldi Automotive GmbH & Co. KG  
 Am alten Fort 115  
 56743 Mendig  
 Tel. 02652/939142  
 Fax. 02652/939144  
 Mail: info@rinaldi-racing.de

Steuer-Nr.: 29/200/02700  
 USt-IdNr.: DE309152897

Amtsgericht Koblenz: HRA 21803  
 Persönlich haftende Gesellschafterin:  
 Rinaldi Automotive Verwaltungs GmbH  
 Sitz: Mendig  
 Amtsgericht Koblenz: HRB 23891  
 Geschäftsführer: Michele Rinaldi

Bankverbindung:  
 Kreissparkasse Mayen  
 BIC: MALADE51MYN  
 IBAN:  
 DE36 5765 0010 0098 0536 14

## Kostenaufstellung 6105

Angebotsdatum: 07.01.2020

Kunden-Nr.: 10842

Bearbeiter: Ident.Nr.:  
 Fahrzeug: KM-Stand: 0  
 Amtl. Kennz.: Nächste HU:  
 Erstzul.: Nächste AU:

ET/AW-Nr	Bezeichnung	Menge	ME	E-Preis	G-Preis
repair shift linkage	Schaltgestänge instandgesetzt.	1,00		105,00	105,00 €
repair underbody	Unterboden aus und eingebaut, anchor nuts angebracht.	3,00		105,00	315,00 €
1611/000/17	Stehbolzen 10x50	2,00	St	1,65	3,30 €
6464-1	Keynut M10x1,50	2,00	St	2,28	4,56 €
6471-1	Anchor Nut M5	20,00	St	1,80	36,00 €
	Krümmer aus und eingebaut, Anschweisadapter für Messsonden angebracht.	4,00		105,00	420,00 €
sealing of oil filter housing	Öl Filter gehäuse aus und eingebaut, Ölfilter gereinigt, neu abgedichtet	2,50		105,00	262,50 €
revision of air jacks	Öltank aus und eingebaut, Luftheber aus und eingebaut, Luftheber revidiert.	5,00		105,00	525,00 €
2020017043	Dichtring Luftheber	6,00	St	16,20	97,20 €
gearbox checked, changing of synchro rings	Getriebe zerlegt und zusammengebaut, Synchronring 3 und 5 Gang ersetzt, Lager 1Gang Welle Mittelgehäuse ersetzt, Getriebeölkühler gespült.	4,00		105,00	420,00 €
RRS000003	Syntix Getriebeöl 75W140	5,00	St	20,00	100,00 €
414.000	Dichtung Getriebe	1,00	St	30,00	30,00 €
313096700322	Synchronring	1,00	St	157,52	157,52 €
313096710322	Synchronring	1,00	St	145,90	145,90 €
450049	Zylinderrollenlager	1,00	St	150,84	150,84 €
E991915	Adapter D10 x D08 Alu	2,00	St	10,16	20,32 €

Rinaldi Automotive GmbH & Co. KG Am alten Fort 115  
 56743 Mendig  
 Tel. 02652/939142  
 Fax. 02652/939144  
 Mail: info@rinaldi-racing.de

Steuer-Nr.: 29/200/02700  
 USt-IdNr.: DE309152897

Amtsgericht Koblenz: HRA 21803  
 Persönlich haftende Gesellschafterin:  
 Rinaldi Automotive Verwaltungs GmbH  
 Sitz: Mendig  
 Amtsgericht Koblenz: HRB 23891  
 Geschäftsführer: Michele Rinaldi

Bankverbindung:  
 Kreissparkasse Mayen  
 BIC: MALADE51MYN  
 IBAN:  
 DE36 5765 0010 0098 0536 14

ET/AW-Nr	Bezeichnung	Menge	ME	E-Preis	G-Preis
01253MR18M08	Reduziernippel	8,00	St	4,20	33,60 €
axle parts removed checked and cleaned	Alle Achsteile vorne und hinten, Stabis, Lenkgetriebe, Lenksäule und Pedale ausgebaut und gereinigt, Motor und Getrebe ausgebaut Getriebe abgeflanscht, Motor und Getriebeträger abmontiert und gereinigt.	10,00		105,00	1.050,00 €
wheel carrier and steering box removed and chacked	Radträger und Lenkgetriebe zerlegt und gereinigt.	3,00		105,00	315,00 €
clutch and flywheel dismantled, crankshaft seal replaced	Riementrieb aus und eingebaut, Lüfterantireb ausgebaut und zerlegt (undicht und macht Geräusche) Geschäuse geschweist, Lager und Simmerringe ersetzt, Schwungrad und Kupplung aus und eingebaut sowie geprüft, Simmerringe an der Kurbelwelle ersetzt.	6,00		105,00	630,00 €
500918	Wellendichtring	1,00	St	11,50	11,50 €
28753	Wellendichtring	1,00	St	11,50	11,50 €
6005C2P5	Rillenkugellager 6005/C2	1,00	St	14,37	14,37 €
1176067	Zylinderrollenlager	1,00	St	87,25	87,25 €
310063	Rillenkugellager 6005/C2	1,00	St	12,96	12,96 €
99911342641	Dichtring	1,00	St	34,12	34,12 €
99911329041	Dichtring	1,00	St	26,10	26,10 €
varnishing rear wing	Heckflügelblatt aus und eingbaut.	0,50		105,00	52,50 €
	Heckflügel lackiert	1,00		450,00	450,00 €
	Yokohama Aufkleber angebracht	1,00		105,00	105,00 €
	Tankschaum sowie Pumpen ausgebaut / Tankblase ausgebaut	4,00		105,00	420,00 €
	Radträger, Radlager sowie Radnaben geprüft geschmiert und zusammengebaut.	6,00		105,00	630,00 €
826028	Wellendichtring 58x80x8	4,00	St	10,39	41,56 €
30353	Wellendichtring 82x105x12	4,00	St	15,71	62,84 €
499672	Wellendichtring 120x140x12	8,00	St	20,28	162,24 €
	Motorträger geschweißst	0,50		105,00	52,50 €
	Motor und Getriebe, alle Fahrwerksteile, Pedale und Lenkung eingebaut.	20,00		105,00	2.100,00 €
1132-0	Adapter D-04/12x1,5mm	1,00	St	5,24	5,24 €
E921106	Adapter D-06 Male/Female 90	1,00	St	10,38	10,38 €

ET/AW-Nr	Bezeichnung	Menge	ME	E-Preis	G-Preis
relocated oil line, wiring harness engine optimized	Alle Stahlflexleitungen verlegt und befestigt, Öltank eingebaut und befüllt, ECU Einspritzdüsen und Motorkabelsterng umgebaut, Fahrzeugelektrik teils angepasst verlegt und befestigt.	12,00		105,00	1.260,00 €
RRS000006	Syntix Motoröl 10W60	20,00	St	18,48	369,60 €
5114-0	Dekabon Leitung 6mm	4,00	St	5,74	22,96 €
5091-01	Sprühkopf	1,00	St	35,54	35,54 €
pressure test of all intercooler	Beide Ladeluftkühler sowie Ölkühler aus und eingebaut, Ladeluftkühler auf dichtheit geprüft ( i.O. bei 1 Bar ), Ölkühler gespült, Luftleitbleche instandgesetzt und befestigt.	6,00		105,00	630,00 €
	Alte Tankblase eingebaut, Tank ohne Schaum zusammengebaut und befüllt.	4,00		105,00	420,00 €
new fuel tank	Alten Tank erneut ausgebaut neue Tankblase eingebaut, Tankschaum zugeschnitten und eingebaut, Tank auf dichtheit geprüft.	6,00		105,00	630,00 €
40272850000	Tank	1,00	St	3.728,33	3.728,33 €
x-ray inspection of all axle parts, steering box,	Achsteile VA und HA aus- und eingebaut, Lenkung aus- und eingebaut, Alle Felegen zerlegt und zusammengebaut	12,00		105,00	1.260,00 €
	Rissprüfung Achsteile inkl. Erstellung Zertifikat	1,00		11.567,65	11.567,65 €
	Antrag HTP erstellt	1,00		1.200,00	1.200,00 €
monitoring system engine	Überwachungssystem eingebaut und konfiguriert	12,00		105,00	1.260,00 €
M25LCU2C/39434	LCU2 Meßsystem (Überwachungssystem)	1,00	St	330,00	330,00 €
M14Z007/39397	Sensoren für Meßsystem	1,00	St	1.582,80	1.582,80 €
M14Z998	Temperaturfühler	1,00	St	74,00	74,00 €
0280150355	Einspritzventil	12,00	St	126,05	1.512,60 €
new fuel injectors	Unterboden Motor instandgesetzt	1,00		280,00	280,00 €
	Unterboden Getriebe instandgesetzt	1,00		280,00	280,00 €
	Gehäuse instandgesetzt	1,00		180,00	180,00 €
mapping on test bench	Abstimmungsarbeiten Prüfstand VGS	1,00		5.200,00	5.200,00 €
	Elektrik und Verkabelung Innenraum komplett zerlegt neu installiert	15,00		105,00	1.575,00 €
91161312432	Warnblinkschalter	1,00	St	54,71	54,71 €

Rinaldi Automotive GmbH & Co. KG  
 Am alten Fort 115  
 56743 Mendig  
 Tel. 02652/939142  
 Fax. 02652/939144  
 Mail: info@rinaldi-racing.de

Steuer-Nr.: 29/200/02700  
 USt-IdNr.: DE309152897

Amtsgericht Koblenz: HRA 21803  
 Persönlich haftende Gesellschafterin:  
 Rinaldi Automotive Verwaltungs GmbH  
 Sitz: Mendig  
 Amtsgericht Koblenz: HRB 23891  
 Geschäftsführer: Michele Rinaldi

Bankverbindung:  
 Kreissparkasse Mayen  
 BIC: MALADE51MYN  
 IBAN:  
 DE36 5765 0010 0098 0536 14

ET/AW-Nr	Bezeichnung	Menge	ME	E-Preis	G-Preis
	Fahrzeug teilweise neu foliert	1,00		950,00	950,00 €
	Getriebe zerlegt und zusammengebaut, Übersetzung geändert, Schaltstange umgebaut	15,00		105,00	1.575,00 €
66140	Schaltgelenk	2,00	St	55,15	110,30 €
	Fahrwerk aus- und eingebaut, Federbeine zerlegt und zusammengebaut	10,00		105,00	1.050,00 €
VAK4BE0KSW	Stoßdämpfer VA Stahl	2,00	St	520,00	1.040,00 €
VAK4BE0KSWA	Stoßdämpfer VA Alu	2,00	St	585,00	1.170,00 €
HAK4BE0KSW	Stoßdämpfer HA Stahl	2,00	St	520,00	1.040,00 €
HAK4BE0KSWA	Stoßdämpfer HA Alu	2,00	St	585,00	1.170,00 €
E4FT3Z002A00	Distanzglocke <b>new damper front and rear</b>	8,00	St	33,76	270,08 €
E4MU1Z010A00	Sechskantmutter	8,00	St	2,55	20,40 €
B4LG1Z005A01	Schraubauge	8,00	St	22,69	181,52 €
E4FT4Z003A04	Kontermutter	8,00	St	9,69	77,52 €
E4FT4Z007A02	Federteller	8,00	St	23,97	191,76 €

Sonst	Teile	Lohn	ZW. Summe
20.632,65	14.241,42	16.537,50	51.411,57

Grundlagen:  
 Steuerwerte:

**Gesamtbetrag EUR 51.411,57**

Rinaldi Automotive GmbH & Co. KG Am alten Fort 115 56743 Mendig Tel. 02652/939142 Fax. 02652/939144 Mail: info@rinaldi-racing.de	Steuer-Nr.: 29/200/02700 USt-IdNr.: DE309152897	Amtsgericht Koblenz: HRA 21803 Persönlich haftende Gesellschafterin: Rinaldi Automotive Verwaltungs GmbH Sitz: Mendig Amtsgericht Koblenz: HRB 23891 Geschäftsführer: Michele Rinaldi	Bankverbindung: Kreissparkasse Mayen BIC: MALADE51MYN IBAN: DE36 5765 0010 0098 0536 14
---	--	--	---





CLASSIC PORSCHE SPECIALISTS

739 Folger Ave  
Berkeley, California 94710  
<https://retro-sport.com>

# Invoice

# 13366

**Balance Due**  
**\$3,871.51**

Bill To

Invoice Date : Dec 13, 2019

Terms : Due on Receipt

Item & Description	Qty	Rate	Amount
Shop Labor Remove and disassemble shift linkage bring to machine shop start work with machinist	2.5 Hour(s)	140.00	350.00
Shop Labor Inventory spare parts	1 Hour(s)	140.00	140.00
Shop Labor Coordinate shipping with logistics companies	1 Hour(s)	140.00	140.00
Shop Labor Palletize wheels and spares	3 Hour(s)	140.00	420.00
Shop Labor Pack spares	2 Hour(s)	140.00	280.00
Shop Labor Prepare car for air transport	2.5 Hour(s)	140.00	350.00
Shop Labor Load car and pallets in transporter	1 Hour(s)	140.00	140.00
Outside Services Apply clear paint protection film	1 project	1,186.25	1,186.25
Auto Parts 3M Scotchgard Pro PPF: 52 sqft of 3M premium durable clear paint protection film	1 unit(s)	676.00	676.00
Auto Parts Alternator belt	1 unit(s)	28.00	28.00
Auto Parts Fan belt	1 unit(s)	28.00	28.00
Miscellaneous Item SD Card	1 unit(s)	60.00	60.00
<b>Sub Total</b>			<b>3,798.25</b>

Taxable Amount	3,798.25
CA Sales Tax (9.25%)	73.26
<b>Total</b>	<b>\$3,871.51</b>
<b>Balance Due</b>	<b>\$3,871.51</b>

Notes

Thank you for your business!  
 If a balance is due, please remit payment to the above address.  
 PAYMENT OPTIONS  
 Pay by check to: Retro Sport, 741 Folger Ave, Berkeley, CA 94710  
 Wire instructions:  
 Benjamin Kirchner Db. Retro-Sport  
 739 Folger Ave, Berkeley, CA 94710-2809  
 (510) 508-4300  
 Wells Fargo Bank N. A.  
 1800 Solano Ave, Berkeley, CA 94707  
 Account: 1001620671  
 Routing: 121000248  
 Swift: WFBIUS6WFFX

To pay invoice now by eCheck or by credit card click the following link:



Terms & Conditions

Accounts not paid within 15 days of the date of the invoice are subject to a 1.5% monthly finance charge. We reserve the right to hold vehicles and any parts until all accounts have been paid.



CLASSIC PORSCHE SPECIALISTS

739 Folger Ave  
Berkeley, California 94710  
<https://retro-sport.com>

# Invoice

# 13325

**Balance Due**  
**\$17,256.60**

Bill To

Invoice Date : Oct 28, 2019  
Terms : Due on Receipt  
For : 962 Prep

Item & Description	Qty	Rate	Amount
Shop Labor Data system installation	32 Hour(s)	140.00	4,480.00
Shop Labor Fix loose distributor cap problem. Machine distributor cap bolts.	1.5 Hour(s)	140.00	210.00
Shop Labor Install dive planes	4 Hour(s)	140.00	560.00
Shop Labor Nut and bolt between test days	1 Hour(s)	140.00	140.00
Shop Labor Clean car between test days	2 Hour(s)	140.00	280.00
Shop Labor Change gears to Sears Point gears	3 Hour(s)	140.00	420.00
Shop Labor Change gears to Daytona gears	3 Hour(s)	140.00	420.00
Shop Labor Rewire Fire system harness for outside trigger	2 Hour(s)	140.00	280.00
Shop Labor Bring wheels to Roger Kraus for mounting and balancing	2 Hour(s)	140.00	280.00
Outside Labor Roger Kraus - mounting and balancing. Disposal fee.	1 project	120.00	120.00
Outside Labor Fabricate new factory replica stainless steel skid plates for nose	1 project	600.00	600.00
Outside Labor Troubleshoot and temp wire fire system for in-cockpit operation	1 project	103.00	103.00
	1	120.00	120.00

Item & Description	Qty	Rate	Amount
Outside Services Fabricate brake pressure sensor fittings	project		
Auto Parts Hirschmann Plug and Lead	1 unit(s)	62.50	62.50
Auto Parts Camera mount - Ram	1 unit(s)	52.00	52.00
Auto Parts Rear brake pad set - PFC	1 unit(s)	420.00	420.00
Auto Parts ATE Brake banjo fittings	2 unit(s)	35.00	70.00
Auto Parts 962 Titanium brake fittings	2 unit(s)	75.00	150.00
Auto Parts Brass 10x1 brake fittings	2 unit(s)	19.50	39.00
Auto Parts Front dive planes - Factory Porsche new old stock	2 unit(s)	500.00	1,000.00
Auto Parts Castrol gear oil (1 qt)	2 unit(s)	19.50	39.00
Brake Fluid - MOTUL Racing RBF 660 (500 ml)	2 unit(s)	26.18	52.36
Auto Parts Michelin tires	4 unit(s)	772.00	3,088.00
Auto Parts Miscellaneous materials for data system install.	1 unit(s)	40.00	40.00
930R 2nd/3rd 1.529 17:26 GQ Gear Set New Albins PG 930R 2nd/3rd 17:26 1.529 GQ Gear Set New Albins PG Std	1 Set	1,168.70	1,168.70
930R 3rd-5th 1.160 25:29 PT Gear Set New Albins PG 930R 3rd-5th 25:29 1.160 PT Gear Set New Albins PG Std	1 Set	1,168.70	1,168.70
930R 3rd-5th 1.038 26:27 QR Gear Set New Albins HB 930R 3rd-5th 26:27 1.038 QR Gear Set New Albins HB Std	1 Set	1,110.70	1,110.70
	Sub Total		16,473.96
	CA Sales Tax (9.25%)		782.64
	<b>Total</b>		<b>\$17,256.60</b>
	<b>Balance Due</b>		<b>\$17,256.60</b>

*circled total* ✓



# veracityracingdata

Veracity Racing Data, LLC 805.238.1699  
5505 Linne Road  
Paso Robles, CA 93446

Order

Invoice #: 00006611

Bill To:

Ship To:

c/o Retro Sport  
741 Folger Ave  
Berkeley, CA 94710  
Attn: Ben Kirchner

SALESPERSON		YOUR NO.	SHIP VIA	SHIP DATE	TERMS	DATE	PG.
Ellen Ferguson			UPS Next Day		Prepaid	10/12/19	1
QTY.	ITEM NO.	DESCRIPTION	PRICE	UNIT	DISC %	EXT PRICE	TX.
1	AIM-EVO5 1.3 GPS08	EVO5 Data Logger, 1.3m GPS08	\$1,699.00	Each		\$1,699.00	X
1	AIM-GS-Dash	GS-Dash Digital Display	\$429.00	Each		\$429.00	X
1	VRD-Linear Pot 75mm	Linear Pot 75mm, Rod End for Throttle	\$250.00	Each		\$250.00	X
1	AIM-String Pot	String Potentiometer-10" for Steering	\$252.00	Each		\$252.00	X
2	AIM-PRS-839	Pressure Sender 0-2,000 psi, 1/8 NPT	\$159.00	Each		\$318.00	X
4	AIM-719 - 719 Patch	AiM 719 - 719 Patch Cable, 2.0 meter (78 inches)	\$29.00	Each		\$116.00	X
1	AIM-Data Hub-40 cm	AiM Data Hub, 4 Port CAN Connection, 40 centimeter (15 inches)	\$60.00	Each		\$60.00	X
1	AIM-SC GP HD 2.2 84	SmartyCam GP HD Rev 2.2, 84° Lens, 2m Cam & CAN Cables	\$1,099.00	Each		\$1,099.00	X
1	AIM-SC GP HD	SmartyCam GP HD Bullet Camera Bracket	\$32.00	Each		\$32.00	X
EVO5 will be shipped overnight from AiM to Retro Sport on 10/14/19. Balance of order shipping UPS ground from Veracity.				Sale Amt.:		\$4,255.00	
				Freight:		\$125.00	
				Sales Tax:		\$308.49	
				Total Amt.:		\$4,688.49	
				Paid Today:		\$0.00	
				Balance Due:		\$4,688.49	



CLASSIC PORSCHE SPECIALISTS

739 Folger Ave  
Berkeley, California 94710  
<https://retro-sport.com>

# Invoice

# 13287

**Balance Due**  
**\$19,806.23**

Bill To

Invoice Date : Sep 25, 2019

Terms : Due on Receipt

For : 11929

Item & Description	Qty	Rate	Amount
Shop Labor Inspect car and speak with Sean Creech, Klaus Fischer and Alain Nadel regarding hours and condition of equipment	4 Hour(s)	140.00	560.00
Shop Labor Open gearbox to figure out ratios (Sean Creech said it had short gears in it) Replace gears with Daytona gears	5 Hour(s)	140.00	700.00
Shop Labor Replace seat belts - out of date	3 Hour(s)	140.00	420.00
Shop Labor Figure out non-stock fuel system (pumps are inside fuel cell). Original pump set up was supposed to be with car - maybe we can find it. We need to have extra pumps on hand. Sean Creech informed which pumps are in it.	1 Hour(s)	140.00	140.00
Shop Labor Nut and bolt	4 Hour(s)	140.00	560.00
Shop Labor Check fire system - Needs new fire bottle. Took it to get re certified and they said the bottle is too old - ordered new bottle.	1 Hour(s)	140.00	140.00
Shop Labor Align car - scale pad	8 Hour(s)	140.00	1,120.00
Shop Labor Bring wheels to Roger Kraus for mounting and balancing	2 Hour(s)	140.00	280.00
Shop Labor Replace headlights with less expensive versions	2 Hour(s)	140.00	280.00
Outside Services Repair front tow hook	1 project	300.00	300.00
Outside Services Mount and balance tires	8 project	30.00	240.00

Item & Description	Qty	Rate	Amount
Auto Parts AP Brake Pads	2 unit(s)	300.00	600.00
Auto Parts Sabelt race harness set	1 unit(s)	561.00	561.00
Bosch 044 Fuel Pump 0580254044390 Bosch "044" high flow fuel pump 200 LPH@5 Bar	2 piece	236.00	472.00
Auto Parts Helmet air blower kit	1 unit(s)	175.50	175.50
Auto Parts New SPA fire bottle	1 unit(s)	520.00	520.00
Auto Parts Michelin tires	8 unit(s)	772.00	6,176.00
930R 2nd/3rd 1.304 23:30 NU Gear Set New Albins PG 930R 2nd/3rd 23:30 1.304 NU Gear Set New Albins PG Std	1 Set	1,168.70	1,168.70
930R 3rd-5th 0.862 29:25 TP Gear Set New Albins PG 930R 3rd-5th 29:25 0.862 TP Gear Set New Albins PG Std	1 Set	1,168.70	1,168.70
930R 3rd-5th 0.733 30:22 UM Gear Set New Albins HB 930R 3rd-5th 30:22 0.733 UM Gear Set New Albins HB Std	1 Set	1,110.70	1,110.70
Auto Parts Windshield wiper arm	1 unit(s)	1,500.00	1,500.00
Auto Parts Headlights	4 unit(s)	84.50	338.00
		Sub Total	18,530.60
		CA Sales Tax (9.25%)	1,275.63
		<b>Total</b>	<b>\$19,806.23</b>
		<b>Balance Due</b>	<b>\$19,806.23</b>

**Notes**

Thank you for your business!  
 If a balance is due, please remit payment to the above address.  
 PAYMENT OPTIONS  
 Pay by check to: Retro Sport, 741 Folger Ave, Berkeley, CA 94710  
 Wire Transfer:  
 Benjamin Kirchner Db. Retro-Sport  
 739 Folger Ave, Berkeley, CA 94710-2809 (510) 508-4300  
 Wells Fargo Bank N. A.  
 1800 Solano Ave, Berkeley, CA 94707

Account: 1001620671  
Routing: 121000248  
Swift: WFBIUS6WFFX

## Terms & Conditions

Retro Sport and its employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on vehicle to secure the amount of repairs thereto. Retro Sport will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond Retro Sport's control. Customer is hereby notified that said property is not insured or protected to the amount of the actual cash value thereof or otherwise, against loss occasioned by theft, fire or vandalism while property remains with Retro Sport. Customer is required to carry their own insurance for the total value of their vehicle while on the Retro Sport premises, and while being transported to/from Retro Sport, or to/from an event.



Sean Creech Motorsports, LLC

# Invoice

1092 Jupiter Park Lane  
Suite 270  
Jupiter, FL 33458

Date	Invoice #
3/24/2015	478

Bill To

P.O. No.	Terms	Project
962 Engine Rebuild	Due on receipt	

Quantity	Description	Rate	Amount
	962 Engine Rebuild By Klaus Fischer at Amalfi Racing		
	3.0 Liter Pistons & Cylinders and shipping	13,968.00	13,968.00
	6 Intake & 6 Exhaust Valves and shipping	2,376.00	2,376.00
1	Engine Sealing Kit	913.00	913.00
6	Ni Resist Rings & shipping	160.80	964.80
1	Main Bearing set	662.40	662.40
1	Flywheel Bearing	28.29	28.29
9	Flywheel bolts	4.14	37.26
12	Set inner valve springs	47.38	568.56
12	Set outer valve springs	47.38	568.56
12	Set of Valve spring retainers	80.80	969.60
1	Intermediate Shaft Bearing set	95.22	95.22
1	Intermediate bearing set	42.32	42.32
1	Chain Wheel Z-24	87.97	87.97
2	Timing Chains	138.78	277.56
6	Slide rails	7.61	45.66
2	Chain wheels	110.29	220.58
2	Flange for chain wheel	127.00	254.00
2	Chain Wheel #2	96.40	192.80
27	Disassemble and inspect engine, remove injector valves. Degrease engine case and cylinder heads.(Dec 9 to 20) at Amalfi Rate	95.00	2,565.00
	UPS outbound shipment of connecting rods	43.63	43.63
	UPS outbound shipment of crank shaft	151.91	151.91
3	Bolt up Crank Case and send out for Check. At Amalfi Rate	95.00	285.00
1	Send out Cylinder heads for refurbish. At Amalfi Rate	95.00	95.00
	Cylinders, Valves and parts inspection and forward to machine shop	120.00	120.00
0.65	Cam Shaft return after repair. At Amalfi Rate	95.00	61.75
	Cost of crank shaft straightening, balance & polishing. Plus shipping	475.00	475.00
	Crank Shaft return after inspection. At Amalfi Rate	95.00	95.00
	Crank case Align hone	275.00	275.00
1	Crank case return & inspection. At Amalfi Rate	95.00	95.00
24	Cylinder Head studs	45.75	1,098.00
12	Con rod bearings	31.25	375.00
25	O rings	0.50	12.50
Thank you for your business.		<b>Total</b>	

Sean Creech Motorsports, LLC

1092 Jupiter Park Lane  
 Suite 270  
 Jupiter, FL 33458

# Invoice

Date	Invoice #
3/24/2015	478

Bill To

P.O. No.	Terms	Project
962 Engine Rebuild	Due on receipt	

Quantity	Description	Rate	Amount
1	Crank shaft pulley bolt	10.50	10.50
6	Cylinder head base shim	6.00	36.00
6	O ring Cylinder Base	5.50	33.00
1	Oil seal Cam	28.80	28.80
12	Rocker arms	250.00	3,000.00
12	Rocker arm shaft coating	45.00	540.00
24	Rocker are shaft seals	3.50	84.00
12	Valve lash caps	35.00	420.00
6	Carillo Connecting rods	425.00	2,550.00
6	Used Cylinder heads	1,500.00	9,000.00
6	Cylinder head inspection, refurbish & assemble.	375.00	2,250.00
6	Match Cylinder & Head for Ni Seal	185.00	1,110.00
1	Cost of camshaft bolt removal	450.00	450.00
2	Custom made camshaft bolts	425.00	850.00
95	General assembly. At Amalfi Rate.	95.00	9,025.00
1	962 Distributor Cap	325.00	325.00
35	Dyno Prep. At Amalfi Rate	95.00	3,325.00
1	Cost for Dyno testing and service after	4,400.00	4,400.00
12	Spark plugs	130.00	1,560.00
Thank you for your business.		<b>Total</b>	\$67,017.67