

Prestige Autohaus

1400 Central Rd. 1A

Walnut Creek, CA 94596

(925) 937-5400

BAR ARD 00291291 EPA CAL000449420

German & Italian Car Service

Invoice # 57807

1969 Alfa Romeo Spider Base

VIN:

Engine: L4 1.8L, 109cid, DOHC, GAS, FI

Trans:

License #

ODO In:44325

Color:

Mfg. Date:

Unit #

Out: 44325

Inv Date: 5/13/2022

Promised: 5/13/2022 @ 5:00pm

Service Writer:

Status: Posted

Driver: Thom, Peter

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
------------------	----------------------	--------------------	-----	-----	-------	-----

Customer requests that: Custom time sheet

Customer requests that: The Fuel Lines are leaking.

Labor Service - Replace leaking fuel lines in engine compartment., incl. injector lines.	2.40		175.00		420.00
New 2134.0600 Fuel Hose, 7.5x13.5		27.00	2.21		59.67
New HC 10 - 16 Hose Clamp 10 - 16 mm		4.00	2.89		11.56
New HC 8-12 Hose Clamp, 8-12 mm		10.00	2.78		27.80
New COPPER WASHER Copper Washer		2.00	2.05		4.10
New 2122.1017 Fuel Hose, 12x17mm		4.00	2.73		10.92

Customer requests that: Castor bushings are worn out.

Labor Service - Replace castor bushings.	1.00		150.00		150.00
New 605 16 902P Bushing Set, Castor poly		1.00	76.00		76.00

Notes

No engine number on block

Vehicle Tire Information

Check Performed.

Front Brakes 7 mm

Rear Brakes 7 mm

	Left Front	Right Front	Left Rear	Right Rear	Checked By
Tire Pressure PSI	30	30	30	30	
Tread Depth	9/32"	9/32"	9/32"	9/32"	

Warranty

All repair work and parts are warranted for one year. Customer supplied parts and used parts carry no warranty, incl. install. Any custom set up, rims or modifications are not covered or warrantied. Any damage resulting is not covered. Retorque wheels after 50 miles. Car storage is \$150.00 per day after finished work or

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

X Consumer acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligations set forth by the card member's agreement with the issuer

Posted 5/13/22 4:55PM

Visa 776.68

Tax Breakdown:

Default Sales Tax 16.63

Invoice Summary

Parts 190.05
Labor 570.00

Sub Total 760.05
Sales Tax (DEF) 16.63

Inv Total 776.68

Prestige Autohaus1400 Central Rd. 1A
Walnut Creek, CA 94596

(925) 937-5400

BAR ARD 00291291 EPA CAL000449420

German & Italian Car Service

Invoice # 57850**1969 Alfa Romeo Spider Base****VIN:**

Engine: L4 1.8L, 109cid, DOHC, GAS, FI

Trans:

License #

ODO In:44361

Color:

Mfg. Date:

Unit #

Out: 44361

Inv Date: 6/14/2022

Promised: 6/21/2022 @ 5:00pm

Service Writer:

Status: Posted

Driver: Thom, Peter

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
Customer requests that: The Front Springs need replacement.						
Labor Service - Install customer supplied front springs. Note some parts are missing.			4.50		175.00	787.50
Media blast and paint parts.						
New	METRIC WASHER	Metric Washer		10.00	0.60	6.00
New	POR 15 SPRAY	Spraypaint, POR 15		1.00	29.64	29.64
Customer requests that: The Rear Springs need replacement.						
Labor Service - Install customer supplied rear springs. Replace bump stops and catch straps. Note some parts are missing. Remove spacers.			7.00		175.00	1,225.00
New	ELEC HEAT SHRINK	Elec, Heat Shrink		6.00	1.58	9.48
New	METRIC WASHER	Metric Washer		2.00	0.60	1.20
New	605 16 760	Rebound Strap Fix Kit		2.00	22.05	44.10
New	COTTER PIN	Cotter Pin		6.00	1.05	6.30
New	SU071	T-Bar End Thrust Washer,poly		2.00	12.60	25.20
Customer requests that: Brake Hoses need to be replaced.						
Labor Service - Replace brake hoses.			1.50		175.00	262.50
New	SS BR044 KIT	Brake hose Kit, braided/stainless		1.00	145.95	145.95
New	55 9520 103	Brake Fluid		1.25	14.96	18.70
New	COPPER WASHER	Copper Washer		1.00	2.05	2.05
Customer requests that: Rear axle seals leaking.						
Labor Service - Rplace rear axle oil seal.			1.00		175.00	175.00
New	COPPER WASHER	Copper Washer		2.00	2.05	4.10
New	RL 57904	Gear Oil, 75W-90 GL-5		1.75	19.58	34.27
Customer requests that: The Exhaust System Hangers need replacement.						
Labor Service - Replace exhaust hangers and support bushings.			1.50		175.00	262.50
New	FENDER WASHER	Fender Washer		8.00	1.14	9.12
New	METRIC NUT	Metric Nut		2.00	0.79	1.58
New	METRIC BOLT	Metric Bolt		3.00	1.84	5.52
New	605 16 651	Exhaust Hanger		1.00	7.46	7.46
New	605 15 936	Bushing, Exhaust		2.00	12.08	24.16
Customer requests that: Customer reports electrical problem.						
Labor Service - Repair and replace ground and positive terminal for main fuel pump.			0.50		175.00	87.50
New	ELEC 1	Elec, Connector		3.00	2.63	7.89
New	ELEC 02500	Elec, wire 12ga, assorted colors		3.00	0.79	2.37
New	FENDER WASHER	Fender Washer		2.00	1.14	2.28

Add On Charges Breakdown

Haz. Materials

1.82

Notes

If 24 3/8 rf 24 1/4 6mm spacer

If 24 3/4 rr 24 1/2 No spacer

Vehicle Tire Information

Check Performed.

Front Brakes mm