

AUTO RECORD

AUTO RECORD

AT-A-GLANCE

NAME Yern HARVEY

ADDRESS R. 1

(Home) Oakwood, Ohio Zip 45873

ADDRESS 599-2354 PHONE

(Business)

MAKE OF CAR Lotus (1964)

MODEL 7 American COLOR Red

SERIAL NO. SB 1766 MOTOR NO. _____

REGISTRATION NO. _____ KEY NO. _____

INSURANCE AGENT Grant - Shisler

ADDRESS Oakwood, Ohio

Gas and Oil

Consumption

GAS AND OIL

DATE	SPEEDOMETER READING	GALS.	COST	MILES per GAL.	OIL qts.	COST	TAX	SERVICE STATION
6/21	273	8.8	3 77					
7/13	423	7.0	3 00					
7/18	652	7.8	3 35					
7/17/73	814	6.8	2 85					
7/28/73	844	3.0	1 30					
7/31/73	1058	8.0	2 95					
8/4/73	1143	3.2	1 45					
8/18/73	1366	5.0	2 15					
3/23/74	1592	5.7	3 25					
4/24/74	1846	8.2	4 35					
4/26/74	1977	7.8	4 15					
4/27/74	2040	4.0	2 13					
5/18/74	2188	4.0	2 31					
5/19/74	2267	Foot	✓					
5/29/74	2411							
5/21/74	2488	5.6	3 26					
5/25/74	2568	5.2	3 60					
5/26/74	2667	5.0	3 100					
5/31/74	2767	7.1	4 10					
6/8/74	2857	4.7	2 70					
6/29/74	3081	2.6	1 50					
6/29/74	3239	5.7	3 90					

GAS AND OIL

LUBRICATION

REPAIRS & ACCESS

TIME MILEAGE

THE PLAYERS

Repairs and

Accessories

DATE	SPEEDOMETER READING	MECHANICAL REPAIR	BODY AND FENDER	ACCESSORIES	SERVICE STATION	COST
Winter 1972	0		Replace Front	Body panels	Restoration cost	6 50
	0		New Hood			23 00
	0			2 R. Glaster Lamps		5 00
	0			Steering wheel		
	0	Regrind cranks				20 00
	0	Balance Rods				20 00
	0	main Brgs				12 00
	0	Rod Brgs				8 00
	0	camshaft				32 50
	0			oil filter		2 35
	0		Paint-Acc.			6 00
	0		Pop Rivets			3 00
	0		Rear Fenders			50 00
	0		Front Fenders			50 00
	0		Nose Cowl			60 00
2/2/74	1481	Ford 116E 1600 cc cross	Flow Engine + Trans.		Total cost	239 86
2/10/74	1481	2 Weber 40 DCOE 2	carburetors		includes complete rebuild	218 00
2/1/74	1481	intake manifold & Throttle Linkage				
2/20/74	1481	clutch Disc				20 33
2/24/74	1481	oil filter				1 90
winter 1975		convert Engine to Dry Sump Lubrication		3 mos. spent on Eng. conversion Top & Extension spring '74'		175 00

GAS AND OIL

LUBRICATION

REPAIRS & ACCESS.

TRIP DIARY

Repairs and

Accessories

DATE	SPEEDOMETER READING	MECHANICAL REPAIR	BODY AND FENDER	ACCESSORIES	SERVICE STATION	COST	
5/1/76	5130			Fan Belt		3	14
3/15/77	5605	Front oil seal - Trans				1	40
3/15/77	5605	Rear Hub oil seal				1	50
3/16/77	5605	Rear oil seal - Trans				3	88
9/24/77	5605	oil Tank Breather +		choke cable		3	88
7/24/77	5605	install down draft carb. + manifold					
		change dist. cap + install new plug wire					
		Fabricate Down Rod		carb. To hard clean valve			
9/4/80	7480	New AXle + Bearings				11	82
4/25/81	7668	New Battery				31	49
3/20/84	8854	Replace Differential		assy - installed 5/26/84 -		100	23
5/31/84	8854	Replace Speedometer		with used unit - 8661 on speedometer		10	00
5/26/84	8854	New Rear Brake		shoes		10	95
5/25/84	9521	New oil line to		Pressure gage + fittings		5	81
6/14/85	9657	New Battery				36	79
2/12/92	10045	New Battery			Quality	26	49
2/17/92	10045	4 Champion N5C		spark plugs	Mastersons	5	47
4-1-92	10061	New Right Rear		Brake cyl. Kit	T+S	8	80
4-1-92	10061	New clutch slave		cyl. Kit	T+S	4	00
12-14-92	10732	Repair leak in rear Axle		Replace Diff. gskt		1	86
12-15-92	10732	weld gusset plate on rear axle		top + braces on wishbone	bracket		
8-6-93	10744	New Brake	Light switch	2 wire		4	06
8-24-93	10893	New Water Pump		8-73 1/2" 1100 only	912 mi. No Ford	28	45

PREPARED BY ACCESS

TRIP DIARY

[illegible]

Tire Mileage

Tire Mileage

	TIRE (BRAND)	TUBE (BRAND)	DATE INSTALLED	SPEEDOMETER READING	DATE REMOVED	SPEEDOMETER READING	MILES IN OPERATION	COST	TAX
RIGHT FRONT	Bridge Stone		1/6/73	0	3/20/73	8857	8857	?	
LEFT FRONT	"		"	0	3/20/73	8857	Renewed		
RIGHT REAR	"		"	0	3/20/73	8857	For		
LEFT REAR	"		"	0	3/20/73	8857	Pinto		
SPARE	"		"	0	3/20/73	8857	0		
RIGHT FRONT	Goodyear Blue Streak		3/26/83	8857	4/21/83	8661	1 yr	Taken	
LEFT FRONT	Racing Tires		3/26/83	8857	4/21/83	8661	Auto	off	
RIGHT REAR	"	"	3/26/83	8857	4/21/83	8661	Crossing	ELVA	
LEFT REAR	"	"	3/26/83	8857	4/21/83	8661	"	MK II	
SPARE									
RIGHT FRONT	Pirelli		6/25/84	8661				33 84	4 03
LEFT FRONT	Cinturato		6/25/84	8661				33 84	4 03
RIGHT REAR	Pirelli		6/25/84	8661				33 84	4 03
LEFT REAR	Cinturato		6/25/84	8661				33 84	4 03
SPARE	Bridgestone		1/6/73	0					
RIGHT FRONT									
LEFT FRONT									
RIGHT REAR									
LEFT REAR									
SPARE									

GAS AND OIL
LUBRICATION
REPAIRS & ACCESS.
TIRE MILEAGE

TRIP DIARY

Memoranda

Purchase Price of Lotus 7
\$1500.00 Aug. 1972

Restored winter
1972-1973

Restoration cost. \$502.85
~~\$450.00~~

1600 cc crossflow eng.
conversion - 1974 \$234.00
Dry sump conversion - 1975 \$175.00
409.00
502.85
911.85