Lola T140 #10

Major Maintenance Record

2018	New ring and pinion setup by PDR Engineering Phil Denny (2015 ring and pinion failed because of loose nut) New front lower A arms New Jongbloed wheels
2015	Crack check front and rear uprights - Gary Arentz Crack check rear stub axles and suspension parts - Motor Warehouse Overhaul Engine Boutry's Engine - Dick Boutry New Aluminum Radiator Strip and Paint Frame with Awl Grip marine paint Paint car Black with decals to match original 1968 Poster
2014	New ring and pinion setup by PRD Engineering – Phil Denny
2013	Crack check and coat 2 Lola front wheels – Gary Arentz
2012	Overhaul and Dyno Koni shocks - Performance Shock
2010	Crack check front and rear uprights – Gary Arentz
2005	Crack check and coat front and rear uprights, and front and rear wheels – Gary Arentz Crack check all other suspension parts – Comptech Racing New core in original brass radiator