



3849 Stephens Court, Suite B • Tucker, GA 30084
 770-938-0908 • Fax 770-938-0915
 www.oldworldmotorcars.com
 oldworld@speedfactory.net

CUSTOMER NAME, ADDRESS, ZIP CODE

DATE 8/12/02 1028
 VEHICLE IDENTIFICATION NUMBER 14945 DISPATCH NO

WRITTEN BY [Signature] MILEAGE 57936 LICENSE NO 365-6TC4
 ORIGINAL ESTIMATE \$ MAKE FERRARI
 NUMBER CALLED TIME BY ADDITIONAL AUTH. AMT YEAR 72 MODEL 365-6TC4
 RES. PHONE BUS. PHONE TIME RECEIVED TIME PROMISED

QTY	P / NUMBER /	C	DESCRIPTION	PRICE	#TIME UNITS	DESCRIPTION	AMOUNT	
24	95691532 A		BRK.CAL.KITS	15100	①	REMOVE LEAKING SELF-LEVELLING UNITS SEND OUT FOR REBUILD. REINSTALL		
40	101637		PINION SEAL	5050		INSTALL KONI DICALS.		
24	95691532 A		BRK.CAL.KITS	15100				
40	101637		PINION SEAL	5050				
52	125076		OIL SEAL	4604	②	CK. BRAKES - L.R. LOCKING UP - REMOVE ROAR CALIPERS - FROZEN & LEAKING. REBUILD. REPL. REAR HOSES. BLEED ANTIREB SYSTEM		
30	131251		DIFF. MOUNT	14912				
99			CV JOINT GEAR	598				
72	101393		BRAKE HOSES	27200	③	CK. FOR OIL LEAKS - DIFF. LEAKING. REMOVE DIFF. FOR ACCESS TO PINION SEAL. REPLACE PINION SEAL + OUTPUT FLANGE SEALS REPLACE WORN OUT MOUNTS. REPL. FLUID.		
4	NPN 2.75		SMNT. BR. FL.	21.80				
7	NPN 2.80		GEAR OIL	11.90				
					④	REMOVE LEFT REAR ROTOR, CLEAN + CHECK EMERG. BRK. SHOES - OIL - CLEAN DRUM + RE-PAIN, INSTALL + ADJ. BOTH SIDES REAR BRAKES, ROAD TEST. CLEAN CAR.		
SUBLET						REBUILD SELF-LEVELLING UNITS	\$1400.00	
NOTES:							LABOR	1725.00
							PARTS	708.34
							OTHER SHOP	
							SUBLET	1400.00
							SHOP SUPPLIES	54.00
							FRIGHT	55.00
							SUB TOTAL	
							TAX	53.36
							PAY THIS AMOUNT	3995.70

DISCLAIMER OF WARRANTIES
 THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

I hereby authorize the following repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.
 NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

X _____
 CUSTOMER ACKNOWLEDGEMENT



Invoice

Date	Invoice #
5/22/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

Item	Quantity	Description	Rate	Amount
Service Labor	4.44	Inspected vehicle for concerns raised by customer. Checked and set tire pressure, all pressures were incorrect. Repaired left brake light socket. Replaced right tag light bulb. Glued carpet at passenger floor. Glued hood pad. Power steering reservoir found empty, topped off with fluid. Hood struts do not hold hood properly.	110.00	488.40
Service Labor	4.3	Put car on lift. Adjusted clutch, found clutch to be in need of replacement. Checked for oil leaks. Oil line at radiator right side found leaking. Power steering system found to be leaking. Removed all wheels. Checked brakes - removed all brake calipers and pads, checked caliper pistons and hoses. No brake fluid at all coming through front hoses, rear hoses show deterioration. All 4 calipers need to be rebuilt. Needs all new hoses front and rear and front pads. Noted that front wheel bearing seals need to be replaced.	110.00	473.00
Service Labor	6.95	Disassembled front brake calipers - found 2 stuck pistons, removed same after soaking. Cleaned, glass beaded, prepped and painted front caliper halves. Disassembled rear calipers, removed pistons. Cleaned, glass beaded, prepped and painted rear caliper halves. Polished all brake caliper pistons.	110.00	764.50

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

Subtotal

Sales Tax (7.0%)

Total

Payments/Credits

Balance Due

E-mail

michael@owmga.com

Page 1



Invoice

Date	Invoice #
5/22/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

Item	Quantity	Description	Rate	Amount
Service Labor	7.7	Cleaned and painted all hardware for calipers. Assembled all 4 calipers with new seals and freshly polished pistons. Rebuilt calipers are ready to install on car. Installed all new rear brake hoses.	110.00	847.00
Service Labor	2.56	Cleaned rear brake pads for re-use. Installed pads and rebuilt calipers using proper hardware. Connected new brake lines to rebuilt calipers. Removed both front hubs. Remove seals & bearings. Clean out old grease. Removed bearing races. Source and ordered new bearings.	110.00	281.60
Service Labor	5.25	Installed new bearings in front hubs and packed with fresh grease. Installed hubs on car and adjusted wheel bearing play. Removed all front brake hoses and installed new ones. Installed new front brake pads with rebuilt calipers using proper hardware. Bled brakes, topped off brake fluid. Wiped down calipers.	110.00	577.50

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

E-mail
michael@owmga.com

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due



Invoice

Date	Invoice #
5/22/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

Item	Quantity	Description	Rate	Amount
Service Labor	8.51	Conducted starter draw test. Checked electrical system. Starter operating very slowly. Noted that battery terminals are getting very hot. Found battery cables loose at battery and at grounding point. Found cable at starter to be loose as well as found that the connector eyelet was not soldered on, but just crimped. Cleaned battery terminals and clamps. Charged battery, fabricated new positive battery cable and install. Installed battery minus spacer at bottom of battery and modified hold down bracket to hold battery more securely. Installed battery cables. Checked starter operation, starter now operating normally. Bled brakes again after running engine, topped off fluid level.	110.00	936.10
Service Labor	0.65	Removed power steering fluid from reservoir. Removed leaking reservoir hose for replacement.	110.00	71.50

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

Subtotal

Sales Tax (7.0%)

Total

Payments/Credits

Balance Due

E-mail

michael@owmga.com

Page 3



Invoice

Date	Invoice #
5/22/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

Item	Quantity	Description	Rate	Amount
Service Labor	7.09	Began removal of components necessary to replace clutch, pressure plate, release bearing, and rear main engine seal. Removed fuel pumps for clearance/access. Lifted center console panel for access to shifter. Removed shift lever from gearbox. Disconnected torque tube from gearbox. Disconnected half shafts. Removed differential from car. Unbolted bell housing, moved gearbox back. Removed pressure plate bolts. Slid pressure plate and disc into bell housing. Removed gearbox.	110.00	779.90
95691531	2	Front Caliper Kit for GTC4	83.30	166.60T
95691532	2	Rear Caliper Kit for GTC4	85.40	170.80T
101393	8	Brake Hose Front	63.24	505.92T
GI-GPX152	1	Front Brake Pad Set for GTC4	42.36	42.36T
Freight	1	Freight	6.67	6.67T
95699013	16	Caliper Joint Seal	4.80	76.80T
147642	1	Deist Base Gasket	3.00	3.00T
101219	2	Hub Seal Front 4872/7	27.06	54.12T
LM48548	2	Bearing	16.49	32.98T
LM48510	2	Bearing	8.09	16.18T
BR12580	2	Bearing	38.54	77.08T
BR12520	2	Bearing	16.49	32.98T
785909	2	Battery Cable	6.44	12.88T

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

Subtotal

Sales Tax (7.0%)

Total

Payments/Credits

Balance Due

E-mail

michael@owmga.com

Page 4



Invoice

Date	Invoice #
5/22/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

Item	Quantity	Description	Rate	Amount
100347	1	Oil Line	232.26	232.26T
106779	1	Shaft Seal	77.58	77.58T
101615	1	O-Ring Seal	2.78	2.78T
138391	1	Rear, Main Seal V12	87.90	87.90T
101297	1	Berg, S/R Ball, Alu15	19.60	19.60T
Service Labor	3.51	Cleaned transmission thoroughly. Removed all grease & clutch dust. Removed ear on right side. Cleaned power steering fluid reservoir. Washed off excess power steering fluid from leaks. Installed new power steering hoses and reinstalled reservoir.	110.00	386.10
H-138	2	FL Hose	2.54	5.08T
Service Labor	3.33	Removed release bearing and fork from bell housing. Pressed bearing off of collar. Cleaned all parts, freed adjusting rods, which were stuck. Removed flywheel. Cleaned bell housing. Removed and replaced crank seal. Cleaned and resurfaced flywheel for best operation with new clutch disc. Repainted timing marks which were worn off. Installed flywheel. Replaced oil line from radiator to thermostat.	110.00	366.30

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due

E-mail
michael@owmga.com



Invoice

Date	Invoice #
5/22/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

Item	Quantity	Description	Rate	Amount
Service Labor	1.92	Drained out all old oil. Installed new oil filters and filled engine with 19 quarts of Valvoline 20W50 motor oil. Bolted fuel pumps in place and grounded properly. Ran engine and checked for leaks. Checked oil level after running. Touched up paint on underside of chassis. Replaced input shaft seal and cleaned throw out bearing collar. Reinstalled collar with new 'o' ring and seal.	110.00	211.20

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

Subtotal	\$7,806.67
Sales Tax (7.0%)	\$113.65
Total	\$7,920.32
Payments/Credits	\$0.00
Balance Due	\$7,920.32

E-mail
michael@owmga.com



Invoice

Date	Invoice #
6/11/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Item	Quantity	Description	Rate	Amount
Service Labor	4.44	Inspected vehicle for concerns raised by customer. Checked and set tire pressure, all pressures were incorrect. Repaired left brake light socket. Replaced right tag light bulb. Glued carpet at passenger floor. Glued hood pad. Power steering reservoir found empty, topped off with fluid. Hood struts do not hold hood properly.	110.00	488.40
Service Labor	4.3	Put car on lift. Adjusted clutch, found clutch to be in need of replacement. Checked for oil leaks. Oil line at radiator right side found leaking. Power steering system found to be leaking. Removed all wheels. Checked brakes - removed all brake calipers and pads, checked caliper pistons and hoses. No brake fluid at all coming through front hoses, rear hoses show deterioration. All 4 calipers need to be rebuilt. Needs all new hoses front and rear and front pads. Noted that front wheel bearing seals need to be replaced.	110.00	473.00
Service Labor	6.95	Disassembled front brake calipers - found 2 stuck pistons, removed same after soaking. Cleaned, glass beaded, prepped and painted front caliper halves. Disassembled rear calipers, removed pistons. Cleaned, glass beaded, prepped and painted rear caliper halves. Polished all brake caliper pistons.	110.00	764.50

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

E-mail
michael@owmga.com

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due



Invoice

Date	Invoice #
6/11/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

Item	Quantity	Description	Rate	Amount
Service Labor	7.7	Cleaned and painted all hardware for calipers. Assembled all 4 calipers with new seals and freshly polished pistons. Rebuilt calipers are ready to install on car. Installed all new rear brake hoses.	110.00	847.00
Service Labor	2.56	Cleaned rear brake pads for re-use. Installed pads and rebuilt calipers using proper hardware. Connected new brake lines to rebuilt calipers. Removed both front hubs. Remove seals & bearings. Clean out old grease. Removed bearing races. Source and ordered new bearings.	110.00	281.60
Service Labor	5.25	Installed new bearings in front hubs and packed with fresh grease. Installed hubs on car and adjusted wheel bearing play. Removed all front brake hoses and installed new ones. Installed new front brake pads with rebuilt calipers using proper hardware. Bled brakes, topped off brake fluid. Wiped down calipers.	110.00	577.50

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

E-mail
michael@owmga.com

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due



Invoice

Date	Invoice #
6/11/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

Item	Quantity	Description	Rate	Amount
Service Labor	8.51	Conducted starter draw test. Checked electrical system. Starter operating very slowly. Noted that battery terminals are getting very hot. Found battery cables loose at battery and at grounding point. Found cable at starter to be loose as well as found that the connector eyelet was not soldered on, but just crimped. Cleaned battery terminals and clamps. Charged battery, fabricated new positive battery cable and install. Installed battery minus spacer at bottom of battery and modified hold down bracket to hold battery more securely. Installed battery cables. Checked starter operation, starter now operating normally. Bled brakes again after running engine, topped off fluid level.	110.00	936.10
Service Labor	0.65	Removed power steering fluid from reservoir. Removed leaking reservoir hose for replacement.	110.00	71.50

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due

E-mail
michael@owmga.com



Invoice

Date	Invoice #
6/11/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

Item	Quantity	Description	Rate	Amount
Service Labor	7.09	Began removal of components necessary to replace clutch, pressure plate, release bearing, and rear main engine seal. Removed fuel pumps for clearance/access. Lifted center console panel for access to shifter. Removed shift lever from gearbox. Disconnected torque tube from gearbox. Disconnected half shafts. Removed differential from car. Unbolted bell housing, moved gearbox back. Removed pressure plate bolts. Slid pressure plate and disc into bell housing. Removed gearbox.	110.00	779.90
95691531	2	Front Caliper Kit for GTC4	83.30	166.60T
95691532	2	Rear Caliper Kit for GTC4	85.40	170.80T
101393	8	Brake Hose Front	63.24	505.92T
GI-GPX152	1	Front Brake Pad Set for GTC4	42.36	42.36T
Freight	1	Freight	6.67	6.67T
95699013	16	Caliper Joint Seal	4.80	76.80T
147642	1	Deist Base Gasket	3.00	3.00T
101219	2	Hub Seal Front 4872/7	27.06	54.12T
LM48548	2	Bearing	16.49	32.98T
LM48510	2	Bearing	8.09	16.18T
BR12580	2	Bearing	38.54	77.08T
BR12520	2	Bearing	16.49	32.98T
785909	2	Battery Cable	6.44	12.88T

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

Subtotal

Sales Tax (7.0%)

Total

Payments/Credits

Balance Due

E-mail

michael@owmga.com



Invoice

Date	Invoice #
6/11/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

Item	Quantity	Description	Rate	Amount
100347	1	Oil Line	232.26	232.26T
106779	1	Shaft Seal	77.58	77.58T
101615	1	O-Ring Seal	2.78	2.78T
138391	1	Rear, Main Seal V12	87.90	87.90T
101297	1	Berg, S/R Ball, Aln15	19.60	19.60T
Service Labor	3.51	Cleaned transmission thoroughly. Removed all grease & clutch dust. Removed ear on right side. Cleaned power steering fluid reservoir. Washed off excess power steering fluid from leaks. Installed new power steering hoses and reinstalled reservoir.	110.00	386.10
H-138	2	F L Hose	2.54	5.08T
Service Labor	3.33	Removed release bearing and fork from bell housing. Pressed bearing off of collar. Cleaned all parts, freed adjusting rods, which were stuck. Removed flywheel. Cleaned bell housing. Removed and replaced crank seal. Cleaned and resurfaced flywheel for best operation with new clutch disc. Repainted timing marks which were worn off. Installed flywheel. Replaced oil line from radiator to thermostat.	110.00	366.30

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due

E-mail
michael@owmga.com



Invoice

Date	Invoice #
6/11/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

Item	Quantity	Description	Rate	Amount
Service Labor	1.92	Drained out all old oil. Installed new oil filters and filled engine with 19 quarts of Valvoline 20W50 motor oil. Bolted fuel pumps in place and grounded properly. Ran engine and checked for leaks. Checked oil level after running. Touched up paint on underside of chassis. Replaced input shaft seal and cleaned throw out bearing collar. Reinstalled collar with new 'o' ring and seal.	110.00	211.20
Discount		Wright Detailing	85.00	85.00
Service Labor	1.89	Discount for detailing Cleaned up new parts for installation. Checked oil level in differential. Checked leak coming from front of car. Appears to be compressor. Will have to run car and check again later.	-85.00 110.00	-85.00 207.90
Service Labor	2.69	Installed clutch disc and pressure plate. Pressed new release bearing on hub. Installed in Bellhousing. Installed gearbox in car. Connected clutch cable and adjusted clutch. Installed speedometer cable and reverse light wires. Installed shift lever and assembled center console.	110.00	295.90

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

Subtotal

Sales Tax (7.0%)

Total

Payments/Credits

Balance Due

E-mail
michael@owmga.com



Invoice

Date	Invoice #
6/11/2009	1767

3862 Stephens Ct., Suite A
Tucker, GA 30084

770-938-0908 - 770-938-0915 Fax
www.oldworldmotorcars.com

Bill To

Due Date	Vehicle Model #1	Vehicle Model #1 VIN	Mileage
5/11/2009	1971 Ferrari 365 GTC4	14945	59,710

Item	Quantity	Description	Rate	Amount
Service Labor	2.93	Installed differential and torque tube. Installed differential mounts, bolted driveshaft in place. Bolted torque tube to gearbox. Installed half shafts. Installed emergency brake cable. Reinstalled fuel pumps. Replaced one leaking fuel hose from pump to front of car. Lubed all splined hubs and knock-offs. Installed wheels and knock offs. Ran engine, checked clutch operation, working well.	110.00	322.30
Service Labor	0.5	Road tested and checked fluid levels again. Checked for running smooth at idle. Adjusted carburetors.	110.00	55.00
Service Labor	1.96	Removed 2 trim panels at passenger side of interior. Removed insulation pad, which is falling down. Cleaned off old glue, reglued carpet, reglued door seal.	110.00	215.60
Service Labor	0.32	Final Road test prior to pickup. Checked clutch and brake operation. All systems working properly. Vehicle is ready for pickup.	110.00	35.20
99101615	1	Clutch Kit	722.00	722.00T
H-177	2	Fuel Line	1.65	3.30T
NPN2.22	18	20w50 Valvoline Racing Oil	6.50	117.00T
NPN2.71	3	Brake Fluid Pint	5.45	16.35T
PH2804-1	2	Oil Filter	19.83	39.66T
Shop Supplies		Shop Supplies	47.00	47.00T

Subtotal \$9,883.88

Sales Tax (7.0%) \$178.60

Total \$10,062.48

Payments/Credits \$-7,920.32

Balance Due \$2,142.16

12 month/12,000 mile warranty on parts and labor.
Warranty valid to original purchaser only.

E-mail
michael@owmga.com

Vintage Autoworks

11/20/2013

3862 Stephens Crt.
Tucker, GA 30084

(770) 938-0908
www.Vintage-Autoworks.com

Bill To:

Invoice

Date	Invoice #
11/20/2013	856

Vehicle Year	Vehicle Make	Vehicle Model	Mileage	Licence	Vehicle VIN	
1972	Ferrari	365 GT4	59888		14945	
Description				Qty	Rate	Amount
Remove spark plug wires from plugs. Clean corrosion from contacts in wires. Remove and replace spark plugs. (Customer supplied spark plugs) Try to start engine. Still no start. Check if fuel pumps operating. Fuel is delivered to carbs. Remove one carb top and check accelerator pump operation. Pump inop. Check jets. Idle jets plugged. Had to use jet drill to open passages. Clean all carbs the same way. Put car on lift. Drain fuel from tanks.				3.29	115.00	378.35
Put five or six gallons in tanks. Add BG 44K to clean any buildup from carbs and intake. Add BG ethanol treatment and fuel drier. Drive car. Fill tanks to top. Run car and let fresh fuel and additives circulate through system. Engine runs well. Needs to have idle adjusted after running again.				2.97	115.00	341.55
Check all lights. No brake lights. Connect brake light switch wires together. Brake lights work. Remove brake light switch and clean contacts and test with ohm meter. Install switch and check operation with pedal. OK.				1.08	115.00	124.20
BG 44K				1	24.99	24.99T
BG Fuel System Treatment				1	26.99	26.99T
Fuel				25.81	3.78	97.56T
Shop Supplies				1	14.17	14.17T
DeKalb County Tax					7.00%	11.46

Please make checks payable to: Vintage Autoworks, Inc.
All credit cards accepted.

Payments/Credits:	\$-1,019.27
Balance Due:	\$0.00