

INVOICE

Invoice #: 36499

Tag #: T968

PORSCHE OF MONTEREY #184

1781 DEL MONTE BLVD.

SEASIDE, CA 93955

PHONE: (831) 899-8888

FAX: (831) 583-6262

EPA # CAL000314156 BAR # ARD00247143



PORSCHE

vice Advisor: 92520 JOHN FRITZ

COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN	MILEAGE OUT	
BLUE	11	PORSCHE 911		WPOCB2A95BS795568			279	280	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN11			WAIT 24APR13		0.00	CASH	24APR13	24APR13	24APR13

OPTIONS: ENG:3.8 Liter

porscheofmontereycares.com

[877] 896-9147

We Sell Tires

Does Your Porsche
Need A Spa Day?Call To Set Up Your
Appointment Today!ALL PARTS ARE NEW UNLESS
OTHERWISE INDICATED.

If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request. If you choose to save replaced parts, please note that a core charge may apply.

☐ Some Parts Not Returnable

ARBITRATION AGREEMENT

Any dispute between customer and the dealership arising from or related to this vehicle or this transaction will be settled by mandatory and binding arbitration pursuant to the Federal Arbitration Act 9 U.S.C. § 1 et. seq. The arbitration shall be conducted by a single arbitrator. The arbitrator may grant whatever relief the parties may be entitled to at law or in equity.

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A PERFORM LUBE, OIL, AND FILTER SERVICE WITH COURTESY INSPECTION

LOF PERFORM LUBE, OIL, AND FILTER SERVICE WITH

COURTESY INSPECTION

96465 CPM

1 900-123-106-30 ALUM SEAL RING

1 948-107-222-00 OIL-FILTER INSERT

1 948-107-322-00 O-RING

9 0W40SYN 0W40SYN OIL

PARTS: 121.82 LABOR: 131.54 OTHER: 0.00 TOTAL LINE A:

279 COMPLETED OIL SERVICE. RESET MAINTENANCE INTERVAL REMINDER.

B PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF

VEHICLE, TIRE TREAD DEPTH, AND SET TIRE PRESSURE TO

SPEC'S (LF RF LR RR).

VI PERFORM COURTESY VEHICLE INSPECTION. INCLUDES:

VISUAL INSPECTION OF VEHICLE, TIRE TREAD

DEPTH, AND SET TIRE PRESSURE TO

SPEC'S (LF RF LR RR).

96465 IPM

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B:

279 TYRE PRESSURES SET TO 36 PSI FRONT AND 44 PSI REAR. FOR

ADDITIONAL INFORMATION PLEASE SEE ATTACHED VEHICLE INSPECTION SHEET.

YOU MAY RECEIVE A SATISFACTION SURVEY BY PHONE OR MAIL. IF YOU'RE UNABLE TO ANSWER COMPLETELY SATISFIED TO ALL THE QUESTIONS, PLEASE CONTACT OUR SERVICE MANAGER. YOUR SATISFACTION IS OUR #1 GOAL! THANK YOU FOR COMING TO LITHIA PORSCHE OF SEASIDE! BAR-AC247143 EPA # CAL000314156

(N/C)
0.00

Porsche of Monterey

☐ Tire pressure check/inflation service was performed.
RF psi LF psi RR psi LR psi
☐ Customer declined tire pressure check/inflation service.

Initials

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:
-----------------------------------	----------------------------------	--------------	-------------	----------------------------

\$	\$			<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)
----	----	--	--	-------------------------------------------------------------------------------------------------------------------------------------

Revised Estimate	\$			<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)
------------------	----	--	--	-------------------------------------------------------------------------------------------------------------------------------------

\$	\$			
----	----	--	--	--

DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE
------	--------------------	------------------------------------------------

*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal law.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received for had the opportunity to inspect any replaced parts as requested by you.

LABOR AMOUNT	131.54
PARTS AMOUNT	121.82
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
WASTE DISPOSAL COSTS*	0.00
TOTAL CHARGES	253.36
LESS INS/DED/DIS	0.00
SALES TAX	10.35
PLEASE PAY THIS AMOUNT	263.71

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

THANK YOU!



PORSCHE

The Porsche Multi-Point Inspection Report

The Porsche Multi-Point Inspection Report is a series of thorough vehicle "health checks" performed by factory-trained Porsche technicians. It is designed to keep your Porsche operating in top condition and to minimize your chances of being inconvenienced on the road. If additional service is recommended on any listed item, your Porsche Service Advisor will be happy to speak with you about your options.

Cu:

RO:

Mileage

Year/Model

VIN

Engine Size

Date

Checked and Okay at this Time

May Require Future Attention

Requires Immediate Attention

Check Fluid Levels and Fill

OK FILL

OK FILL

- | | |
|----------------------------------------------------------------------------|----------------------------------------------------------------|
| <input checked="" type="checkbox"/> Engine Oil | <input checked="" type="checkbox"/> Brake Reservoir |
| <input checked="" type="checkbox"/> Windshield Washer | <input checked="" type="checkbox"/> Headlamp Washer |
| <input checked="" type="checkbox"/> Power Steering | <input checked="" type="checkbox"/> Coolant Recovery Reservoir |
| <input checked="" type="checkbox"/> Transmission (if equipped w/ dipstick) | |

Check Following Systems / Components

- | | | |
|-------------------------------------|-------------------------------------|------------------------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Visually inspect headlamp alignment |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Windshield washer spray, wiper operation and wiper blades |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Windshield cracks and/or chips |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Heating, ventilation and air conditioning check |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Engine air cleaner filter |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Oil and/or fluid leaks |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Constant velocity (CV) drive axle boots (if equipped) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Exhaust system (leaks, damage, loose parts) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Steering and steering linkages |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Shocks/struts, air suspension and other suspension components for leaks and/or damage |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Brake system (including lines, hoses and parking brake) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Engine cooling system, hoses and clamps |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Radiator, heater and air conditioning hoses for leaks / damage |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Accessory drive belt(s) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Clutch operation (if equipped) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | State inspection due (if applicable) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Your last completed maintenance |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Your next factory scheduled maintenance is due at |

Month / Day / Year

Mileage : 4 / 13

Mileage : 4 / 14

Comments:

2011 Speedster

3.8L

4-24-13

280

Check Battery Condition

Good
Comments:

Recharge


Bad

Check Brakes

Measure Front / Rear Brake Linings

RF

RR



LF

LR

Over 5mm or 7/32"

3 to 5mm or 4/32" to 7/32"

Less than 3mm or 4/32"

Brake Measurements Not Taken This Service Visit

Comments:

Check Tires

TREAD DEPTH

LF

- ☒ 7/32" or Greater
- ☒ 4/32" to 6/32"
- ☒ 3/32" or Less

- ☒ 7/32" or Greater
- ☒ 4/32" to 6/32"
- ☒ 3/32" or Less

LR

RF

- ☒ 7/32" or Greater
- ☒ 4/32" to 6/32"
- ☒ 3/32" or Less

- ☒ 7/32" or Greater
- ☒ 4/32" to 6/32"
- ☒ 3/32" or Less

RR



- | | | | |
|----------------------------------------|-----------------------|----|-------------------------------------|
| <input checked="" type="checkbox"/> LF | Wear Pattern / Damage | RF | <input checked="" type="checkbox"/> |
| <input checked="" type="checkbox"/> LR | Tire Wear Indicators | RR | <input checked="" type="checkbox"/> |

Alignment Check Recommended Wheel Balance Recommended

Comments:

This Courtesy Inspection is performed by Your Porsche Service Team

Service Advisor:

Technician:

Customer Signature:

PNA 000 012 ed. 05/08

Tire Pressure Set to

Factory Recommendations

PSI 36 Front 44 Rear

INVOICE

Invoice #: 39492

Tag #: T159

PORSCHE OF MONTEREY #184



PORSCHE

1781 DEL MONTE BLVD.

SEASIDE, CA 93955

PHONE: (831) 899-8888

FAX: (831) 583-6262

EPA # CAL000314156 BAR # ARD00247143

Service Advisor: 92520 JOHN FRITZ

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE	MILEAGE IN	MILEAGE OUT
BLUE	11	PORSCHE 911			WPOCB2A95BS795568			622	622
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN11			WAIT 12SEP14		0.00	CASH	12SEP14	12SEP14	12SEP14

OPTIONS: ENG:3.8 Liter

porscheofmontereycares.com
[877] 896-9147

We Sell Tires



Does Your Porsche Need A Spa Day?



Call To Set Up Your Appointment Today!

ALL PARTS ARE NEW UNLESS
OTHERWISE INDICATED.

If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request. If you choose to save replaced parts, please note that a core charge may apply.

☐ Some Parts Not Returnable

ARBITRATION AGREEMENT

Any dispute between customer and the dealership arising from or related to this vehicle or this transaction will be settled by mandatory and binding arbitration pursuant to the Federal Arbitration Act 9 U.S.C. § 1 et. seq. The arbitration shall be conducted by a single arbitrator. The arbitrator may grant whatever relief the parties may be entitled to at law or in equity.

LINE OPCODE TECH TYPE HOURS

A PERFORM LUBE, OIL, AND FILTER SERVICE WITH COURTESY INSPECTION

LOF PERFORM LUBE, OIL, AND FILTER SERVICE WITH

COURTESY INSPECTION

96465 CPM

1 948-107-222-00 OIL-FILTER INSERT

1 948-107-322-00 O-RING

1 900-123-106-30 ALUM SEAL RING

9 0W40SYN 0W40SYN OIL

PARTS: 117.09 LABOR: 135.96 OTHER: 0.00 TOTAL LINE A: 253.05

622 COMPLETED OIL SERVICE. RESET SERVICE INTERVAL REMINDER.

B PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF

VEHICLE, TIRE TREAD DEPTH, AND SET TIRE PRESSURE TO

SPEC'S (LF RF LR RR)

VI PERFORM COURTESY VEHICLE INSPECTION. INCLUDES:

VISUAL INSPECTION OF VEHICLE, TIRE TREAD

DEPTH, AND SET TIRE PRESSURE TO

SPEC'S (LF RF LR RR)

96465 IPM

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B:

622 PLEASE SEE ATTACHED INSPECTION REPORT. FRONT TIRE PRESSURES SET TO 36 PSI, REARS TO 40 PSI.

EST: 275.00

12SEP14 07:53 SA: 92520

YOU MAY RECEIVE A SATISFACTION SURVEY BY PHONE OR MAIL. IF YOU'RE UNABLE TO ANSWER COMPLETELY SATISFIED TO ALL THE QUESTIONS, PLEASE CONTACT OUR SERVICE MANAGER. YOUR SATISFACTION IS OUR #1 GOAL! THANK YOU FOR COMING TO LITHIA PORSCHE OF SEASIDE! BAR-AC247143 EPA # CAL000314156

PAID

SEP 12 2014

PORSCHE OF MONTEREY

(N/C)
0.00

<input type="checkbox"/> Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi <input type="checkbox"/> Customer declined tire pressure check/inflation service.					Initials _____
Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:	
				<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)	
Revised Estimate				<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)	

DATE

CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal law.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received for had the opportunity to inspect any replaced parts as requested by you.

LABOR AMOUNT	135.96
PARTS AMOUNT	117.09
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
WASTE DISPOSAL COSTS*	0.00
TOTAL CHARGES	253.05
LESS INS/DED/DIS	0.00
SALES TAX	9.95
PLEASE PAY THIS AMOUNT	263.00

INVOICE

Invoice #: 39930

Tag #: T489

PORSCHÉ OF MONTEREY #184

1781 DEL MONTE BLVD.

SEASIDE, CA 93955

PHONE: (831) 899-8888

FAX: (831) 583-6262

EPA # CAL000314156 BAR # ARD00247143



Service Advisor: 92520 JOHN FRITZ

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE	MILEAGE IN	MILEAGE OUT
BLUE	11	PORSCHE 911			WPOCB2A95BS795568			645	645
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN11			WAIT 01DEC14		0.00	CASH	01DEC14	01DEC14	01DEC14

OPTIONS: ENG:3.8 Liter

porscheofmontereycares.com
[877] 896-9147

We Sell Tires



Does Your Porsche Need A Spa Day?



Call To Set Up Your Appointment Today!

ALL PARTS ARE NEW UNLESS
OTHERWISE INDICATED.

If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request. If you choose to save replaced parts, please note that a core charge may apply.

☐ Some Parts Not Returnable

ARBITRATION AGREEMENT
Any dispute between customer and the dealership arising from or related to this vehicle or this transaction will be settled by mandatory and binding arbitration pursuant to the Federal Arbitration Act 9 U.S.C. § 1 et. seq. The arbitration shall be conducted by a single arbitrator. The arbitrator may grant whatever relief the parties may be entitled to at law or in equity.

LINE OPCODE TECH TYPE HOURS

A CUSTOMER REPORTS OIL LEAKING FROM ENGINE. INSPECT AND REPORT.
ENG ENGINE & RELATED REPAIRS

96465 WP4
3 900-385-019-01 TORX SCREW 6X20
1 999-701-504-40 O-RING
1 999-701-505-40 O-RING

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A:
645 VERIFIED CONCERN. CREATED V.A.L. FOUND OIL LEAKING FROM THE
VACUUM PUMP ON THE PASSENGERS SIDE OF THE ENGINE. REMOVED PUMP AND
INSPECTED FOR PHYSICAL DAMAGE. NONE FOUND. REPLACED BOTH O RINGS. NO
OIL LEAKS FOUND AFTER REPAIR.

(N/C)
(N/C)
(N/C)
(N/C)

0.00

B PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF
VEHICLE, TIRE TREAD DEPTH, AND SET TIRE PRESSURE TO

SPEC'S (LF RF LR RR).
VI PERFORM COURTESY VEHICLE INSPECTION. INCLUDES:
VISUAL INSPECTION OF VEHICLE, TIRE TREAD
DEPTH, AND SET TIRE PRESSURE TO
SPEC'S (LF RF LR RR).

96465 IPM
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B:
645 TYRE PRESSURES SET TO 34 PSI FRONT AND 40 PSI REAR. FOR
ADDITIONAL INFORMATION PLEASE SEE ATTACHED VEHICLE INSPECTION SHEET.

(N/C)
0.00

YOU MAY RECEIVE A SATISFACTION SURVEY BY
PHONE OR MAIL. IF YOU'RE UNABLE TO ANSWER
COMPLETELY SATISFIED TO ALL THE QUESTIONS,
PLEASE CONTACT OUR SERVICE MANAGER. YOUR
SATISFACTION IS OUR #1 GOAL! THANK YOU FOR
COMING TO LITHIA PORSCHE OF SEASIDE!
BAR-AC247143 EPA # CAL000314156

<input type="checkbox"/> Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi <input type="checkbox"/> Customer declined tire pressure check/inflation service. Initials _____				
Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:
\$	\$			<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)
Revised Estimate	\$			<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)

***HAZARDOUS WASTE DISPOSAL COSTS:** We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal law.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

DESCRIPTION	AMOUNT	TOTALS
LABOR AMOUNT	0.00	
PARTS AMOUNT	0.00	
GAS, OIL, LUBE	0.00	
SUBLET AMOUNT	0.00	
WASTE DISPOSAL COSTS*	0.00	
TOTAL CHARGES	0.00	
LESS INS/DED/DIS	0.00	
SALES TAX	0.00	
PLEASE PAY THIS AMOUNT	0.00	

INVOICE

Invoice #: 42351

Tag #: T8375

PORSCHE OF MONTEREY #184

1781 DEL MONTE BLVD.

SEASIDE, CA 93955

PHONE: (831) 899-8888

FAX: (831) 583-6262

EPA # CAL000314156 BAR # ARD00247143



Service Advisor: 171934 JAIME RODRIGUEZ

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE	MILEAGE IN	MILEAGE OUT
BLUE	11	PORSCHE 911			WPOCB2A95BS795568		6UVE729	733	733
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN11			WAIT 29DEC15		0.00	CASH	29DEC15	29DEC15	29DEC15

OPTIONS: ENG:3.8_Liter

porscheofmontereycares.com
[877] 896-9147

Does your
Porsche need
a spa day?



CALL TODAY
TO SET UP YOUR APPOINTMENT!

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request. If you choose to save replaced parts, please note that a core charge may apply.

☐ Some Parts Not Returnable

ARBITRATION AGREEMENT

Any dispute between customer and the dealership arising from or related to this vehicle or this transaction will be settled by mandatory and binding arbitration pursuant to the Federal Arbitration Act 9 U.S.C. § 1 et. seq. The arbitration shall be conducted by a single arbitrator. The arbitrator may grant whatever relief the parties may be entitled to at law or in equity.

LINE OPCODE TECH TYPE HOURS

A REPLACE BATTERY

BAT REPLACE BATTERY

86383 CPR

1 999-611-080-21 BATTERY

1 ACID BATTERY ACID

PARTS: 276.76 LABOR: 149.60 OTHER: 0.00 TOTAL LINE A: 426.36

733 A NEWLY FILLED AND CHARGED 80AH BATTERY WAS INSTALLED. CHARGING SYSTEM CHECKED AND FOUND TO BE OPERATING PROPERLY.

B 10,000 MILE MINOR SERVICE, * PERFORM MAINTENANCE CHECKLIST FOR 10,000 MILE SERVICE

10K 10,000 MILE MINOR SERVICE, * PERFORM MAINTENANCE CHECKLIST FOR 10,000 MILE SERVICE

86383 CPR

1 948-107-222-00 OIL-FILTER INSERT

1 948-107-322-00 O-RING

1 900-123-106-30 ALUM SEAL RING

9 0W40SYN 0W40SYN OIL

PARTS: 118.51 LABOR: 198.47 OTHER: 0.00 TOTAL LINE B: 316.98

733 10K SERVICE COMPLETED. FLUID LEVELS WERE TOPPED OFF. THE TIRES, BRAKES, AND UNDERCARRIAGE WERE INSPECTED AND FOUND TO BE IN GOOD CONDITION. THE TIRE PRESSURES WERE SET TO SPECIFICATIONS. FAULT MEMORY OF ONBOARD COMPUTER WAS READ OUT AND THE SERVICE REMINDER WAS RESET.

C CUSTOMER STATES TPMS LIGHT CAME ON PLEASE CHECK AND ADVISE. EL ELECTRICAL & RELATED REPAIRS

86383 IPM

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: (N/C) 0.00

733 THE TIRE PRESSURES WERE 4PSI LOW. TRANSMITTER BATTERY LIFE WAS CHECKED AND ALL 4 TRANSMITTERS WERE FOUND TO HAVE 60 MONTHS BATTERY LIFE REMAINING.

D PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF

- ☐ Tire pressure check/inflation service was performed.
RF _____ psi LF _____ psi RR _____ psi LR _____ psi
☐ Customer declined tire pressure check/inflation service. Initials _____

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:
\$	\$			<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)
Revised Estimate				<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)

DATE

CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal law.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

LABOR AMOUNT

PARTS AMOUNT

GAS, OIL, LUBE

SUBLET AMOUNT

WASTE DISPOSAL COSTS*

TOTAL CHARGES

LESS INS/DED/DIS

SALES TAX

PLEASE PAY THIS AMOUNT

TOTAL

INVOICE

Invoice #: 42351

Tag #: T8375

PORSCHÉ OF MONTEREY #184

1781 DEL MONTE BLVD.

SEASIDE, CA 93955

PHONE: (831) 899-8888

FAX: (831) 583-6262

EPA # CAL000314156 BAR # ARD00247143



Service Advisor: 171934 JAIME RODRIGUEZ

PRICE ADVISOR: 171934 JAIME RODRIGUEZ										
COLOR	YEAR	MAKE/MODEL				VIN		LICENSE	MILEAGE IN	MILEAGE OUT
BLUE	11	PORSCHE 911				WPOCB2A95BS795568		6UVE729	733	733
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY	
01JAN11			WAIT 29DEC15		0.00	CASH	29DEC15	29DEC15	29DEC15	
OPTIONS: ENCLOSURE										

OPTIONS: ENG:3.8 Liter

porscheofmontereycares.com
[877] 896-9147

**Does your
Porsche need
a spa day?**



CALL TODAY
TO SET UP YOUR APPOINTMENT!

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request. If you choose to save replaced parts, please note that a core charge may apply.

☐ Some Parts Not Returnable

ARBITRATION AGREEMENT
Any dispute between customer and the dealership arising from or related to this vehicle or this transaction will be settled by mandatory and binding arbitration pursuant to the Federal Arbitration Act 9 U.S.C. § 1 et. seq. The arbitration shall be conducted by a single arbitrator. The arbitrator may grant whatever relief the parties may be entitled to at law or in equity.

LINE OPCODE TECH TYPE HOURS

VEHICLE, TIRE TREAD DEPTH, AND SET TIRE PRESSURE TO

SPEC'S (LF RF LR RR).

VI PERFORM COURTESY VEHICLE INSPECTION. INCLUDES:

VISUAL INSPECTION OF VEHICLE, TIRE TREAD

DEPTH, AND SET TIRE PRESSURE TO

SPEC'S (LF RF LR RR).

PARTS:

86383 IPM

0.00 LABOR:

0.00 OTHER:

0.00

TOTAL LINE D:

(N/C)
0.00

EST: 805.00

29DEC15 13:43 SA: 171934

YOU MAY RECEIVE A SATISFACTION SURVEY BY PHONE OR MAIL. IF YOU'RE UNABLE TO ANSWER COMPLETELY SATISFIED TO ALL THE QUESTIONS, PLEASE CONTACT OUR SERVICE MANAGER. YOUR SATISFACTION IS OUR #1 GOAL! THANK YOU FOR COMING TO LITHIA PORSCHE OF MONTEREY! BAR-AC247143 EPA # CAL000314156

PAID

DEC 29 2015

PORSCHÉ OF MONTEREY

- ☐ Tire pressure check/inflation service was performed.
RF _____ psi LF _____ psi RR _____ psi LR _____ psi
☐ Customer declined tire pressure check/inflation service.

Initials

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:
				<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)
Revised Estimate				<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)

DATE

CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

***HAZARDOUS WASTE DISPOSAL COSTS:** We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal law.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

LABOR AMOUNT	348.07
PARTS AMOUNT	395.27
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
WASTE DISPOSAL COSTS*	0.00
TOTAL CHARGES	743.34
LESS INS/DED/DIS	0.00
SALES TAX	34.09
PLEASE PAY THIS AMOUNT	777.43

INVOICE

Invoice #: 45858

Tag #: T2730

PORSCHE OF MONTEREY #184



PORSCHE

1781 DEL MONTE BLVD.
SEASIDE, CA 93955
PHONE: (831) 899-8888
FAX: (831) 583-6262
EPA # CAL000314156 BAR # ARD00247143

Service Advisor: 92520 JOHN FRITZ

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE	MILEAGE IN	MILEAGE OUT
BLUE	11	PORSCHE 911			WPOCB2A95BS795568		6UVE729	778	778
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN11			WAIT 26MAY17		0.00	CASH	26MAY17	26MAY17	26MAY17

OPTIONS: ENG:3.8_Liter

porscheofmontereycares.com
[877] 896-9147

Does your
Porsche need
a spa day?



CALL TODAY
TO SET UP YOUR APPOINTMENT!

ALL PARTS ARE NEW UNLESS
OTHERWISE INDICATED.

If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request. If you choose to have replaced parts, please note that a core charge may apply.

☐ Some Parts Not Returnable

ARBITRATION AGREEMENT

Any dispute between customer and the dealership arising from or related to this vehicle or this transaction will be settled by mandatory and binding arbitration pursuant to the Federal Arbitration Act 9 U.S.C. § 1 et. seq. The arbitration shall be conducted by a single arbitrator. The arbitrator may grant whatever relief the parties may be entitled to at law or in equity.

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	10,000	MILE	MINOR SERVICE, * PERFORM MAINTENANCE CHECKLIST FOR 10,000 MILE SERVICE				
	10K	10,000	MILE MINOR SERVICE, * PERFORM MAINTENANCE CHECKLIST FOR 10,000 MILE SERVICE				
		96465	CPM			143.76	143.76
	1	948-107-222-00	OIL-FILTER INSERT		27.34	27.34	27.34
	1	948-107-322-00	O-RING		13.79	13.79	13.79
	1	900-123-106-30	ALUM SEAL RING		2.96	2.96	2.96
	9	0W40SYN	0W40SYN OIL		8.50	8.50	76.50
PARTS:	120.59	LABOR:	143.76	OTHER:	0.00	TOTAL LINE A:	264.35
778	Completed 10,000 mile / 1 year Service.						

B	PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRE TREAD DEPTH, AND SET TIRE PRESSURE TO SPEC'S (LF RF LR RR).						
VI	PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRE TREAD DEPTH, AND SET TIRE PRESSURE TO SPEC'S (LF RF LR RR).						
	96465	IPM					(N/C)
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	0.00
778	TIRE PRESSURES SET TO 35 PSI FRONT AND 39 PSI REAR						

EST: 325.00

26MAY17 08:06 SA: 92520

YOU MAY RECEIVE A SATISFACTION SURVEY BY PHONE OR MAIL. IF YOU'RE UNABLE TO ANSWER COMPLETELY SATISFIED TO ALL THE QUESTIONS, PLEASE CONTACT OUR SERVICE MANAGER. YOUR SATISFACTION IS OUR #1 GOAL! THANK YOU FOR COMING TO LITHIA PORSCHE OF MONTEREY! BAR-AC247143 EPA # CAL000314156

<input type="checkbox"/> Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi				
<input type="checkbox"/> Customer declined tire pressure check/inflation service. Initials _____				
Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:
\$	\$			<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)
Revised Estimate	\$			<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)

*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal law.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

LABOR AMOUNT	143.76
PARTS AMOUNT	120.59
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
WASTE DISPOSAL COSTS*	0.00
TOTAL CHARGES	264.35
LESS INS/DED/DIS	0.00
SALES TAX	10.55
PLEASE PAY THIS AMOUNT	274.90

INVOICE

Invoice #: 46514

Tag #: T713

PORSCHÉ OF MONTEREY #184

1781 DEL MONTE BLVD.

SEASIDE, CA 93955

PHONE: (831) 899-8888

FAX: (831) 583-6262

EPA # CAL000314156 BAR # ARD00247143



Service Advisor: 170184 JAKOB HENDRIX

COLOR	YEAR	MAKE/MODEL		VIN		LICENSE		MILEAGE IN	MILEAGE OUT
BLUE	11	PORSCHE 911		WPOCB2A95BS795568		6UVE729		806	808
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN11			16:00 16AUG17		0.00	CASH	17AUG17	16AUG17	17AUG17

OPTIONS: ENG:3.8 Liter

porscheofmontereycares.com
[877] 896-9147

Does your
Porsche need
a spa day?



CALL TODAY
TO SET UP YOUR APPOINTMENT!

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request. If you choose to save replaced parts, please note that a core charge may apply.

☐ Some Parts Not Returnable

ARBITRATION AGREEMENT
Any dispute between customer and the dealership arising from or related to this vehicle or this transaction will be settled by mandatory and binding arbitration pursuant to the Federal Arbitration Act 9 U.S.C. § 1 et. seq. The arbitration shall be conducted by a single arbitrator. The arbitrator may grant whatever relief the parties may be entitled to at law or in equity.

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	40,000	MILE	MAJOR SERVICE, *PERFORM MAJOR SERVICE; WITH OUT PREFORMING OIL CHANGE THAT WAS RECENTLY COMPLETED REF. R.O#45858. CLIENT REQUESTS JEREMIAH TO WORK ON VEHICLE				
CAUSE:	40K	MAJOR SERVICE					
40K	40,000	MILE	MAJOR SERVICE, *PERFORM MAJOR SERVICE				
	96465	CPR				1023.65	1023.65
1	997-571-219-01	CABIN-AIR FILTER.		76.12	76.12	76.12	76.12
2	997-110-130-31	AIR FILTER		49.63	49.63	99.26	99.26
6	999-170-232-90	SPARK PLUG		39.96	39.96	239.76	239.76
1	000-043-305-52	BRAKE FLUID 1L		41.21	41.21	41.21	41.21
PARTS:	456.35	LABOR:	1023.65	OTHER:	0.00	TOTAL LINE A:	1480.00
806	PERFORMED AND COMPLETED 40K MAJOR SERVICE						

B	PERFORM	COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRE TREAD DEPTH, AND SET TIRE PRESSURE TO SPEC'S (LF RF LR RR).					
VI	PERFORM	COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRE TREAD DEPTH, AND SET TIRE PRESSURE TO SPEC'S (LF RF LR RR).					
	99999	CPR				0.00	0.00
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	0.00

PAID
AUG 17 2017
PORSCHÉ OF MONTEREY

YOU MAY RECEIVE A SATISFACTION SURVEY BY PHONE OR MAIL. IF YOU'RE UNABLE TO ANSWER COMPLETELY SATISFIED TO ALL THE QUESTIONS, PLEASE CONTACT OUR SERVICE MANAGER. YOUR SATISFACTION IS OUR #1 GOAL! THANK YOU FOR COMING TO LITHIA PORSCHE OF MONTEREY!
BAR-AC247143 EPA # CAL000314156

<input type="checkbox"/> Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi		<input type="checkbox"/> Customer declined tire pressure check/inflation service. Initials _____	
Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time
\$	\$		
Revised Estimate	\$		
DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	

***HAZARDOUS WASTE DISPOSAL COSTS:** We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal law.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

LABOR AMOUNT	1023.65
PARTS AMOUNT	456.35
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
WASTE DISPOSAL COSTS*	0.00
TOTAL CHARGES	1480.00
LESS INS/DED/DIS	0.00
SALES TAX	39.93
PLEASE PAY THIS AMOUNT	1519.93

Maintenance Checklist – Boxster/Cayman (987) & 911 Carrera/S (997) (2010-12)

Required Maintenance and Lubrication Service (USA & Canadian Vehicles Only, Not For 911 Turbo/GT3 (997), use separate checklists)

* **Oil Change** Every 10,000 miles (15,000 km) or 1 year. See Below Check Box.

☒ **Maintenance** (Labor Operation 03 16 00 ..) See Technical Manual

After 40,000, 80,000, 120,000, 180,000 miles (60,000, 120,000, 180,000, 240,000 km) etc.

Note: If the mileage for scheduled maintenance is not reached, maintenance must be performed no later than after 8, 12..... years.

The terms 'check' and 'inspection' include all necessary subsequent work such as adjusting, readjusting, correcting and topping off, but do not include repairing, replacing and reconditioning parts or assemblies.

- ☒ **Diagnosis system:** Read fault memory; reset maintenance interval/Read and record range information on R.O.
- ☒ **Change engine oil and oil filter** (Every 10,000 miles/15,000 km, see separate Oil Change Sheet, PNA 000 162 EF)
- ☒ **Vehicle underside and engine compartment:** Visual inspection for leaks (oils and fluids) and abrasion (lines and hoses); Underbody panels: visual inspection for completeness, secure installation and damage
- ☒ **Coolant hoses:** Check condition
- Radiators and air intakes:** Visual inspection for external debris and blockage
- Coolant:** Check level and antifreeze protection level
- ☒ **Air filter:** Replace filter element
- ☒ **Pollen filter:** Replace filter element
- ☒ **Fuel lines and connections:** Visual inspection for damage and leaks
- ☒ **Brake system:** Visual inspection of the brake pads and brake discs for wear
- ☒ **Parking brake:** Check free play of parking brake lever
- ☒ **Brake hoses and lines:** Visual inspection for damage, routing and corrosion
- ☒ **Steering gear:** Visual inspection of the dust boots for damage
- Tie rod ends:** Check play and dust boots
- ☒ **Axle joints:** Check play; visual inspection of the dust boots for damage. Check the screw connections of the front and rear running gear adjustment points are secure
- ☒ **Drive shafts:** Visual inspection of the dust boots for leaks and damage
- ☒ **Exhaust system:** Visual inspection for leaks and damage; check mounting and heat shields
- ☒ **Tires:** Check condition and tire pressure
- ☒ **Check firewall and cabrio section body drains** for debris
- ☒ **Check the door, lid locks and safety hook of the front lid** for secure seating and function properly
- ☒ **Seat belts:** Check function and condition
- ☒ **Vehicle lighting:** Check function
- All headlights:** Check setting
- ☒ **Horn:** Check function
- ☒ **Windshield wiper/washer system, headlight washer:** Check fluid level and nozzle settings (use winter antifreeze protection during winter months)
- ☒ **Check wiper blades**
- ☒ **Battery:** Check condition and electrolyte level
- ☒ **Electrical equipment, warning and indicator lights:** Check function

Additional maintenance for spark plugs Labor operation 03 81 00 ..

☒ Replace spark plugs every 40,000 miles (60,000 km) or every 4 years

Additional maintenance for drive belt Labor operation 03 60 00 ..

- ☒ Check drive belt at 40,000 miles (60,000 km) or every 4 years
- ☐ Check drive belt at 100,000 miles (150,000 km) or every 10 years
- ☐ Check drive belt at 160,000 miles (240,000 km) or every 16 years

Additional maintenance for convertible top Labor operation 03 70 00 ..

☒ Maintain and care for convertible top at 20,000 miles (30,000 km) or every 2 years

Additional maintenance 60,000 miles (90,000 km) or every 6 years Labor operation 03 83 00 ..

- ☐ Replace drive belt
- ☐ Change all-wheel drive controller oil – 911 Carrera 4 – 4-wheel drive models
- ☐ PDK transmission: Change clutch oil

~~**Additional maintenance every 120,000 miles (180,000 km) or 12 years** Labor operation 03 88 00 ..~~

- ~~☐ Change manual transmission oil~~
- ~~☐ Change PDK transmission oil~~
- ~~☐ Change front differential oil – 911 Carrera 4 – 4-wheel drive models only~~

Every 2 years

☒ Change brake fluid

Every 4 years

☐ Replace tire sealant


After 4, then every 2 years

☒ Check battery for the tire pressure monitoring system

~~After 4, 8, 10, then every 2 years~~

☐ Inspect airbag system

☒ Assembly and running gear mounts: Visual inspection of all rubber/hydraulic mounts for damage

Inspection Performed - Technician Signature: 

Road Test Check

☒ Remote control, front seats, foot brake and parking brake (also operating travel), engine, clutch, steering, transmission, ParkAssist, automatic speed control, PSM switch, PASM switch, Sport switch, heater, air-conditioning system and instruments: Check operation

☒ Oils, fluids: Visual inspection for leaks

Road Test Performed - Technician Signature: 

Customer Name: _____

Date: 8/17/17

VIN: WPO CG2A15B5745518


Mileage (check one) ☒ Miles ☐ Kilometers: 806

Dealer Name: Porsche of Monterey

Dealer Code: 152

Repair Order #: 46514

Technician Name: Jeremiah Lane

Technician Signature: 

INVOICE

Invoice #: 50144

Tag #: T560

PORSCHE MONTEREY #184

1781 DEL MONTE BLVD.

SEASIDE, CA 93955

PHONE: (831) 899-8888

FAX: (831) 583-6262

EPA # CAL000314156 BAR # ARD00247143



vice Advisor: 170184 JAKOB HENDRIX

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE	MILEAGE IN	MILEAGE OUT
BLUE	11	PORSCHE 911			WPOCB2A95BS795568		6UVE729	931	932
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN11			WAIT 08OCT18		0.00	CASH	08OCT18	08OCT18	08OCT18

OPTIONS: ENG:3.8 Liter

porscheofmontereycares.com
[877] 896-9147

**Does your
Porsche need
a spa day?**



**CALL TODAY
TO SET UP YOUR APPOINTMENT!**

ALL PARTS ARE NEW UNLESS
OTHERWISE INDICATED.

If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request. If you choose to save replaced parts, please note that a core charge may apply.

☐ Some Parts Not Returnable

ARBITRATION AGREEMENT
Any dispute between customer and the dealership arising from or related to this vehicle or this transaction will be settled by mandatory and binding arbitration pursuant to the Federal Arbitration Act 9 U.S.C. § 1 et. seq. The arbitration shall be conducted by a single arbitrator. The arbitrator may grant whatever relief the parties may be entitled to at law or in equity.

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	PERFORM	LUBE, OIL, AND FILTER SERVICE WITH COURTESY INSPECTION					
	LOF	PERFORM LUBE, OIL, AND FILTER SERVICE WITH COURTESY INSPECTION					
		96465 CPR			195.97	195.97	
	1	948-107-222-00 OIL-FILTER INSERT		25.33	25.33	25.33	
	1	948-107-322-00 O-RING		13.77	13.77	13.77	
	9	0W40SYN 0W40SYN OIL		9.65	9.65	86.85	
	1	900-123-106-30 ALUM SEAL RING		3.08	3.08	3.08	
PARTS:	129.03	LABOR:	195.97	OTHER:	0.00	TOTAL LINE A:	325.00
931 Completed 10,000 mile / 1 year Service. For additional information please see attached inspection sheet.							

B	PERFORM	COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRE TREAD DEPTH, AND SET TIRE PRESSURE TO SPEC'S (LF RF LR RR).					
VI	PERFORM	COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRE TREAD DEPTH, AND SET TIRE PRESSURE TO SPEC'S (LF RF LR RR).					
		96465 CPR			0.00	0.00	
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	0.00
931 TIRE PRESSURES SET TO 35 PSI FRONT AND 39 PSI REAR							

C	CLIENT REQUESTS	JEREMIAH TO WORK ON VEHICLE					
	00	MAINTENANCE					
		96465 CPR			0.00	0.00	
	1	WAP-424-244-0K SOCKS HASHTAG UNISEX		27.00	27.00	27.00	
PARTS:	27.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE C:	27.00

D	CLIENT STATES	TRIM PIECE FOR CENTER DASH VENT ABOVE PCM CAME OFF;					
		PARTS IN STORGAE UNDER PCM					
	00	MAINTENANCE					
		96465 CPR			35.00	35.00	
PARTS:	0.00	LABOR:	35.00	OTHER:	0.00	TOTAL LINE D:	35.00

<input type="checkbox"/> Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi				Initials _____
<input type="checkbox"/> Customer declined tire pressure check/inflation service.				
Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:
				<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)
Revised Estimate				<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)

***HAZARDOUS WASTE DISPOSAL COSTS:** We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal law.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	WASTE DISPOSAL COSTS*	TOTAL CHARGES	LESS INS/DED/DIS	SALES TAX	PLEASE PAY THIS AMOUNT

DATE CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

INVOICE

Invoice #: 50144

Tag #: T560

PORSCHÉ MONTEREY #184

1781 DEL MONTE BLVD.

SEASIDE, CA 93955

PHONE: (831) 899-8888

FAX: (831) 583-6262

EPA # CAL000314156 BAR # ARD00247143



Service Advisor: 170184 JAKOB HENDRIX

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE	MILEAGE IN	MILEAGE OUT
BLUE	11	PORSCHE 911			WPOCB2A95BS795568		6UVE729	931	932
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN11			WAIT 08OCT18		0.00	CASH	08OCT18	08OCT18	08OCT18

OPTIONS: ENG:3.8 Liter

porscheofmontereycares.com
[877] 896-9147

**Does your
Porsche need
a spa day?**



**CALL TODAY
TO SET UP YOUR APPOINTMENT!**

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request. If you choose to save replaced parts, please note that a core charge may apply.

Some Parts Not Returnable

ARBITRATION AGREEMENT
Any dispute between customer and the dealership arising from or related to this vehicle or this transaction will be settled by mandatory and binding arbitration pursuant to the Federal Arbitration Act 9 U.S.C § 1 et. seq. The arbitration shall be conducted by a single arbitrator. The arbitrator may grant whatever relief the parties may be entitled to at law or in equity.

LINE OPCODE TECH TYPE HOURS

931 Removed the center vent and clipped vent adjuster back together. No damage the adjuster. The vent is function properly at this time.

EST: 325.00

08OCT18 12:46 SA: 170184

YOUR SATISFACTION IS OUR #1 GOAL! PLEASE
CONTACT OUR SERVICE MANAGER WITH ANY CONCERNS
YOU ENCOUNTER. YOU MAY RECEIVE A SURVEY BY
PHONE OR MAIL. THANK YOU VERY MUCH FOR YOUR
BUSINESS AND COMING TO PORSCHE OF MONTEREY!
BAR-AC247143 EPA# CAL00314156

PAID

OCT 08 2018

PORSCHÉ MONTEREY

<input type="checkbox"/> Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi <input type="checkbox"/> Customer declined tire pressure check/inflation service. Initials _____				
Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:
\$	\$			<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)
Revised Estimate				<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)

DATE

CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

***HAZARDOUS WASTE DISPOSAL COSTS:** We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal law.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

LABOR AMOUNT	230.97
PARTS AMOUNT	156.03
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
WASTE DISPOSAL COSTS*	0.00
TOTAL CHARGES	387.00
LESS INS/DED/DIS	0.00
SALES TAX	14.43
PLEASE PAY THIS AMOUNT	401.43

DESCRIPTION

TOTALS

INVOICE

Invoice #: 56026

Tag #: T482

PORSCHE MONTEREY #184

1781 DEL MONTE BLVD.

SEASIDE, CA 93955

PHONE: (831) 899-8888

FAX: (831) 583-6262

EPA # CAL000314156 BAR # ARD00247143

REMIT PAYMENT TO: LITHIA MOTORS SUPPORT SERVICES

P.O. BOX 4186 PORTLAND, OR 97208-4186

Service Advisor: 210502 GARRETT CLAPPER

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE	MILEAGE IN	MILEAGE OUT
BLUE	11	PORSCHE 911			WPOCB2A95BS795568		6UVE729	1028	1029
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN11			WAIT 15JUN20		0.00	CASH	15JUN20	15JUN20	15JUN20

OPTIONS: ENG:3.8 Liter

porscheofmontereycares.com
[877] 896-9147

**Does your
Porsche need
a spa day?**



CALL TODAY
TO SET UP YOUR APPOINTMENT!

ALL PARTS ARE NEW UNLESS
OTHERWISE INDICATED.

If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request. If you choose to save replaced parts, please note that a core charge may apply.

☐ Some Parts Not Returnable

ARBITRATION AGREEMENT
Any dispute between customer and the dealership arising from or related to this vehicle or this transaction will be settled by mandatory and binding arbitration pursuant to the Federal Arbitration Act 9 U.S.C. § 1 et. seq. The arbitration shall be conducted by a single arbitrator. The arbitrator may grant whatever relief the parties may be entitled to at law or in equity.

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	PERFORM	COURTESY	VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRE TREAD DEPTH, AND SET TIRE PRESSURE TO SPEC'S (LF RF LR RR).				
	VI	DEFAULT					
		96465	CPR			0.00	0.00
PARTS:		0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A: 0.00
1028 Completed 10,000 mile / 1 year Service. For additional information please see attached inspection sheet. Performed visual inspection of the brakes 10 mm Front & 10 mm. Inspected tire tread depth 7/32 Front & 7/32 Rear. Topped off all fluids. Reset maintenance reminder light. (Recommend new tires due to age, over ten years)							

B	PERFORM	LUBE, OIL, AND FILTER SERVICE WITH COURTESY INSPECTION					
	LOF	DEFAULT					
		96465	CPR			202.34	202.34
	1	900-123-106-30	ALUM SEAL RING		1.58	1.58	1.58
	1	0PB-115-466	OIL FILTER INSERT		26.12	26.12	26.12
	1	9A7-115-499-00	SEALING RING		9.65	9.65	9.65
	9	0W40SYN	0W40SYN OIL		9.85	9.85	88.65
PARTS:		126.00	LABOR:	202.34	OTHER:	0.00	TOTAL LINE B: 328.34
1028 Completed 10,000 mile / 1 year Service. For additional information please see attached inspection sheet. Performed visual inspection of the brakes 10 mm Front & 10 mm. Inspected tire tread depth 7/32 Front & 7/32 Rear. Topped off all fluids. Reset maintenance reminder light. (Recommend new tires due to age, over ten years)							

EST: 340.00

15JUN20 09:08 SA: 210502

9254577676

<input type="checkbox"/> Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi <input type="checkbox"/> Customer declined tire pressure check/inflation service. Initials _____				
Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:
\$	\$			<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)
Revised Estimate	\$			<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)

DATE

CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

***HAZARDOUS WASTE DISPOSAL COSTS:** We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal law.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	WASTE DISPOSAL COSTS*	TOTAL CHARGES	LESS INS/DED/DIS	SALES TAX	PLEASE PAY THIS AMOUNT



PORSCHE

The Porsche Multi-Point Inspection Report

The Porsche Multi-Point Inspection Report is a series of thorough vehicle "health checks" performed by factory-trained Porsche technicians. It is designed to keep your Porsche operating in top condition and to minimize your chances of being inconvenienced on the road. If additional service is recommended on any listed item, your Porsche Service Advisor will be happy to speak with you about your options.

Customer

RO/Tag

Mileage

Year/Model

VIN

Engine Size

Date

Checked and Okay at this Time

May Require Future Attention

Requires Immediate Attention

Check Fluid Levels and Fill

OK FILL

OK FILL

- | | |
|------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> <input type="checkbox"/> Engine Oil | <input checked="" type="checkbox"/> <input type="checkbox"/> Brake Reservoir |
| <input checked="" type="checkbox"/> <input type="checkbox"/> Windshield Washer | <input checked="" type="checkbox"/> <input type="checkbox"/> Headlamp Washer |
| <input checked="" type="checkbox"/> <input type="checkbox"/> Power Steering | <input type="checkbox"/> <input type="checkbox"/> Coolant Recovery Reservoir |
| <input type="checkbox"/> <input type="checkbox"/> Transmission (if equipped w/ dipstick) | |

Check Following Systems / Components

- | | |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Visually inspect headlamp alignment |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Windshield washer spray, wiper operation and wiper blades |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Windshield cracks and/or chips |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Heating, ventilation and air conditioning check |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Engine air cleaner filter |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Oil and/or fluid leaks |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Constant velocity (CV) drive axle boots (if equipped) |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Exhaust system (leaks, damage, loose parts) |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Steering and steering linkages |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Shocks/struts, air suspension and other suspension components for leaks and/or damage |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Brake system (including lines, hoses and parking brake) |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Engine cooling system, hoses and clamps |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Radiator, heater and air conditioning hoses for leaks / damage |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Accessory drive belt(s) |
| <input checked="" type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Clutch operation (if equipped) |
| <input type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> State inspection due (if applicable) |
| <input type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Your last completed maintenance |
| <input type="checkbox"/> <input type="checkbox"/> | <input type="checkbox"/> Your next factory scheduled maintenance is due at |

Comments:

This Courtesy Inspection Completed By Your Porsche Service Team

Service Advisor:

Technician:

Customer Signature:

PNA 000 012 Ed. 05/08

2011 911

3.8

1028

BS 795568

Engine Size

6/15/20

Check Battery Condition

☒ Good
Comments:

☐ Recharge


☐ Bad

Check Brakes

Measure Front / Rear Brake Linings

RF ☒ ☐ ☐

RR ☒ ☐ ☐



LF ☒ ☐ ☐

LR ☒ ☐ ☐

Over 5mm or 7/32"

3 to 5mm or 4/32" to 7/32"

Less than 3mm or 4/32"

Brake Measurements Not Taken This Service Visit

Comments:

The tires are over 10 years old

Check Tires

TREAD DEPTH

LF

- ☒ 7/32" or Greater
- ☐ 4/32" to 6/32"
- ☐ 3/32" or Less

- ☒ 7/32" or Greater
- ☐ 4/32" to 6/32"
- ☐ 3/32" or Less

LR

RF

- ☒ 7/32" or Greater
- ☐ 4/32" to 6/32"
- ☐ 3/32" or Less

- ☒ 7/32" or Greater
- ☐ 4/32" to 6/32"
- ☐ 3/32" or Less

RR



- ☒ ☐ ☐ LF
- ☒ ☐ ☐ LR

Wear Pattern / Damage

Tire Wear Indicators

- ☒ ☐ ☐ RF
- ☒ ☐ ☐ RR

☐ Alignment Check Recommended

☐ Wheel Balance Recommended

Comments:

Age due to year

Tire Pressure Set to

Factory Recommendations

PSI

25

Front

39

Rear

For Your Next Battery Call: 1-800-AAA-HELP

To Join AAA Call: 1-800-JOIN-AAA

This Invoice Must Be Retained for Limited Warranty
There is no charge for storage, shop supplies,
or hazardous/other waste removal.

541711

Professionally Installed by:

CARMEL BUNE



Date: 11/10/2022	Call Number: 36448	Service Technician: M. ARZU
Bill To		AAA Member Discount (\$25 off of the retail price)
Me		
Me		Estimate/Diagnostic Fee:
Phone #:		\$ /or hourly at \$ /per hour
Year: 2011	Make: PORSCHE	Model: SPEEDSTER
License Plate:	Odometer: 1130	Method Payment
Description of Repairs (Estimate/Invoice): REPLACE BATTERY		<input type="checkbox"/> Cash <input type="checkbox"/> Check <input checked="" type="checkbox"/> Credit Card

QUANTITY	PART NUMBER	DESCRIPTION OF LABOR AND PARTS - All parts are new unless otherwise stated	PARTS	LABOR
1	94BC	Battery Price with Exclusive Member Discount (Minimum of \$25)	\$	
		Standard Installation		\$ 0
		Battery and Charging System Analysis		\$ 0
		Battery Core Charge		\$
		Labor Intensive Install (If Applicable)	\$	\$
		Parts and Accessories	\$	\$
		Solve #7129106	\$	\$

Yes <input type="checkbox"/> No <input type="checkbox"/> Battery Management System Reset Done \$	California AB-2153 (Lead Acid Battery Recycling Act) mandates a \$1.00 fee for each new or remanufactured battery sold in the State of California.
Yes <input type="checkbox"/> No <input type="checkbox"/> Battery Management System Reset Needs to be Performed*	\$1.00
*Failure to promptly reset your vehicle's Battery Management System may cause damage to your vehicle's electrical system and will void the battery warranty	
Member/Customer Signature x	

Limited Warranty for Non-Commercial Passenger Vehicles - For limited warranty details see reverse side.	Subtotal Labor	\$
Limited Warranty Replacement	Subtotal Parts	\$174.09
Original Purchase Date Original Invoice #	Sales Tax	\$16.18
36 Month Free Replacement + 36 Month Discount Period = 72 Month Total Limited Warranty	Total	\$193.17

PRO RATA WARRANTY ADJUSTMENT 36 Month Free Replacement + 36 Month Prorated Replacement Cost = 72 Month Total Limited Warranty Free Replacement Warranty Remaining + 36 Months Prorated *No member discount applied For commercial vehicle limited warranty coverage, see reverse side. If a core is not returned, a non-recycling fee will be charged. If a vehicle is fitted with two "like" batteries used for starting power, not just for auxiliary, both have to be replaced for best results. When a warranty event occurs and one battery has failed, both are to be replaced and credit will be issued for both.	Original Test Results FAILED TEST 36448 Prior Acid Damage <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No KAM Unit Used <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW AND SIGN: I UNDERSTAND, THAT UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE, IF MY FINAL BILL WILL EXCEED \$100. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL. <input type="checkbox"/> I REQUEST A WRITTEN ESTIMATE <input checked="" type="checkbox"/> I DO NOT REQUEST A WRITTEN ESTIMATE <input type="checkbox"/> I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED \$	<input checked="" type="checkbox"/> I understand and acknowledge that my battery may not require immediate replacement; however I am authorizing replacement of my battery at this time. Comments Customer Signature X B.S.
SIGNED X 11/10/2022 B.S.	
DATE 11/10/2022	

BURTON AUTOMOTIVE LLC.

1640 DEL MONTE BLVD.

SEASIDE CA 93955

(831) 394-6044



burtonauto@yahoo.com

SERVICE ORDER

192336

1 Dec 2020

ARD 285343

CAL000421120

We are open Monday thru Friday 8:am to 5pm

Thank you for suporting small business

ORIGINAL DATE : TUESDAY, 1 DECEMBER 2020

COMPANY 17494

CUSTOMER

ADDRESS

TELEPHONE(S)

KEY #

WRITER
MARK

DUE BY
1 Dec 20 13:02

ENGINE NUMBER

YEAR 2011

MAKE PORSCHE

MODEL 911

LICENSE # 6UVE729

V.I.N. WP0CB2A95BS795568

UNIT ?

MILES IN AND OUT 1,080 / 0

TYPE LABOR PERFORMED

QTY TECH. SALE EACH SUBTOTAL

L CALIFORNIA OFFICIAL SMOG TEST 1996 - 2020 (RENEWAL)

TIM \$ 46.75

PASS

Attention:

California law requires auto repair facilities to check tire pressure if a work order is written on any vehicle!

Note: There will be a \$10.00 fee to perform this service. If you opt not to have this done to your vehicle, your signature is required for our protection of penalties from the State of California.

Note: If vehicle has exhaust leak before catalyst and causes a sample dilution customer is to pay 50% of aborted/attempted smog test.

X

TYPE SUBLET SOLD

QTY TECH. SALE EACH SUBTOTAL

S SMOG CERTIFICATE

1.00 \$ 8.25 \$ 8.25

ORIGINAL ESTIMATE \$ 55.00

X:

RECOMMENDATIONS

I hereby authorize the above name to operate and store the above vehicle for the purpose of testing, inspection, repair and delivery, at my own risk. I understand that the above named is not responsible for loss or damage equipment or articles left on or in vehicles in case of fire, theft, or any cause beyond their control. I understand that if I wish to retain worn and damaged parts that request will be made at the time of authorization or repairs. I understand that two (2) days after notice of completion of services rendered, that a storage charge of not more than \$25.00 per day, will be charged unless otherwise agreed to in writing. BY LAW YOU MAY CHOOSE ANOTHER LICENSED FACILITY TO PERFORM ANY NEEDED REPAIRS OR ADJUSTMENTS, WICH THE SMOG TEST INDICATES ARE NECESSARY.

Signature: _____ Date: _____

DEPOSIT

SUBTOTAL - LABOR \$ 46.75

SUBTOTAL TIRES

SUBTOTAL - MISCELLANEOUS \$ 8.25

TOTAL SALES \$ 55.00

TOTAL COLLECTED \$ 0.00

AMOUNT DUE \$ 55.00

PAYMENT :

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 12/01/2020 @ 1:12 PM

Model Year: 2011	Vehicle Make: • PORSCHE	Vehicle Model: 911 CARRERA S
VIN (scanned from vehicle):	WP0CB2A95BS795568	
VIN (manually entered or from DMV document):	WP0CB2A95BS795568	
License Plate: 6UVE729	License State: CA	Fuel Type: Gasoline
Certification Type: California	Odometer: 1080	

Overall Test Result

PASS

Congratulations! Your vehicle passed the Smog Check inspection, which helps California reach its daily goal of removing smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection: PASS Functional Inspection: PASS

Smog Check Certificate Number: RS933327C

DMV ID Number: 6967S151R908

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

Visual Inspection Result Information

<u>Result</u>	<u>Inspection Category</u>	<u>Result</u>	<u>Inspection Category</u>
NOTAPPLICABLE	Air Injection System	PASS	Catalyst
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crankcase Emission Controls
NOTAPPLICABLE	Exhaust Gas Recirculation (EGR)	PASS	Fuel Evaporative System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
NOTAPPLICABLE	Turbocharger/Supercharger	PASS	Vacuum Lines to Sensors/Switches

Emission Control Systems Functional Check Results

<u>Result</u>		<u>Result</u>	
PASS	Liquid Fuel Leak Check	PASS	OBDII
PASS	Smoke Check		

Smog Check Inspection Station Information

Station ID: RC285343
BURTON AUTOMOTIVE, LLC
1640 DEL MONTE BLVD
SEASIDE, CA 93955
(831) 394-6044

Inspector Name/ID: HAGBERG, TIMOTHY/EO033154
Software Version/OIS ID: 20.3.1150.0/CV015160

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

12/1/20
Date

[Signature]
Inspector's Signature

**J & D AUTO REPAIR**

1675 CONTRA COSTA
SAND CITY, CA 93955
(831) 899-1111

Our Business hours are 8am to 5pm M-F. We accept VISA/MC

Monday - Friday 8am to 5pm

Page: 1

janndaauto1675@gmail.com

Fax: 831 899-9793

Invoice: 86175

Date: 8 DEC 2022

License: ARD096990

EPA CAL 91220535

Home #:
Work #:
Cell #:
Email:
Sales: JOSE

Ext.

Year: 2011
Make: PORSCHE
Model: 911 / CARRERA GTS
License: 6UVE729
Vin: WP0CB2A95BS795568
Unit:
Meter Hrs: 0.00
Open Date: 8 DEC 2022

Miles/Km: 1,193.0
Eng. Type: H6 / DOHC
Eng. No.: 3.8L
Prod.:
Color/Doors: Doors= 2 d
Remarks/PO:
Customer #: 9894
Completed: 8 DEC 2022 13:39

Description of Labor / Service Provided:

STAR SMOG INSPECTION
CERT# TA572704C
TIRE PRESSURE: FRONT-37, REAR-44

Tech: Total
Invoice: 86175
JAMS 3 DEC 2022 13:00
License: ARD096990
EPA CAL 91220535

SHALLY
Original Estimate: \$ 69.25 :
Revision #1 .00
8 DEC 2022 13:40 Increase 0.00
BRIAN SHALLY () - SPOKE TO

I acknowledge notice and oral approval of an increase in the original estimated price
Revision #2 .00 Increase 0.00
Revision #3 .00 Increase 0.00

PAID DEC 08 PAID

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIALS. YOU AND YOUR EMPLOYEE MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION, OR DELIVERY AT MY RISK. AN EXPRESS MECHANICS LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT, DYNAMOMETER TESTING OR ANY OTHER CAUSE BEYOND YOUR CONTROL. IN THE EVENT LEGAL ACTION IS NECESSARY TO ENFORCE THIS CONTRACT I UNDERSTAND THAT I AM SOLEY RESPONSIBLE FOR ALL COSTS INCLUDING ATTORNEY FEES AND COURT COSTS. I HAVE READ AND UNDERSTAND THE ABOVE AND ACKNOWLEDGE RECEIPT OF AN ESTIMATE. SMOG CHECK CUSTOMERS: BY LAW YOU MAY CHOOSE ANOTHER SMOG CHECK STATION TO PERFORM REPAIRS, INSTALLATIONS, ADJUSTMENTS, OR SUBSEQUENT TESTS.

CASH _____ CHARGE _____ CHECK _____

Payment 1: 0.00
Payment 3: 0.00

Account #9894
Payment 2: 0.00
Payment 4: 0.00

Key # SMG
0.00
0.00

Labor: \$ 61.00
Parts: \$ 0.00
Environmental: \$ 0.00
Smog Certificate: \$ 8.25
Subtotal Charges: \$ 8.25
Service Charge: \$ 0.00
Sublet: \$ 0.00
Subtotal: \$ 69.25
Sales Tax: \$ 0.00
Labor: \$ 61.00
Total Sale: \$ 69.25
Total Paid: \$ 0.00
Total Due: \$ 69.25

Thank You From: J & D AUTO REPAIR

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 12/08/2022 @ 1:37 PM

Model Year:	2011	Vehicle Make:	PORSCHE	Vehicle Model:	911 CARRERA S
VIN (scanned from vehicle):		WP0CB2A95BS795568			
VIN (manually entered or from DMV document):		WP0CB2A95BS795568			
License Plate:	6UVE729	License State:	CA	Fuel Type:	Gasoline
Certification Type:	California	Odometer:	1193		

Overall Test Result

PASS

Congratulations! Your vehicle passed the Smog Check inspection, which helps California reach its daily goal of removing smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection: PASS Functional Inspection: PASS

Smog Check Certificate Number: TA572704C

DMV ID Number: 6757A358T038

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

Visual Inspection Result Information

Result	Inspection Category	Result	Inspection Category
NOT APPLICABLE	Air Injection System	PASS	Catalyst
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crankcase Emission Controls
NOT APPLICABLE	Exhaust Gas Recirculation (EGR)	PASS	Fuel Evaporative System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
NOT APPLICABLE	Turbocharger/Supercharger	PASS	Vacuum Lines to Sensors/Switches

Emission Control Systems Functional Check Results

Result		Result	
PASS	Liquid Fuel Leak Check	PASS	OBDII
PASS	Smoke Check		

Smog Check Inspection Station Information

Station ID:	RC096990	Inspector Name/ID:	FRANCO, JAMES/EO635013
J & D AUTO REPAIR		Software Version/OIS ID:	22.3.1649.0/CV007353
1675 CONTRA COSTA			
SAND CITY, CA 93955			
(831) 899-1111			

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

12-8-22

Date

Inspector's Signature

INVOICE

Invoice #: 67846

Tag #: T983

PORSCHE MONTEREY #184

1781 DEL MONTE BLVD.
SEASIDE, CA 93955
PHONE: (831) 899-8888
FAX: (831) 583-6262



EPA # CAL000314156 BAR # ARD00247143

REMIT PAYMENT TO: LITHIA MOTORS SUPPORT SERVICES
PO BOX 679811 DALLAS, TEXAS 75267-9811

Service Advisor: 280261 Christopher Car

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE	MILEAGE IN	MILEAGE OUT
BLUE	11	PORSCHE 911			WP0CB2A95BS795568		6UVE729	1270	1270
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN11			17:30 22MAY24		0.00	CASH	22MAY24	22MAY24	22MAY24

OPTIONS: ENG:3.8_Liter

porscheofmontereycares.com
[877] 896-9147

**Does your
Porsche need
a spa day?**



CALL TODAY
TO SET UP YOUR APPOINTMENT!

ALL PARTS ARE NEW UNLESS
OTHERWISE INDICATED.

If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request. If you choose to save replaced parts, please note that a core charge may apply.

☐ Some Parts Not Returnable

ARBITRATION AGREEMENT
Any dispute between customer and the dealership arising from or related to this vehicle or this transaction will be settled by mandatory and binding arbitration pursuant to the Federal Arbitration Act 9 U.S.C. § 1 et. seq. The arbitration shall be conducted by a single arbitrator. The arbitrator may grant whatever relief the parties may be entitled to at law or in equity.

LINE OPCODE TECH TYPE HOURS

A PERFORM LUBE, OIL, AND FILTER SERVICE WITH COURTESY INSPECTION
LOF PERFORM LUBE, OIL, AND FILTER SERVICE WITH
COURTESY INSPECTION

	LIST	NET	TOTAL
96465 CPX		299.32	299.32
1 900-123-106-30 SEALING RING	3.12	3.12	3.12
1 0PB-115-466 OIL FILTER INSERT	34.29	34.29	34.29
1 9A7-115-499-00 SEALING RING	11.97	11.97	11.97
9 0W40SYN 0W40SYN OIL	11.25	11.25	101.25
PARTS: 150.63 LABOR: 299.32 OTHER: 0.00 TOTAL LINE A:			449.95

1270 Completed 10,000 mile / 1 year Service. Performed oil service. For additional information please see attached inspection sheet. Performed visual inspection of the brakes 10 mm Front & Rear 10 mm. Inspected tire tread depth 7/32 Front & 7/32 Rear. Topped off all fluids. Reset maintenance reminder light.

B C/S: BATTERY HEALTH MAY NEED TO BE CHECKED. VEHICLE NEEDED TO BE JUMP STARTED. INSPECT AND ADVISE.

00 DEFAULT			
96465 CPR		87.78	87.78
PARTS: 0.00 LABOR: 87.78 OTHER: 0.00 TOTAL LINE B:			87.78

1270 Tested the battery and the test shows good but recharge. This is a sign that the battery has aged. Recommend starting the vehicle every other day to maintain the state of charge.

C C/S: BATTERY IN KEY FOB IS DEAD. PLEASE REAPLACE.

00 MAINTENANCE			
96465 CPR		0.00	0.00
1 999-611-108-00 BATTERY	14.81	14.81	14.81
PARTS: 14.81 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C:			14.81

1270 Installed new key battery. The key Fob still is inop. Recommend replacement key fob.

D PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRE TREAD DEPTH, AND SET TIRE PRESSURE TO

☐ Tire pressure check/inflation service was performed.
RF _____ psi LF _____ psi RR _____ psi LR _____ psi
☐ Customer declined tire pressure check/inflation service. Initials _____

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:
\$	\$			
Revised Estimate	\$			
				<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)

* HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal law.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	WASTE DISPOSAL COSTS*	TOTAL CHARGES	LESS INS/DED/DIS	SALES TAX	PLEASE PAY THIS AMOUNT

INVOICE

Invoice #: 67846

Tag #: T983

PORSCHE MONTEREY #184



PORSCHE

1781 DEL MONTE BLVD.
SEASIDE, CA 93955
PHONE: (831) 899-8888
FAX: (831) 583-6262

EPA # CAL000314156 BAR # ARD00247143

REMIT PAYMENT TO: LITHIA MOTORS SUPPORT SERVICES
PO BOX 679811 DALLAS, TEXAS 75267-9811

Service Advisor: 280261 Christopher Car

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE	MILEAGE IN	MILEAGE OUT
BLUE	11	PORSCHE 911			WP0CB2A95BS795568		6UVE729	1270	1270
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
01JAN11			17:30 22MAY24		0.00	CASH	22MAY24	22MAY24	22MAY24

OPTIONS: ENG:3.8_Liter

porscheofmontereycares.com
[877] 896-9147

**Does your
Porsche need
a spa day?**



CALL TODAY
TO SET UP YOUR APPOINTMENT!

ALL PARTS ARE NEW UNLESS
OTHERWISE INDICATED.

If our Dealership does not have to return the parts to the manufacturer or distributor under a warranty arrangement and they are not exempt due to their size, weight or other factors, they will be returned to you upon request. If you choose to save replaced parts, please note that a core charge may apply.

☐ Some Parts Not Returnable

ARBITRATION AGREEMENT
Any dispute between customer and the dealership arising from or related to this vehicle or this transaction will be settled by mandatory and binding arbitration pursuant to the Federal Arbitration Act 9 U.S.C. § 1 et. seq. The arbitration shall be conducted by a single arbitrator. The arbitrator may grant whatever relief the parties may be entitled to at law or in equity.

LINE OPCODE TECH TYPE HOURS

SPEC'S (LF RF LR RR)
VI PERFORM COURTESY VEHICLE INSPECTION. INCLUDES:
VISUAL INSPECTION OF VEHICLE, TIRE TREAD
DEPTH, AND SET TIRE PRESSURE TO
SPEC'S (LF RF LR RR)

PARTS: 96465 CPR 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00
1270 TIRE PRESSURES SET TO 33 PSI FRONT AND 34 PSI REAR

ESTIMATE: 614.45 22MAY24 08:47 SA: 280261
CONTACT:

CREATED 2024-05-14 10:05:00AM
TAKEN BY NICHOLAS NEWTON

YOUR SATISFACTION IS OUR #1 GOAL! PLEASE
CONTACT OUR SERVICE MANAGER WITH ANY CONCERNS
YOU ENCOUNTER. YOU MAY RECEIVE A SURVEY BY
PHONE OR MAIL. THANK YOU VERY MUCH FOR YOUR
BUSINESS AND COMING TO PORSCHE OF MONTEREY!
BAR-AC247143 EPA# CAL00314156

<input type="checkbox"/> Tire pressure check/inflation service was performed. RF psi LF psi RR psi LR psi <input type="checkbox"/> Customer declined tire pressure check/inflation service. Initials _____			
Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time
\$	\$		
Revised Estimate			
\$			

***HAZARDOUS WASTE DISPOSAL COSTS:** We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal law.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

DESCRIPTION	LABOR AMOUNT	TOTALS
PARTS AMOUNT	387.10	165.44
GAS, OIL, LUBE	0.00	0.00
SUBLET AMOUNT	0.00	0.00
WASTE DISPOSAL COSTS*	0.00	0.00
TOTAL CHARGES	552.54	552.54
LESS INS/DED/DIS	0.00	0.00
SALES TAX	15.30	15.30
PLEASE PAY THIS AMOUNT	567.84	567.84